

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Explanation of error code structure and FU (function unit) abbreviations

error:

all = **4-digit** error numbers in the 1st line are the general errors appearing (and logged in the generator memory) at all generators Optimus RAD-R/F-C and Velara even if the reason for the error might not be related to the function unit sending the event

VTB = **4-digit** error numbers in the 2nd line are errors displayed at user interfaces with Velara (VTB) generators in C/V Allura environment (TheBox interface), but only if read via the ACCO interface (system controller), explanations identical to the 4/5-digit VTC errors

VTC = **4-digit** or **5-digit** error numbers in the 3rd line are errors displayed at user interfaces with Velara (VTC) generators in a CFD, Ibis, URF, Eleva environment

C = **7-digit** error numbers 61xxxx in the 4th line are the reference error numbers displayed at the Cockpit desk of Duo Diagnost systems if Optimus C is at release 1.2 and Duo system firmware at release 3.x .

error code structure **xxYY**:

xx = function unit involved or sending the event (non-existing function units appearing at some screens Optimus and Velara are not listed), **YY** = error symptom

Some units are indicated in error detail screens with their **HEX** address, these are listed in **bold xxH** characters. Function units 00.. - 09.. numbers are HEX and decimal.

At generators Optimus RAD release 2 generators error messages might appear with the HEX address instead of the decimal address.

class:

E = Error (displayed at the control desk or user interface and logged) or **W** = Warning (logged only); **E/W** case dependent,

IR = invalid request; **F** = fatal error (LED of function unit steadily on)

explanation, test procedures, fixing suggestions:

if written only in normal characters valid for all generator types whilst *italic comments especially or exclusively for Velara, indicated with V:*

special comment prefixes:

2R: Optimus RAD release 2 only (previous releases not supported)

3RF: Optimus RAD + R/F release 3.x

C: Optimus C in a Duo Diagnost system

V: *Velara TC and TheBox*

00..	CU	central unit EZ139; <i>EZ = central unit CuBe (central unit + base extension)</i>
01..	FU_DRC	dose rate control, physically located on CU EZ139, parts of basic interface EZ150 also involved (Amplimat), FU_DRC also handles fluoroscopy; <i>part of EZ = central unit CUBE (Central Unit + Base Extension), FU_DRC also handles fluoroscopy</i>
02..	FU_kV	kV control EZ130; <i>part of EH = FU kV-mA</i>
03..	FU_mA	mA control EZ119, handles 2 filaments for up to 3 tubes; <i>part of EH = FU kV-mA, handles 2 filaments for max to 2 tubes</i>
07..	FU_CIE	central interface extension EZ150, basic interface, drives low speed rotor control
08..	FU_HI	human interface C300, control desk
10..	0AH FU_RC	rotor control (high speed / dual speed) EY100,
13..	0DH FU_ADAP_a	adapter decade cables for 4 aux. units RAD = WA102 or 1WA102
14..	0EH FU_ADAP_b	adapter decade cables for 4 aux. units RAD = 2WA102
15..	0FH FU_ADAP_c	adapter decade cables for 4 aux. units R/F = WB102

Some error explanations can have the information ... #1#2H or #1H, #2H, #3H, #4H, #5H, #6H. It just says that up to 2 or 6 function units might be listed in this chain with their HEX address, empty fields indicate 00H.

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	0099 1673 05757	W	<i>can only occur with special software versions where the trial period has elapsed</i>		<i>update CU firmware</i>
all VTB VTC C	00A0 0000 06548	IR	<i>received a simulation mode request from the system controller during adaptation</i>		<i>request simulation mode (without X-ray) in standby</i>
all VTB VTC C	00A1 0001 06549	IR	<i>received a simulation mode ON request from the system controller whilst the generator tried to turn it ON anyway</i>		<i>request simulation mode (without X-ray) in standby</i>
all VTB VTC C	00A2 0002 06550	IR	<i>received a simulation mode OFF request from the system controller whilst the generator tried to turn it OFF anyway</i>		<i>contact Helpdesk Hamburg, send error log and detailed error information</i>
all VTB VTC C	00A3 0003 06551	F	<i>FU-mA cannot turn ON simulation mode without X-ray</i>		<i>1. Check and/or change values sent by system controller for the control method, select another EPX 2. Change PC-104 3. Change CUBE 4. Contact Helpdesk Hamburg</i>
all VTB VTC C	00A4 0004 06552	F	<i>FU-mA cannot turn OFF simulation mode without X-ray</i>		
all VTB VTC C	00B0 0064 06648 6106648	E/W	<i>error in application data service interface</i>		<i>contact Helpdesk Hamburg, send error log and detailed error information</i>
all VTB VTC C	00B1	E/W	<i>internal interrupt message was not expected by generator order list</i>		
all VTB VTC C	00B2	E/W	<i>human interface order is not expected - NO member in display table</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00B3	E/W	data language selector is invalid, = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00B4	E/W	message invalid in Adopmes		
all VTB VTC C	00B5	E/W	input parameter out of range in syntax = leads to a hang-up in combination with CU release 3.x if FU_HI firmware < 4512 113 20524 = causes a warning entry with CU release 2, does not disturb application		fixed with FU_HI firmware 4512 113 20524 for release 2 + 3 generators = if CU release still at 3.2 and FU_HI firmware still 20523 a PREP wakes up the generator check if FCO 00 135 006 has been carried out solved with desk firmware version 4512 113 20525
all VTB VTC C	00B6	E/W	FU adap WA/WB data for DI are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00B7	E/W	message can not be send		
all VTB VTC C	00B8	E/W	tomo mode switch can not be enabled		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00B9 0073 06657 6106657	E	AD: message from unknown function unit		<i>contact Helpdesk Hamburg, send error log and detailed error information</i>
all VTB VTC C	00BA	E/W	data of RGDV are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00BB	E/W	base data of RGDV are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00BC	E/W	state data of RGDV are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00BD	E/W	data of APR are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00BE	E/W	data of active RGDV are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00BF	E/W	data of RGKeys are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00BG	E/W	no more lowest level menus available		
all VTB VTC C	00BH	E/W	display position collision		
all VTB VTC C	00BI	E/W	menu/APR mismatch in same level		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00BJ	E/W	menu name not found		
all VTB VTC C	00BK	E/W	APR is assigned to a different RGDV		
all VTB VTC C	00BL	E/W	menu name already exists		
all VTB VTC C	00BM	E/W	max display position reached		
all VTB VTC C	00BN	E/W	APR not found in this menu		
all VTB VTC C	00BO	E/W	data of menu tree are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf and start programming from scratch dump CU Complete file which won't work, download CU Complete again using Agent 3.1.2, get it from the Intranet ..\..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00BP 0096 06680 6106680	E	AD: unknown message from system controller		<i>contact Helpdesk Hamburg, send error log and detailed error information</i>
all VTB VTC C	00BQ 0097 06681	E/W W	APR can not be modified, <i>calculation of startup x-ray data set failed</i>		<i>load a new startup EPX from the system controller</i>
all VTB VTC C	00BR 0098 06682	E/W W	APR is not assigned to an RGDV <i>a startup x-ray dataset has been processed on startup and the dataset needed to be limited</i>		<i>load a new startup EPX from the system controller</i>

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00BS 0099 06683	E/W IR	the RGDV of the APR is not ready for operation, <i>an adaptation request has been received whilst the CU was performing adaptation anyhow</i>		<i>contact Helpdesk Hamburg, send error log and detailed error information</i>
all VTB VTC C	00BT 0100 06684 6106684	E/W W	data of APR characteristics are invalid = appears with a non-programmed CU after the very first turn-on, = when appearing after CU Complete restore the data file might be defective, <i>an adaptation dataset calculation could not be successfully performed, due to incorrect parameters or generator state</i>		if permanent erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase Optimus_RAD_RF_C.pdf and start programming from scratch dump CU Complete file which won't work, download CU Complete again using Agent 3.1.2, get it from the Intranet ..\data_collection\AGenT\AGenT-download- pages-and-PC-settings.pdf <i>1. change PC-104 2. change CUBE 3. contact Helpdesk Hamburg, send error log and detailed error information</i>
all VTB VTC C	00BU	E/W	adaptation paused due to missing load		if the tube temperature supervision sees any of the temperatures beyond a limit to allow 100% load adaptation waits until a 100% load is possible and keeps on automatically 00BU will not be displayed at the control desk or on the service PC, the only indication is the red traffic light at the control desk and a flickering "Waiting" window on the PC screen
all VTB VTC C	00BV	E/W	tube temperature supervision status message during adaptation		
all VTB VTC C	00BW	E/W	APR not accepted by general calculation		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00BX	E/W	Variofocus allowed invalid = appears with a non-programmed CU after the very first turn-on = when appearing after CU Complete restore the data file might be defective		if permanent erase NV-RAM (see ..\..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00BY	E/W	RGDV order without active RGDV		
all VTB VTC C	00BZ 0106 06690	IR	<i>system controller sent select mode for an unused buffer</i>		<i>contact Helpdesk Hamburg, send error log and detailed error information</i>
all VTB VTC C	00CB 0146 06766	W	received internal interface message #1#2H unknown <i>FU #1 sent IIM which CU didn't know, possibly inconsistency between FU resp. CU version (release/level), FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo</i>	<i>did you install a wrong version?</i>	1. change function unit 2. change PC-104 3. change CUBE 4. contact Helpdesk Hamburg, send error log and detailed error information
all VTB VTC C	00CC 0147 06767	W	frame repeat counter overflow (internal interface message #1#2H) <i>communication with FU #1 disturbed, possibly the FU is overloaded or stopped FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo</i>		
all VTB VTC C	00CD 0148 06768	W	function unit #1H not addressable <i>transmit to FU #1 can't be started FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo</i>	RGDV switch-over times very long	might be caused by a defective WA unit
all VTB VTC C	00CE 0149 06769	W	rx signal conflict function unit #1H <i>reception from FU #1 disturbed FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00CF 0150 06770	W	no retry from function unit #1H <i>while sending to FU #1 it is not communicating anymore (i.e. the expected Remote Transmit Request is missed), possibly because of overload or stop,</i> FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo		
all VTB VTC C	00CG 0151 06771	W	domain tx response, mailbox type wrong <i>error messages CD, CF or CL not reported because wrong error mailbox token</i>		
all VTB VTC C	00CH 0152 06772	W	invalid tbdor parameter function unit type <i>invalid parameter of CA_PUT_CU_IIM_TOKEN</i>		
all VTB VTC C	00CJ 0154 06774	W	CAN auto configuration successful function unit #1H = will always be logged if command "CAN Auto Configuration" has been carried out = appears with a non-programmed CU after the very first turn-on <i>info that CAN auto configuration has updated the CAN NV table,</i> <i>if #1=53H all is ok because CAN auto config. initiated by service command</i> <i>if #1=45H CAN auto config. started because NV-data corrupted</i>	= when appearing after CU Complete restore the data file might be defective <i>CAN auto configuration can be used to initiate a soft reboot</i>	if permanent erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using AgentT 3.1.2, get it from the Intranet ..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf <i>if there are more NV-problems exchange CUBE</i>
all VTB VTC C	00CK 0155 06775	W	CAN auto configuration without success function unit #1H <i>CAN auto configuration ran without updating the CAN NV table,</i> <i>if #1=53H CAN auto config. by service command</i> <i>if #1=45H CAN auto config. started because NV-data corrupted</i>	<i>CAN auto configuration can be used to initiate a soft reboot</i>	
all VTB VTC C	00CL 0156 06776	W	function unit #1H not addressable <i>transmit to FU #1 can't be started</i> FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00CM 0157 06777	W	function unit #1H sent event and did not answer RTR <i>reception from FU #1 disturbed (i.g. no answer to remote transmit request; possible reasons CUBE overload; FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo</i>		
all VTB VTC C	00CP 0160 06780	W	max function unit count exceeded while auto configuration more FU's found than can be handled		
all VTB VTC C	00CQ 0161 06781	W	radiography system is not responding (CAN connected systems) only Optimus RAD/RF/C		
all VTB VTC C	00CR 0162 06782	W	guarded connection failed = if communication to SUN is off at Digital Diagnost or Thoravision systems only Optimus RAD/RF		
all VTB VTC C	00CX 0168 06788	W	last only repeat counter overflow internal interface message #1#2H <i>reception from FU #1 disturbed FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo</i>		
all VTB VTC C	00CY 0169 06789	W	abort of rx of internal interface message #1#2H, unexpected frame <i>reception from FU #1 disturbed FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo</i>	+15VDC missing at turn-on, typically in combination with 00-' (invalid code) + 00M0 and fatal error LED condition EZ119	try to find the reason for the missing +15VDC, remove PCBs and all external devices using +15V like e.g. measuring chambers, suppressor diode on backpanel EZ might be short
all VTB VTC C	00CZ 0170 06790	W	unexpected frame received after internal interface message #1#2H <i>reception from FU #1 disturbed; message is delivered nevertheless, FU parameter #1: 02=kV-(mA-)control; 03=(kV-)mA-control; 0A=RoCo</i>		
all VTB VTC C	00DA 0209 06865 6106865	E/W	no CPU access to CAN chip <i>problem with CAN chip on CUBE</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00DB 0210 06866	W	CAN chip reset not acknowledged <i>problem with CAN chip on CUBE</i>		
all VTB VTC C	00DC 0211 06867	W	CAN chip reset release not acknowledged <i>problem with CAN chip on CUBE</i>		
all VTB VTC C	00DD 0212 06868	W	CAN chip DPRAM check failed <i>problem with CAN chip on CUBE</i>		
all VTB VTC C	00DE 0213 06869 6106869	E/W	unexpected CAN chip interrupt pointer <i>problem with CAN chip on CUBE</i>		
all VTB VTC C	00DF 0214 06870	W	CAN chip state undefined <i>problem with CAN chip on CUBE</i>		
all VTB VTC C	00DG 0215 06871	W	CAN chip error active after passive #1H <i>00DH ended</i>		
all VTB VTC C	00DH 0216 06872	W	CAN chip state error passive #1H <i>CUBE-CAN-chip error because of detected transmission problem; it's just an info; the transmission is still working; possibly no running FU is connected to the CAN bus or EMC problems</i>		
all VTB VTC C	00DI 0217 06873 6106873	E	CAN chip state bus off #1H <i>CUBE-CAN-chip serious error because of detected transmission (probably EMC) problems; no transmission possible till next startup</i>		
all VTB VTC C	00DJ 0218 06874	W	CAN chip state DPRAM error <i>problem with CAN-chip on CUBE</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00DK 0219 06875	W	CAN chip state DPRAM error and passive <i>problem with CAN-chip on CUBE</i>		
all VTB VTC C	00DL 0220 06876 6106876	W	unexpected CAN chip interrupt <i>problem with CAN-chip on CUBE</i>		
all VTB VTC C	00DM 0221 06877	W	CAN frame error (code #1H) <i>problem with CAN-chip on CUBE</i>		
all VTB VTC C	00E0 0256 06948 6106948	E/W	iRMX exception #2#1H occurred, 2R+3RF: appears if a desk key has been pushed after erasing APR data without a reset afterwards, 3RF: might appear if data sets can not be downloaded due to unknown data mismatch <i>first two byte parameters taken as a 16 bit word give RMX exception code</i>		2R+3RF: if 00E0 appears during APR loading erase CU memory by setting the battery jumper to the off position for at least 5 minutes, put it back to ON, then start programming from scratch, better not use existing CU Complete download file, it might carry the problem C: load release 1.2 flash load program, >> load Agent 3.1.2, get it from the Intranet <a href="..\..\data_collection\AGenT\AGenT-download-
pages-and-PC-settings.pdf">..\..\data_collection\AGenT\AGenT-download- pages-and-PC-settings.pdf
all VTB VTC C	00FA 0337 07065	W	CPU: CAL(CS)-Error code: #2#1H <i>system CAN problem</i>		<i>it might be necessary to remove the PC cable connection (even if the Agent program is not active anymore) and to switch the system off and on again to inhibit the master state of the PC</i>
all VTB VTC C	00FB 0338 07066	W	CPU: CS: Fast Domain Error <i>communications failure on system CAN</i>		
all VTB VTC C	00G0 0384 07148	E/W	variable in case statement has undefined value <i>internal SW failure, invalid state transition action specified</i>		
all VTB VTC C	00G1 0385 07149 6107149	E/W	condition_code <> OK after CALL to send <i>this error is not used</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00G2 0386 07150	E/W	condition_code <> OK after CALL to init <i>CU could not initialize the internal CAN properly</i>		
all VTB VTC C	00G3 0387 07151	W	entering CU ONLY simulation mode <i>the CU just entered CU ONLY simulation mode and any FU's present will be ignored</i>		
all VTB VTC C	00G4 0388 07152	E	firmware update archive file corrupted <i>a firmware update was unsuccessful because the archive file used was corrupted</i>		
all VTB VTC C	00I1 0513 07349	E/W	CPU Index to I/O-table is wrong <i>not used in Optimus TC</i>		
all VTB VTC C	00I2 0514 07350	E/W	No interrupt reason on sig-bus <i>not used in Optimus TC</i>		
all VTB VTC C	00I3 0515 07351	E/W	No interrupt reason on XS-bus <i>not used in Optimus TC</i>		
all VTB VTC C	00I4 0516 07352 6107352	E/W	one FU has a watchdog-error, a message with an unexpected message number (IIM) has been received, the first parameter byte gives the IIM that was received. <i>not used in Optimus TC</i>		TV is not programmed correctly = check XRGSCOPE > Optimus > Program > Dose Rate Control > CONT > scantime_TV = 20ms
all VTB VTC C	00J1 0577 07449 6107449	E/W	DI: unknown IIM #1H <i>a message with an unexpected message number (IIM) has been received, the first parameter byte gives the IIM that was received</i>		
all VTB VTC C	00J2 0578 07450 6107450	E//R	DI: rx LWDR parameter out of range FS= #1H PID= #2H <i>DI: rx LWDR p. range FS=#1H PID=#2H SID=#3#4 false parameter received from system controller; error parameter bytes: 1=function selector FS, 2=parameter id (PID) of the faulty parameter in this message</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00J3 0579 07451 6107451	E/IR	DI: rx LWDR message corrupted FS= #1H PID=#2H DI: rx LWDR p. range FS=#1H PID=#2H SID=#3#4 st=#5H corrupted/invalid message received from system controller; error parameter bytes: 1=function selector FS, 2=parameter id (PID) of the faulty parameter in this message		
all VTB VTC C	00J4 0580 07452 6107452	E/W	DI: internal table lookup failed FS= #1H PID=#2H DI: table error FS=#1H PID=#2H SID=#3#4H TYP=#5H CU could not find parameter info in its internal table; error parameter bytes: 1=function selector FS of faulty message; 2=parameter id PID of the faulty parameter in this message		
all VTB VTC C	00J5 0581 07453	E/W	DI: tx LWDR parameter out of range DI: tx LWDR p. range FS=#1H PID=#2H SID=#2H4#4H val=#5H#6H CU is attempting to send false parameter to system controller; error parameter bytes: 1=function selector FS of faulty message; 2=parameter id PID of the faulty parameter of this message		C: Optimus C release 1.1 if mains resistance value > 300mohms programmed, load release 1.2 flash load program, >> load AgentT 3.1.2, get it from the Intranet ..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00J6 0582 07454 6107454	E	DI: tx LWDR parameter error FS= #1H PID=#2H ER= #3H DI: tx LWDR p. error FS=#1H PID=#2H SID#3#4H st=#5H CU is trying to send a corrupted/invalid message to system controller; error parameter bytes: 1=function selector FS of faulty message; 2=parameter id PID of the faulty parameter in this message; 3=internal error code		
all VTB VTC C	00J7 0583 07455 6107455	E W/IR	DI: LWDR message creation failed DI: LWDR message creation failed FS=#1H ERR=#2H the CU software failed to process a fixed parameter of an LWDR message; procedure ID can be used by XRG development team to determine the source of the problem; error class W = message from CU, IR = message from SC		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00J8 0584 07456	W	DI: unknown X-ray mode No. run data provided the CU is trying to send a run data message with an invalid X-Ray mode		
all VTB VTC C	00J9 0585 07457	W IR	DI: message from suspended device ignored message from SC whilst the generator is being controlled over the service interface		
all VTB VTC C	00JA 0593 07465	W IR	DI: no interface version received FS= #1H DI: no interface version received, message ignored; failure during initialization by the system controller		
all VTB VTC C	00JB 0594 07466 6107466	E IR	DI: unknown LWDR message received FS= #1H unknown LWDR message received from SC; possible compatibility problem SC-OptiTC; parameter 1= function selector FS		
all VTB VTC C	00JC 0595 07467 6107467	E W	DI: tx LWDR message size invalid FS= #1H internal SW error; possible compatibility problem SC-OptiTC; parameter 1= function selector FS		
all VTB VTC C	00JD 0596 07468	IR	DI: rx LWDR message invalid FS= #1H unknown/invalid/corrupted LWDR message received from SC; possibly compatibility problem SC-Opti TC; parameter 1 = function selector (FS)		
all VTB VTC C	00JE 0597 07469	IR	DI: can't translate FS=#1H PID=#2H SID=#3#4H val=#5#6H the CU has received an LWDR message with a parameter value that it cannot translate to its internal format; possibly compatibility problem SC-opti TC; function selector = param 1, parameter id = param 2, sub-param id = params 3+4, value = param 5+6		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00L1 0705 07649 6107649	E/W	GC: checksum error = appears with a non-programmed CU after the very first turn-on = when appearing after CU Complete restore the data file might be defective <i>reasons might be: checksum errors for selected table part; table first time calculated</i>		if permanent erase NV-RAM (see ..\..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using Agent 3.1.2, get it from the Intranet ..\..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00L2 0706 07650 6107650	E/W IR	tube calculation data might have changed during start-up or service work online with the PC parts of the tube data might be missing after tube data loading process to the generator <i>reasons might be: selected (programmable) table parts not existing or not accessible, selected table parts not valid, number of coordinates of selected table is zero</i>	a defective filament (data corruption) will be taken from the APR data at Duo Diagnost systems with Optimus C, the remaining filament is automatically set for all APR in ADAM, after tube load and adaptation the assignment filament<>APR is back to normal check whether the medium focus has been programmed in the default APR data set, it does not exist and MUST NOT be programmed	= CAN connected systems: EZX42+EZX43 must be removed during the loading process = Thoravision and Digital Diagnost: signal bus EZX23 must also be removed to avoid reset commands of the SUN, = signal bus EZX23 must be removed anyhow for adaptation = such measures are not required for Optimus C and non-system-CAN systems
all VTB VTC C	00L3 0707 07651 6107651	E/W W	GC: limit data error <i>reasons might be: (programmable) tables contain not enough coordinates for specified application, expected table values not found</i>		
all VTB VTC C	00L4 0708 07652 6107652	E/W IR	during service work online with the PC such error might come up after whatever XRGSCOPE screen has been sent with <F2> to the generator <i>reasons might be: the lower and upper limits of the limitation tables are inconsistent (example: L_min > L_max), combinations of application data produce inconsistent lower and upper limits (example: power factor = 0)</i>		check RGDV Data Set B "Tube power factor [%]": " = if [***] or [0] appears then set [100] instead, check all other Data Set B settings as they might have changed, too

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00L5 0709 07653 6107653	E/W IR	GC: calculation error <i>reasons might be: division by zero, input parameter not usable for calculation (example: pulse speed value = 0), input parameter specification not kept (example: decreasing U coordinate into curve), error in sequence of U coordinates of curve</i>		
all VTB VTC C	00L6 0710 07654 6107654	E/W IR	GC: function not implemented <i>reasons might be: selected nomogram is unavailable, selected Vario focus function or X-ray technique is not implemented</i>		
all VTB VTC C	00M0 0768 07748 6107748	E/W E	Unable to initialize FU(s) #1H, #2H, #3H, #4H, #5H, #6H the unit(s) will be indicated in the string at #1H, #2H ... , all other fields will indicate 00H	+15VDC missing at turn-on, typically in combination with 00CY + 00- (invalid code) and fatal error LED condition EZ119	try to find the reason for the missing -15VDC, remove PCBs and all external devices using -15V like e.g. measuring chambers, suppressor diode on backpanel EZ might be short
all VTB VTC C	00M1 0769 07749 6107749	E/W E	Configuration key is missing or defective <i>for future use: the existing CU has no configuration key and so this error message should never appear</i>	check that all chip pins properly stick in the socket EZ139 D38	if chip defective order 4512 100 45292 together with the generator serial number
all VTB VTC C	00M2	E/W	Unable to initialize the FU mA		
all VTB VTC C	00M3 0771 07751 6107751	E/W E	No response at all from FU(s) #1H, #2H, #3H, #4H, #5H, #6H the missing unit(s) will be indicated in the string at #1H, #2H ... , all other fields will indicate 00H unit indications at the top of this document		check if FCO 00 135 004 (high speed rotor control modification) has been carried out
all VTB VTC C	00M4 0772 07752 6107752	E	Function value from SE out of range <i>this error points to a failure which can only be caused by the software; a function call is performed from the function group MC and the module mcidle.c to a procedure in the function group SE, this procedure returns a parameter which is out of range</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00M5 0773 07753 6107753	E	Procedure index from SE out of range <i>this error points to a failure which can only be caused by the software; a function call is performed from the function group MC and the module mcidle.c to a procedure in the function group SE, this procedure returns a parameter which is out of range</i>		
all VTB VTC C	00MA 0785 07765	W	Limit for allocated memory exceeded, job id: #1 <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has detected, that the limit for the allocated memory for the job (referenced by the job id) is reached</i>		
all VTB VTC C	00MB 0786 07766	W	Limit for available memory exceeded, job id: #1 <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has detected, that the limit for the allocated memory for the job (referenced by the job id) is reached</i>		
all VTB VTC C	00MC 0787 07767	W	Limit for borrowed memory exceeded, job id: #1 <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has detected, that the limit for the borrowed memory for the job (referenced by the job id) is reached</i>		
all VTB VTC C	00MD 0788 07768	W	Allocated memory is increasing, job id: #1 <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has detected, that the limit for the allocated memory for the job (referenced by the job id) is increasing</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00ME 0789 07769	W	Available memory is decreasing, job id: #1 <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has detected, that the limit for the available memory for the job (referenced by the job id) is decreasing</i>		
all VTB VTC C	00MF 0790 07770	W	Borrowed memory is increasing, job id: #1 <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has detected, that the limit for the borrowed memory for the job (referenced by the job id) is increasing</i>		
all VTB VTC C	00MG 0791 07771	W	NVRAM: Main control, NV checksum error <i>the checksum of the table which stores the parameters for OSRAM is corrupted, this happens also when the table does not (yet) exist after installing a new CUBE board or parts of it</i>		
all VTB VTC C	00MH 0792 07772 6107772	E	Job incorrectly identified <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has not found all jobs under their expected names</i>		
all VTB VTC C	00MI 0793 07773	W	Limit for number of objects exceeded, job id: #1 <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has detected, that the limit for a number of objects for the job (referenced by the job id) is reached</i>		
all VTB VTC C	00MJ 0794 07774	W	Number of objects are increasing, job id: #1 <i>this error points to a failure which can only be caused by the software; a background program called OSRAM has detected, that the limit for a number of objects for the job (referenced by the job id) is increasing</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00MK 0795 07775	W	FU_mA filament checksum failed,FUtype:#1,filament:#2 <i>the data for the filament received from the FU is different to the data stored in the CU, parameter #2 is the filament number, #1 is the FU number, where FumA_A=3, FumA_B04 etc, #3 is the tube number (1...3) and #4 is the focus (1=SF 3=LF)</i>		
all VTB VTC C	00ML 0796 07776	W	<i>FU(s) failed, rebooting in CU only mode the CU could not contact one or more FU's necessary for running and so is rebooting in CU the only mode</i>		
all VTB VTC C	00MM 0797 07777	W	<i>job gone, job id: #1 this error points to a failure which can only be caused by the software; a background program called OSRAM analyses all jobs under their expected names, but the job identified by "job id" is now gone</i>		
all VTB VTC C	00MN 0798 07778	W	<i>FU msg too short; expect:#1 got:#3#2 fu:#4 iim:#5 mid:#6 a message has been received from an FU during startup of the CU which is shorter than the expected message; possibly incompatibility between CU and FU or problem with FU; expected size = param 1, receive size = params 2+3, FU = param 4, iim = p. 5</i>		
all VTB VTC C	00MO 0799 07779	W	<i>unexpected message; Fu type:#1, iim:#2 unexpected message received from an FU during CU startup; FU = param 1, iim received param 2; possibly incompatibility between CU and FU or problem with FU</i>		
all VTB VTC C	00MP 0800 07780	W	<i>generator performing automatic reboot the generator is about to reboot itself automatically</i>		
all VTB VTC C	00NO 0832 07848	W	<i>BX: LWDR message creation failed FS= #1H ERR= #2H the LWDR pack was unable to create the requested message; function selector requested was #1H and the LWDR pack error code was #2H</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00N1 0833 07849	W	<i>BX: table error FS= #1H PID= #2H SID #3#4H TYP= #5H CU could not find parameter info in its internal table; error parameter bytes: 1=function selector FS of faulty message, 2=parameter id PID of the faulty parameter of this message</i>		
all VTB VTC C	00N2 0834 07850	IR	<i>BX: rx LWDR param. missing FS=#1H PID=#2H SID=#3#4H st=#5H LWDR pack tried to decode a message which had one or more missing fixed parameters, function selector is #1H, sub-param. id #3#4H LWDR status is #5H</i>		
all VTB VTC C	00N3 0835 07851	IR	<i>BX: rx LWDR param. range FS=1H PID=#2H SID=#3#4H false parameter received from system controller, error param. bytes: 1=function selector FS of faulty message, 2=param. id PID of faulty param. in this message</i>		
all VTB VTC C	00N4 0836 07852	IR	<i>BX: rx LWDR corrupted FS=#1H PID=#2H SID=#3#4H st=#5H corrupted/invalid message received from system controller, error param. bytes: 1=function selector FS of faulty message, 2=param. id PID of the faulty parameter in this message</i>		
all VTB VTC C	00N5 0837 07853	IR	<i>BX: rx unknown LWDR message FS=#1H unknown LWDR message received from SC, possibly incompatibility problem SC-Velara, param. 1= function selector FS</i>		
all VTB VTC C	00N6 0838 07854	IR	<i>BX: tx LWDR param. range FS=#1H SID=#2H SID=#3#4H val=#5#6H TheBox is attempting to send a false parameter to CU, error parameter bytes: 1=function selector FS of faulty message, 2=parameter id PID of the faulty parameter in this message</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00N7 0839 07855	IR	<i>BX: tx LWDR param. error FS=#1H PID=#2H SID=#3#4H st=#5H TheBox is trying to send a corrupted/invalid message to system controller, error parameter bytes: 1=function selector FS of faulty message, 2=parameter id PID of the faulty parameter in this message, 3=internal error code</i>		
all VTB VTC C	00N8 0840 07856	IR	<i>BX: tx unknown LWDR message FS=#1H TheBox is trying to send an unknown LWDR message, possibly compatibility problem TheBox-Velara, parameter 1=function selector FS</i>		
all VTB VTC C	00N9 0841 07859	W	<i>BX: not enough memory TheBox ran out of memory trying to create an LWDR message</i>		
all VTB VTC C	00NA 0849 07865	E	<i>BX SDL: max transmit retries reached, Fit message lost a transmission towards the Integrus Acco failed</i>		
all VTB VTC C	00NB 0850 07866	E	<i>BX SDL: rx sequence mismatch, at least one Fit message lost synchronization problem at SDL level</i>		
all VTB VTC C	00NC 0851 07867	E	<i>BX SDL: tx sequence mismatch, at least one Fit message lost synchronization problem at SDL level</i>		
all VTB VTC C	00ND 0852 07868	W	<i>BX: unexpected message received fu_type=#1H, iim=#2H received an unexpected message, FU type is #1H iim is #2H</i>		
all VTB VTC C	00NE 0853 07869		<i>BX: multiple request signals on signal bus currently not used</i>		
all VTB VTC C	00NF 0854 07870	IR	<i>BX: Fit command not recognized unexpected or unrecognized Fit command received</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00NG 0855 07871	IR	<i>BX: Fit message number not recognized TheBox tried to encode or decode a Fit message with an unexpected or unrecognized message type</i>		
all VTB VTC C	00NH 0856 07872	IR	<i>BX: error in Fit message parameters a Fit parameter was either missing or incorrect</i>		
all VTB VTC C	00NI 0857 07873	W	<i>BX: unexpected Fit command #2#1H message #4#3H received an unexpected Fit command / message was received, the command is reported using #2#1H and the message type using #4#3H</i>		
all VTB VTC C	00NJ 0858 07874	IR	<i>BX: unexpected buffer #1H received TheBox attempted to process an unexpected buffer (given by #1H)</i>		
all VTB VTC C	00NK 0859 07875	W	<i>BX: unexpected LWDR function selector #1H received an unexpected LWDR message was received by TheBox, function selector =#1H</i>		
all VTB VTC C	00NL 0860 07876	IR	<i>BX: parameter out of range an internal parameter to a function call was out of range</i>		
all VTB VTC C	00NM 0861 07877	IR	<i>BX: illegal SID value read from hardware an illegal SID value has been read from the hardware</i>		
all VTB VTC C	00NN 0862 07878	W	<i>BX: SPD value out of range TheBox received an SID value which could not be converted into a valid LWDR EDL distance</i>		
all VTB VTC C	00NO 0863 07879	IR	<i>BX: curve parameter out of range a curve could not be calculated because the given curve parameters were out of range</i>		
all VTB VTC C	00NP 0864 07880	IR	<i>BX: unexpected state #1H an unexpected / invalid CU or TheBox state was received</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00NQ 0865 07881	W	<i>BX: CU info request #1H failed a request (number #1H) from TheBox to the CU software for information failed</i>		
all VTB VTC C	00NR 0866 07882	W	<i>BX: #1H kV not found in curve TheBox failed to find the required mA value in the curve returned by the Velara software</i>		
all VTB VTC C	00NS 0867 07883	W	<i>BX: attempt to divide by zero an attempt was made to divide a value by zero</i>		
all VTB VTC C	00NT 0868 07884	W	<i>BX: unexpected Fit command #1H TheBox has received an unexpected Fit command type, i.e. not one of SET – EVA – CP\$SET – RE\$SET – LOCK - UNLOCK</i>		
all VTB VTC C	00NU 0869 07885	IR	<i>BX: flag already set to #1H TheBox has attempted to set an internal flag when it already had the same value #1H</i>		
all VTB VTC C	00NV 0870 07886	W	<i>BX: SW timers exhausted TheBox has run out of internal software timers</i>		
all VTB VTC C	00NW 0871 07887	W	<i>BX: invalid NVRAM checksum for file no. #2#1H TheBox has tried to open the file number #1#1H and failed, if the file was corrupt then it has been replaced by a new file with default values in it; if it was missing then a new file has been created using the default values</i>		
all VTB VTC C	00NX 0872 07888	IR	<i>BX: given Fit parameter too long for message TheBox has tried to create a Fit message with an invalid (too long) parameter</i>		
all VTB VTC C	00PA 0977 08065	W	<i>CPU: IIM/MSC number unknown allowed are only IIMs/MSCs as all MSCN_DR and the MSCN_SE_MAIN; DRC will be called by a wrong IIM/MSC</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00PB 0978 08066	W	CPU: technique mode unknown <i>DR_modes means all specified CMs, the DRC calculation calls the wrong mode</i>		
all VTB VTC C	00PC 0979 08067	W IR	CPU: value limit overflow <i>CPU: DRC input parameter #1H out of range this occurs if the entry check of all parameters from XR fails or the boundary check of kV_mA_curve fails, one of these values is out of the specified range</i>		
all VTB VTC C	00PD 0980 08068 6108068	E	PC communication: unknown TDL proc id <i>the service call to DRC is wrong, the called service procedure is not available in DRC</i>		
all VTB VTC C	00PE 0981 08069	W	NVRAM: DRC NV checksum error = appears with a non-programmed CU after the very first turn-on = when appearing after CU Complete restore the data file might be defective <i>checksum of NV RAM is invalid/wrong, maybe a NV problem</i>		if permanent erase NV-RAM (see ..\..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf) and start programming from scratch dump CU Complete file which won't work, download CU Complete again using Agent 3.1.2, get it from the Intranet ..\..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf
all VTB VTC C	00PF 0982 08070	W	CPU: equal kV-sets from CU comes twice <i>the kV_mA_curves or kV_mA_ms_curves, gotten from CU SW, contain more than two equal following kV curve points</i>		
all VTB VTC C	00PG 0983 08071	W	CPU: kV sequence does not increase <i>this warning occurs when the following kV value of a curve point doesn't decrease, DRC got this curve from CU</i>		
all VTB VTC C	00PH 0984 08072	W	CPU: EDL is not possible, min_mA limit <i>this warning will never occur with Velara, EDL is deactivated in DRC for Velara release 1</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00PI 0985 08073	W	CPU: DCALC Dr_curve has only one element <i>this warning occurs when a dose rate curve doesn't exist</i>		
all VTB VTC C	00PJ 0986 08074	W	CPU: DCALC Dr_curve has strange values <i>DRC expanded the curve coming from CU; this warning occurs if DRC makes an expand error</i>		
all VTB VTC C	00PK 0987 08075	W	CPU: equal kV sets from CU with equal mA <i>the kV_mA_curves for continuous fluoro, gotten from CU, contain more than one equal following kV_mA curve points</i>		
all VTB VTC C	00PL 0988 08076	W	dose digits disturbance = noise level at chamber signal input increases a limit value before kV is started <i>this warning occurs if the measurement of the dose signal increases 20mV before the exposure is started</i>	check signal waveform in standby, prep and ready 2 condition before exposure starts the chamber signal at EZ150 X4 should not be > 20mV release 3.3 and > 80mV release 3.5, otherwise the problem source has to be investigated	= solved with release 3.5 (higher limit value) = does not exist at release 2.x generators
all VTB VTC C	00PM 0989 08077	W IR	CPU::PULS: value limit overflow <i>CPU: :PULS: input parameter #1H out of range this occurs if the entry check of all parameters from CU fails, especially for pulsed technique; one of these values is out of the specified range</i>		
all VTB VTC C	00PN 0990 08078	W	CPU::PULS: equal kV-sets from CU comes twice <i>the kV_mA_ms curves for a pulsed technique, gotten from CU, contain more than one equal following kV_mA_ms curve points</i>		
all VTB VTC C	00PO 0991 08079	W	CPU: calculation during pulse <i>this warning occurs if the control method changes during a pulse technique which is actually running in an x-ray pulse</i>		
all VTB VTC C	00PP 0992 08080	W	CPU: :DR-ICE: dose too high, limited more than 500% of the dose has been measured relatively to the expected (100%) dose		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00PQ 0993 08081	W	<i>CPU: :DRC: dose much smaller after exposure than during exposure the 'published' dose will be taken from the latest time during pulse</i>		
all VTB VTC C	00PR 0994 08082	IR	<i>CPU: :DRC: parameter concerning the sensor doesn't fit FDXD installed, but data set sent with SensorScanTime of 0; this is not compatible with FDXD</i>		
all VTB VTC C	00PS 0995 08083	W	<i>CPU: :DRC: Pulse-Statemachine inconsistence; cause: #1H this warning is issued at state machine failure result with a parameter (values 1-5); values from 1-4 are internal for development, value 5 typically means that the requested frame speed and the realized frame speed are not the same</i>		
all VTB VTC C	00S* 1146 08342	PC log-in entry	every PC service log-in XRGSCOPE or APRMAN causes this entry to indicate service work	too many entries can be prevented by keeping XRGSCOPE active even when the connection might be disconnected or the generator is turned off + on	
all VTB VTC C	00S? 1167 08363 6108363	E	PC communication: unexpected error <i>an internal software / runtime problem was detected; under normal conditions it shall never happen</i>		
all VTB VTC C	00S0 1152 08348 6108348	E	PC communication; tube programming error <i>during the tube data programming a data distribution error occurred</i>		
all VTB VTC C	00S1 1153 08349	W	<i>PC communication: reconfiguration needed the configuration stored at the NVRAM does not match with the configuration stored at the FlashDisk; this could mean that the battery is empty or the FlashDisk is corrupted or something was changed, e.g. a function unit or the FlashDisk or the CUBE board</i>		
all VTB VTC C	00S2 1154 08350	E	<i>PC communication: timeout reached can occur in the CU simulation mode or more generally if a task does not respond to a service request within 5 minutes</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00S3 1155 08351	W	PCcomm: service interface speed fall back performed the persistent baudrate of 115kbps was wited back to the default 9600bps because a lower baudrate was used by the service tool		
all VTB VTC C	00S4 1156 08352	W	PCcomm: CU battery lifetime low the CU battery lifetime is low, its lifetime may have exceeded its 2 year guaranteed lifetime		
all VTB VTC C	00S5 1157 08353	E	PCcomm: restore process failed the restore of a backup file was not successful		
all VTB VTC C	00S6 1158 08354	W	PCcomm: restore data from different firmware version the backup was made by a different version of the firmware than that which is currently running on the system; it is possible that some restored data were ignored or overridden with different data		
all VTB VTC C	00SA 1169 08365 6108365	E	PC communication: Not enough space at destination segment <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SB 1170 08366	E	PC communication: Base out of range <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SC 1171 08367 6108367	E	PC communication: Value too large <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SD 1172 08368 6108368	E	PC communication: Terminator not found <i>this is a software bug, nothing to fix, maybe retry will help</i>		if XRGSCOPE is used to program film-screen-combinations Optimus RAD-R/F release ≥3.6, use AGenT 4.1.1. ..\..\data_collection\AGenT\AGenT-4-1-1--download-pages-and-PC-settings.pdf
all VTB VTC C	00SE 1173 08369 6108369	E	PC communication: Error in description <i>this is a software bug, nothing to fix, maybe retry will help</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00SF 1174 08370 6108370	E	PC communication: Item type unknown <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SG 1175 08371 6108371	E	PC communication: Internal type unknown <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SH 1176 08372 6108372	W	PC communication: Value negative <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SI 1177 08373	E	PC communication: Not enough space at destination buffer <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SJ 1178 08374 6108374	E	PC communication: Syntax wrong <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SK 1179 08375 6108375	E	PC communication: String too long <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SL 1180 08376	W	PC communication: String truncated <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SM 1181 08377	E	PC communication: TDL segment overflow <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SN 1182 08378 6108378	E	PC communication: FU reference table full <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SO 1183 08379 6108379	E	PC communication: Node ID unknown <i>this is a software bug, nothing to fix, maybe retry will help</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00SP 1184 08380 6108380	E	PC communication: FU Code unknown <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SQ 1185 08381 6108381	E	PC communication: Syntax error in node ID = can happen if the PC boots up with the generator on and the communication cable to CU already connected <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SR 1186 08382	W	PC communication: No node ID found <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SS 1187 08383 6108383	E	PC communication: Request not performed <i>the request sent to the generator could not be performed, because the request was not allowed, incorrect or a previous error leads to this response</i>		
all VTB VTC C	00ST 1188 08384 6108384	E	PC communication: RMX error <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SU 1189 08385	W	PC communication: Enumeration element not found <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SV 1190 08386 6108386	E	PC communication: Mail corrupted <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SW 1191 08387 6108387	E	PC communication: Procedure ID unknown <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00SX 1192 08388 6108388	E	PC communication: FU mA incompatible <i>the version of FU_mA could not be handled by the CU firmware</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00SY 1193 08389 6108389	E	PC communication: FU Off request failed <i>the FU was requested to stop operation, but it didn't work</i>		
all VTB VTC C	00SZ 1194 08390 6108390	E	PC communication: Wrong response <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00T? 1231 08463 6108463	E	TTS: Unexpected Error <i>an internal resource problem was detected</i>		
all VTB VTC C	00TA 1233 08465 6108465	E	TTS: Received Message unknown <i>the received message is unknown and will not be processed</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00TB 1234 08466 6108466	E	tube temperature supervision error from FU_kv <i>tube housing contact or cable defect, detected by FU_kv</i>	<p>= short to ground or signal noise from any source at tube housing thermal switch signal EZX3 / EWGX8 / EWGX9</p> <p>- pins 3-4 back panel version 4512 108 05983</p> <p>- pins 6-7 back panel versions 4512 108 05984 + 4512 108 09361</p> <p>remove cable connection and insert a decade plug with a short link pins 3-4 or 6-7 instead to simulate the tube housing contact, if problem disappears, if not measure signal TH_OL_SW/ at EZ130 X1:A11, details see ..\data_collection\faultfinding\mnemonic_routing.pdf</p> <p>= short to ground at signal TH_OL EZ130 X1:A12, signal routing of TH_OL see ..\data_collection\faultfinding\mnemonic_routing.pdf</p> <p>this signal is not used in any system as a thermal tube sensor is not available yet</p> <p>with PC and XRGSCOPE: go path >Select Unit > FU-kV > FU-kV > Faultfind > Monitoring > Measure Temperatures ></p> <p>tube temp switch: should be closed = ok will have short circuit =00TB can be = open if connection removed</p>	<p>problem might be caused by non-screened stator and thermal switch cables</p> <p>screened stator cable 3 x 1.31mm*2 0722 215 02054</p> <p>2-wire screened cable for thermal switch 4512 100 66151</p>
all VTB VTC C	00TC 1235 08467 6108467	E	internal tube temperature supervision error <i>for more info see TTS internal error logging</i>		<p>tube data table corrupted? = can happen after CU Complete restore if tubes are of a different speed type = reboot generator to get it into a stable standby condition, then repeat loading of CU Complete. = if error persistent even after reboot erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase_Optimus_RAD_RF_C.pdf and start programming from scratch</p>

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00TD 1236 08468 6108468	E	TTS: Tube Number unknown <i>this is a software bug, nothing to fix, maybe retry will help</i>		
all VTB VTC C	00TE 1237 08469 6108469	E	TTS: NVRAM Checksum Error <i>the checksum found is not correct, that could mean that the battery is empty or the NVRAM is corrupt</i>		
all VTB VTC C	00TF 1238 08470 6108470	E	TTS: NVRAM unavailable <i>the requested NVRAM space is unavailable</i>		
all VTB VTC C	00TG 1239 08471 6108471	E	TTS: Tube overheated <i>the temperature of the focal track exceeds the T0 limit</i>	1) mA measuring circuit might be defective, check circuit in standby against oscilloscope screenshot ma_pulse.pcx most likely in non-AEC technique 2) wrong calculation of switched loads	1) exchange high tension transformer 2) exchange FU_mA PROM by version 4512 113 20212 check if application data (APR, system dependent) can be improved
all VTB VTC C	00TH 1240 08472	W	TTS: Load Data Supply inconsistent <i>one or more of the values (mAs, t, mA, kV) are 0</i>		
all VTB VTC C	00TI 1241 08473	W	TTS: tube housing contact state inconsistent <i>the tube housing contact is open, but the calculated temperature of the tube doesn't match with it; check the tube type programming or cooling unit</i>		
all VTB VTC C	00TJ 1242 08474	W	TTS: cooling unit defect <i>cooling unit is defective</i>		
all VTB VTC C	00X0 1472 08848 6108848	E/W E	FU_RC high speed did not respond to a stator request within the time required Duo: CPU wrong timer id <i>the FU_RoCo did not respond during tube switch to a stator request within the time required</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00X1 1473 08849 6108849	E/W E	FU_RC high speed did not obtain the requested speed within the time required Duo: CPU wrong timer mode		
all VTB VTC C	00X2 1475 08850 6108850	E/W E	wrong message type <i>internal CAN_send failed the transmission of a message on the CAN bus to the FU_RoCo / _kV / _mA failed</i>		
all VTB VTC C	00X3 1475 08851	E/W E	DWORD does not fit into BYTE3 <i>FU_kV tube select timeout FU_kV did not respond to a tube selection request within the time required</i>		
all VTB VTC C	00X4 1476 08852 6108852	E/W E	timeout of X-ray backup timer <i>FU_kV data set timeout FU_kV did not respond to the data setting message within the time required</i>	1) check backup time with kV-mA-ms technique at screen Faultfind > X-Ray log > Dose Rate Control Logging > Non Automatic Technique Calculation: t_nominal is the safety backup time of CU 2) switch exposure, then read screen > Read Actual Status; if time measured > t_nominal exchange mA control PCB	
all VTB VTC C	00X5 1477 08853	E/W E	timeout of X-ray rotation timer <i>FU_mA data setting failed FU_mA rejected the x-ray parameter setting</i>		try replacement of desk hand-switch 4512 104 36801
all VTB VTC C	00X6 1478 08854	E/W E	timeout setting function units, response missing <i>FU_mA grid test failed</i>		if in combination with 00XK + 07LJ load tube file again
all VTB VTC C	00X7 1479 08855	E/W E	curve token is NO_TOKEN <i>FU_mA data set timeout FU_mA did not respond to the data setting messages within the time required</i>		
all VTB VTC C	00X8 1480 08856	E	<i>FU_mA not installed the data set from AD specifies a tube / focus combination which is not available</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00X9 1481 08857	E	<i>DRC calculation timeout DRC did not respond to a calculation request within the time required</i>		
all VTB VTC C	00XA 1489 08865	E/W E	switch table invalid <i>no DRC mode the x-ray mode / nomogram selector combination in the data set does not yield a valid DRC mode</i>		
all VTB VTC C	00XB 1490 08866	E/W E	tube data rotation invalid = appears with a non-programmed CU after the very first turn-on = when appearing after CU Complete restore the data file might be defective <i>FU_mA off request timeout FU_mA control state machine has not responded to a request to go to the OFF state within the time required</i>		if permanent erase NV-RAM (see ..\data_collection\info_files\Memory_quick_erase _Optimus_RAD_RF_C.pdf and start programming from scratch dump CU Complete file which won't work, download CU Complete again using Agent 3.1.2, get it from the Intranet <a href="..\data_collection\AGenT\AGenT-download-
pages-and-PC-settings.pdf">..\data_collection\AGenT\AGenT-download- pages-and-PC-settings.pdf
all VTB VTC C	00XC 1491 08867	E/W E	watch dog invalid <i>FU_kV off request timeout fU_kV control state machine has not responded to a request to go to the OFF state within the time required</i>		
all VTB VTC C	00XD 1492 08868	E/W E	configuration table invalid <i>FU_RoCo init request timeout FU_RoCo state machine has not responded to a request to go to the INIT state within the time required</i>		
all VTB VTC C	00XE 1493 08869	E/W E	test data invalid <i>FU_mA off to standby request timeout FU_mA control state machine has not responded to a request to go to the STANDBY state from the OFF state within the time required</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00XF 1494 08870	E/W E	rotor control high speed data invalid <i>FU_kV of to standby request timeout FU_kV control state machine has not responded to a request to go to the STANDBY state from the OFF state within the time required</i>		
all VTB VTC C	00XG 1495 08871	E/W E	received internal interrupt message is unknown <i>FU_RoCo init to stopped request timeout FU_RoCo state machine has not responded to a request to go to the STOPPED state from the INIT state within the time required</i>		
all VTB VTC C	00XH 1496 08872	E/W E	received function unit type unknown <i>FU_mA prep to standby request timeout FU_mA control state machine has not responded to a request to go to the STANDBY state from a PREP state within the time required</i>		
all VTB VTC C	00XI 1497 08873 6108873	E/W E	initialization with FU_RC high speed not ok <i>FU_kV prep to standby request timeout FU_kV control state machine has not responded to a request to go to the STANDBY state from a PREP state within the time required</i>		check if FCO 00 135 004 at FU_RC has been carried out
all VTB VTC C	00XJ 1498 08874 6108874	E/W E	exposure time too short <i>FU_RoCo prep to stopped request timeout FU_RoCo state machine has not responded to a request to go to the STOPPED state from a PREP state within the time required</i>	might occur in combination with 02WG tube arcing (or other 02xx kV errors) if the exposure has been terminated prior to a controlled termination of AEC or mA_control; look for adjacent errors in the error log index which occurred at the same time	
all VTB VTC C	00XK 1499 08875	E/W E	FU_mA refuses data set <i>FU_mA standby to prep request timeout FU_mA control state machine has not responded to a request to go to the requested PREP state from the STANDBY state within the time required</i>		if in combination with 07LJ + 00X6 load tube file again

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00XL 1500 08876	E/W E	<p>tube yield table invalid = appears with a non-programmed CU after the very first turn-on = when appearing after CU Complete restore the data file might be defective</p> <p><i>FU_kV standby to prep request timeout FU_kV control state machine has not responded to a request to go to the requested PREP state from the STANDBY state within the time required</i></p>		<p>if permanent erase NV-RAM (see ..\..\data_collection\info_files\Memory_quick_erase Optimus RAD RF C.pdf and start programming from scratch</p> <p>dump CU Complete file which won't work, download CU Complete again using Agent 3.1.2, get it from the Intranet ..\..\data_collection\AGenT\AGenT-download-pages-and-PC-settings.pdf</p>
all VTB VTC C	00XM 1501 08877	E/W E	<p>additional collimator filter correction table invalid</p> <p><i>FU_RoCo stopped to prep request timeout FU_RoCo state machine has not responded to a request to go to the requested START state from the STOPPED state within the time required</i></p>		
all VTB VTC C	00XN 1502 08878	E/W E	<p>collimator wedge filter correction table invalid</p> <p><i>FU_mA prep to prepx request timeout FU_mA control state machine has not responded to a request to go to the PREPARED XRAY state from the PREP state within the time required</i></p>		
all VTB VTC C	00XO 1503 08879 6108879	E/W E	<p>exposure time too long</p> <p><i>FU handler looping the main loop in the procedure to run all FU state machines has run more than the specified maximum loops without reaching a stable state</i></p>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00XP 1504 08880	E/W W	exposure time too long <i>SW timers exhausted more timers have been requested than the module Xrswtim can maintain</i>	most likely in free techniques without AEC, FU_mA terminates non-EAC exposures once the set mAs are achieved, if X_ACT_S/ has not been received as mAs counter trigger or if STOP_X_C/ has not been sent by FU_mA CU terminates the exposure; !! can be logged even though the exposure has been interrupted prior to a regular termination in combination with 02xx kV errors !! look for adjacent errors in the error log index which occurred at the same time	
all VTB VTC C	00XQ 1505 08881	E/W W	tube statistic data invalid - when upgrading a generator form release 3.3 or 3.4 to 3.5 as the tube counter tables are of different format <i>unknown input message unexpected message received</i>		
all VTB VTC C	00XR 1506 08882	E/W W	gsta data invalid <i>run data collect timeout run data could not be collected within the time required</i>		
all VTB VTC C	00XS 1507 08883	E/W W	tube number in CU and FU_kV different might appear in combination with 02WA <i>run x-ray off timeout notification of X-ray off has not been received from the radiation state machine within the time required</i>	check status of tube selection signals TB_2/ EZ130 X1:A13 TB_3/ EZ130 X1:C13 there should not be multiple selections, TB_2/ and/or TB_3/ must not be low active if tube 1 is selected; does WGK1 (2WGK1) switch the 230VAC between X61 / X62 ? if so, is a suppressor diode parallel to the TB_?_RT/ short? check at the backpanel drawings	if multiple selections are active exchange kV control PCB; exchange WG PCB; remove suppressor diode or exchange backpanel PCB EZ;

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00XT 1508 08884	E/W W	Rotation in CU and FU_RC high speed or FU_CIE for low speed different. If more than 4 PREP's have been switched within one minute the 5th will cause this entry not allowing the next acceleration to prevent overheating of the stator. <i>set x-ray off timeout notification of X-ray off has not been received from the radiation state machine within the time required</i>	bouncing hand switch? check behavior at EN_X/ EZX82	If in combination with 10LA (FU_RC high speed only) program "enable" at "rotation prolongation after prep".
all VTB VTC C	00XU 1509 08885 6108885	W	input message field out of range <i>input message field out of range procedures 8003, 8004, 8005, 8009, 8010, 8018, 8030, 8031, 8032, 8033, 8035: a field in the message has an unexpected value</i>		can happen during transition fluoro to exposure, Scopomat exposures only, solved with release 3.5
all VTB VTC C	00XV 1510 08886	W	NVRAM HW test flags invalid <i>kV value not in specified yield table the kV value from DRC is not within the range of the specified yield table provided for the current tube</i>		
all VTB VTC C	00XW 1511 08887 6108887	E	EN_X active in startup <i>frid not allowed by FU_mA grid mode has been selected for a tube / focus combination that does not support grid mode</i>		
all VTB VTC C	00XX 1512 08888 6108888	E W	RD_PR_X stays active after prep <i>FU_mA le-adaptation aborted FU_mA aborts the emission current adaptation</i>		
all VTB VTC C	00XY 1513 08889	W	<i>FU_mA boost-adaptation aborted FU_mA aborts boost adaptation</i>		
all VTB VTC C	00XZ 1514 08890	W	<i>adap-request in adaptation procedure (8030 le and/or 8031 boost) adaptation request received while adaptation in progress</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00Y0 1536 08948	E	<i>specific yield out of range, adjusted a zero value has been detected in the yield table</i>		
all VTB VTC C	00Y1 1537 08949	E	<i>FU_kV tube select failed FU_kV did not respond to tube selection message</i>		
all VTB VTC C	00Y2 1538 08950	E	<i>FU_RoCo braking timeout FU_RoCo did not confirm that the rotor was stopped</i>		
all VTB VTC C	00Y3 1539 08951	E	<i>SE rotation speeds not compatible with FU_RoCo the rotation speeds XR got during start up from SE and FU_RoCo don't fit</i>		
all VTB VTC C	00Y4 1540 08952	IR	<i>curve invalid curve received from AD is not valid</i>		
all VTB VTC C	00Y5 1541 08953	IR	<i>requested index not received the selected index to play was not recorded before</i>		
all VTB VTC C	00Y6 1542 08954	IR	<i>play mode invalid only the record / play mode is allowed to change if you switch from record to play</i>		
all VTB VTC C	00Y7 1543 08955	-	<i>error is disabled</i>		
all VTB VTC C	00Y8 1544 08956	W	<i>adaptation parameters changed by AD the requested adaptation parameter from the FU_mA got changed by AD</i>		
all VTB VTC C	00Y9 1545 08957	W	<i>wait time for CTRL_X in adaptation exceeded user started adaptation but waited too long before applying CTRL_X signal to allow adaptation exposures</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00YA 1553 08965	W	<i>adaptation : filament not available ADAP SM requests adaptation of filament which is not in configuration</i>		
all VTB VTC C	00YB 1554 08966	E	<i>XR manager looping the main loop in the procedure to run all XR state machines has run more than the specified maximum loops without reaching a stable state</i>		
all VTB VTC C	00YC 1555 08967	E	<i>FU_mA simulation mode request timeout FU_mA has not responded to a simulation request within the time required</i>		
all VTB VTC C	00YD 1556 08968	W	<i>FU_mA calibration timeout no response to FU_mA calibration request</i>		
all VTB VTC C	00YE 1557 08969	E	<i>X_ACT_S signal missing the X_ACT_S signal is not connected to the CU</i>		
all VTB VTC C	00YF 1558 08970	IR	<i>tube switch during preparation a tube switch was requested when generator not in standby</i>		
all VTB VTC C	00YG 1599 08971	E	<i>filament status message not received XR not initialized properly</i>		
all VTB VTC C	00YH 1560 08972	E	<i>CAN configuration message not received XR not initialized properly</i>		
all VTB VTC C	00YI 1561 08973	E	<i>options message not received XR not initialized properly</i>		
all VTB VTC C	00YJ 1562 08974	E	<i>software backup timeout software backup timer terminated X-ray</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00YK 1563 08975	W	<i>EN_X signal missing the EN_X signal is not connected to the CU</i>		
all VTB VTC C	00YL 1564 08976	E	<i>CON_EN_X_C failure the EN_X_C signal could not be set via CON_EN_X_C</i>		
all VTB VTC C	00YM 1565 08977	E	<i>dose limit cannot be kept, le below Imin to keep the dose rate limit EDL has to go below the Imin emission current value</i>		
all VTB VTC C	00YN 1566 08978	W	<i>EN_X signal detected at start-up the PREP signal EN_X detected at start-up</i>		
all VTB VTC C	00YO 1567 08979	W	<i>RQ_SN_X signal detected at start-up RQ_SN_X signal detected at start-up</i>		
all VTB VTC C	00YP 1568 08980	W	<i>CTRL_X signal detected at start-up the X-ray signal CTRL_X detected at start-up</i>		
all VTB VTC C	00YQ 1569 08981	W	<i>CTRL_X_C signal detected at start-up the X-ray signal CTRL_X_C detected at start-up</i>		
all VTB VTC C	00YR 1570 08982	W	<i>X_ACT_S signal detected at start-up the X-ray signal X_ACT_S detected at start-up</i>		
all VTB VTC C	00YS 1571 08983	W	<i>NR_PR_X signal failure at start-up PREP ready signal NR_PR_X failure at start-up</i>		
all VTB VTC C	00YT 1572 08984	W	<i>CTRL_X_C signal detected in STANDBY X-ray signal CTRL_X_C detected in STANDBY</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00YU 1573 08985	E	X_ACT_S signal detected in STANDBY X-ray signal X_ACT_S detected in STANDBY		
all VTB VTC C	00YV 1574 08986	E	dose rate limit cannot be kept, t below t-min to keep the dose rate limit, EDL has to go below the t-min value		
all VTB VTC C	00YW 1575 08987	E	dose rate limit cannot be kept, Q below Q-min to keep the dose rate limit, EDL has to go below the Q-min value		
all VTB VTC C	00YX 1576 08988	IR	X-ray mode invalid requested X-ray mode not allowed in simulation without X-ray		
all VTB VTC C	00YY 1577 08989	IR	simulation mode request invalid simulation mode request under wrong conditions		
all VTB VTC C	00YZ 1578 08990	E	invalid segment length in message from FU unexpected message format received from a function unit		
all VTB VTC C	00Z0 1600 09048	E	emergency reduction data set required an emergency reduced data set is required but not sent yet to XR		
all VTB VTC C	00Z1 1601 09049	W	no FU_RoCo reply to re-trigger message FU_RoCo did not send a reply to a re-trigger message (rotation request)		
all VTB VTC C	00Z2 1602 09050	IR	second update filament checksum request before the 1 st request is finished XR got a 2 nd update filament checksum request		
all VTB VTC C	00Z3 1603 09051	IR	request for not installed filament XR got a request for a not installed filament		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00Z4 1604 09052	W	<i>FU_mA filament limit data request timeout on a filament limit data request to FU_mA</i>		
all VTB VTC C	00Z5 1605 09053	W	<i>cooling unit coolant flow defect the cooling unit of the tube's coolant can no longer be guaranteed</i>		
all VTB VTC C	00Z6 1606 09054	IR	<i>data setting during idle with PREP in idle and PREP condition a data setting is not allowed</i>		
all VTB VTC C	00Z7 1607 09055	W	<i>no rotation limits from FU_RoCo at start-up no information from FU_RoCo at start-up</i>		
all VTB VTC C	00Z8 1608 09056	E	<i>emergency power limit exceeded whilst running an emergency data set the 330W limit has been exceeded</i>		
all VTB VTC C	00Z9 1609 09057	W	<i>filament #1H state #2H from FU_mA, assumed not installed XR received an undefined filament state from FU_mA</i>		
all VTB VTC C	00ZA 1617 09065	W	<i>NVRAM checksum bad of tube yield table tube yield tables NVRAM data corrupt or missing, default values will be used</i>		
all VTB VTC C	00ZB 1618 09066	W	<i>NVRAM checksum bad of tube statistics tube statistics NVRAM data corrupted or missing, new data will be created</i>		
all VTB VTC C	00ZC 1619 09067	W	<i>NVRAM checksum bad of tube load units tube load units NVRAM data corrupted or missing, new data will be created; can be caused by a software update</i>		
all VTB VTC C	00ZD 1620 09068	W	<i>FU_kV standby to PREP slow FU_kV took longer than expected getting to PREP</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	00ZE 1621 09069	W	<i>FU_mA standby to PREP slow FU_mA took longer than expected getting to PREP</i>		
all VTB VTC C	00ZF 1622 09070	W	<i>FU_mA grid test slow FU_mA grid test took longer than expected</i>		
all VTB VTC C	00ZG 1623 09071	E	<i>record mode invalid an APR for record mode has been received with an invalid control method in it</i>		
all VTB VTC C	00ZH 1624 09072	E	<i>rotation speeds inconsistent the CU has requested FU_RoCo to accelerate to a given (non-zero) speed, but RoCo has reported a different speed (i.e. rotation speeds inconsistent); cause is too many requests to RoCo within a minute, before and after a tube switch-over</i>		
all VTB VTC C	02AB 4114 26566	W	<i>procedure called with wrong parameter software development error</i>		
all VTB VTC C	02AC 4115 26567 6126567	E	<i>wrong index for table access software development error</i>		
all VTB VTC C	02AD 4116 26568 6126568	E	<i>wrong do case entry software development error</i>		
all VTB VTC C	02AE 4117 26569	W	<i>unknown IIM received software development error</i>		
all VTB VTC C	02AF 4118 26570	W	<i>IIM parameter out of range software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02CA 4241 26765	W	error in CASE selector <i>internal software failure, possibly caused by defective hardware</i>		
all VTB VTC C	02CB 4242 26766	W	a CAN message with wrong IIM-no (no recipient defined) received <i>CU sent IIM, which the FU didn't know; possibly inconsistency between FU or CU version (release/level); wrong version installed?</i>		
all VTB VTC C	02CC 4243 26767	W	multiple reception of the same CAN frame (transmitter ill) <i>communication with CU disturbed, possibly CU overloaded</i>		
all VTB VTC C	02CE 4245 26769	W	unexpected signal value in CAN rx task <i>reception from CU disturbed</i>		
all VTB VTC C	02CF 4246 26770	W	CAN bus timeout while domain transmission <i>transmission to CU disturbed</i>		
all VTB VTC C	02CG 4247 26771	W	token of CAN response mailbox is not a mailbox token <i>error message 00CF not reported because wrong error mailbox token</i>		
all VTB VTC C	02CX 4264 26788	W	multiple rx of the same CAN last/only frame (transmitter ill) <i>reception from CU disturbed</i>		
all VTB VTC C	02CY 4265 26789	W	aborted CAN domain receive (because of timeout or wrong signal) <i>reception from CU disturbed</i>		
all VTB VTC C	02CZ 4266 26790	W	unexpected CAN domain frame received (outside IIM-reception) <i>reception from CU disturbed, message is delivered nevertheless</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02DA 4305 26865	W	no CPU access to the CAN controller <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	02DB 4306 26866	W	reset or release of the CAN controller was not acknowledged <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	02DD 4308 26868	W	check of the DPRAM of the CAN controller failed <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	02DE 4309 26869	W	unexpected interrupt pointer in the CAN controller <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	02DF 4310 26870	W	CAN controller state undefined <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	02DG 4311 26871	W	CAN controller state ERROR ACTIVE after ERROR PASSIVE <i>info: 02DH ended</i>		
all VTB VTC C	02DH 4312 26872	W	CAN controller state ERROR PASSIVE <i>function unit CAN chip error because of detected transmission problem; it's just an info, the transmissions still working; possibly no running function unit connected to the CAN bus or EMC problems</i>		
all VTB VTC C	02DI 4313 26873	W	CAN controller state BUS OFF <i>function unit CAN chip serious error because of detected transmission problems (probably EMC); no transmission possible until next start-up</i>		
all VTB VTC C	02DJ 4314 26874	W	CAN controller state DPRAM ERROR <i>problem with CAN chip on the function unit</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02DK 4315 26875	W	CAN controller state DPRAM ERROR and ERROR PASSIVE <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	02EA 4369 26965 6126965	E	interrupt 0: divide by zero <i>SW or HW development error</i>		
all VTB VTC C	02EB 4370 26966 6126966	E	interrupt 1: single step <i>SW or HW development error</i>		
all VTB VTC C	02EC 4271 26967 6126967	E	interrupt 2: NMI <i>SW or HW development error</i>		
all VTB VTC C	02ED 4372 26968 6126968	E	interrupt 3: breakpoint <i>SW or HW development error</i>		
all VTB VTC C	02EE 4373 26969 6126969	E	interrupt 4: overflow exception <i>SW or HW development error</i>		
all VTB VTC C	02EF 4374 26970 6126970	E	interrupt 5: array bounds exception <i>SW or HW development error</i>		
all VTB VTC C	02EG 4375 26971 6126971	E	interrupt 6: unused opcode <i>SW or HW development error</i>		
all VTB VTC C	02EH 4376 26972 6126972	E	interrupt 7: ESC opcode <i>SW or HW development error</i>		
all VTB VTC C	02EI 4377 26973 6126973	E	CAN connection to CU lost		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02GA 4497 27165	W	interpolation not possible		
all VTB VTC C	02HA 4561 27265	W	kV nominal value out of range +/- (4%+1kV) 3 measurements within 30ms <i>kV nominal value out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get kV nominal , then read Error: Specific Information to get the faulty value	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 = if all supplies ok replace PCB
all VTB VTC C	02HB 0462 27266 6127266	E	kV nominal value out of range 0kV > U > 170kV <i>kV nominal value out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get kV nominal , then read Error: Specific Information to get the faulty value	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 = if all supplies ok replace PCB
all VTB VTC C	02HC 0463 27267	W	Z nominal value out of range +/- 1% +/- 0.2 3 measurements within 30ms duty cycle range Z = 3...30% <i>Z nominal value out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get Z nominal , then read Error: Specific Information to get the faulty value	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 = if all supplies ok replace PCB
all VTB VTC C	02HD 4564 27268 6127268	E	Z nominal value out of range 0% > Z > 50% duty cycle range Z = 3...30% <i>Z nominal value out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get Z nominal , then read Error: Specific Information to get the faulty value	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 = if all supplies ok replace PCB

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HE 4565 27269	W	kV actual value too large during transition standby to exposure ➤ 3kV at > 400ms after PREP <i>kV value during standby too large</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: Specific Information to get the faulty value monitor with oscilloscope at EZ130 X3 AVHT 20kV/V trigger: EN_X/ EZX82	check signal connections EZ130 to HT measuring circuit EG100 connection details see ..\data_collection\faultfinding\mnemonic_routing.pdf check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02HF 4566 27270 6127270	E	kV actual value too large during transition standby to exposure > 4kV at > 400ms after PREP <i>kV value during standby too large</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: Specific Information to get the faulty value monitor with oscilloscope at EZ130 X3 AVHT 20kV/V trigger: EN_X/ EZX82	check signal connections EZ130 to HT measuring circuit EG100 connection details see ..\data_collection\faultfinding\mnemonic_routing.pdf check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HG 4567 27271 6127271	W	kV actual value out of range +/- (4% +1kV) 2 measurements within 20ms <i>kV actual value out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get kV nominal , then read Error: Read HW Values to get the faulty value monitor with oscilloscope at EZ130 X3 AVHT 20kV/V or X4 anode and X5 cathode trigger: CTRL_X_C/ EZX74 check mains conditions	release 2 generators: = check kV behavior against document ..\data_collection\kV_control\kV1_2_mod.pdf and carry out modification if necessary = carry out kV driver test chapter 8.2 FAULT FINDING release 3 generators: = check and carry out adjustment "factor for duty" cycle according to document ..\data_collection\kV_control\OPTIMUS_RF_6_b_010.pdf = carry out kV driver test chapter 5.3 register Converter R/F = check if FCO 00 135 014 has been carried out check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HH 4568 27272 6127272	E	kV actual value out of range 20kV > U > 170kV 3 measurements within 30ms <i>kV actual value out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get kV nominal , then read Error: Read HW Values to get the faulty value monitor with oscilloscope at EZ130 X3 AVHT 20kV/V or X4 anode and X5 cathode trigger: CTRL_X_C/ EZX74 check mains conditions	release 2 generators: = check kV behavior against document ..\data_collection\kV_control\kV1_2_mod.pdf and carry out modification if necessary = carry out kV driver test chapter 8.2 FAULT FINDING release 3 generators: = check and carry out adjustment "factor for duty" cycle according to document ..\data_collection\kV_control\OPTIMUS_RF_6_b_010.pdf = carry out kV driver test chapter 5.3 register Converter R/F = check if FCO 00 135 014 has been carried out check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HI 4569 27273 6127273	W	E value (converter DC) during standby out of range 470V > E > 780V 3 measurements within 30ms <i>E value during standby out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select screen Error: Read HW Values to get the faulty value measure with multi meter at ENK2:41 :42 when generator is on and ENK1 energized !! Attention High Voltage !! might appear after a converter damage, breakers and fuses might have been on after the event, generator was turned on with short in converter which lets the damping resistors ENR1...3 open the springs (can be soldered on again)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB if ceramic body is cracked exchange damping spring resistor version dependent: release 2 generators with 100 Ohms resistors (horizontal mounting) 4512 100 44941 release 2+3 generators with 47 Ohms resistors (vertical mounting) 4512 100 45441

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HJ 4570 27274 6127274	E	E value (converter DC) during standby out of range 450V > E > 800V 3 measurements within 30ms <i>E value during standby out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select screen Error: Read HW Values to get the faulty value measure with multi meter at ENK2:41 :42 when generator is on and ENK1 energized !! Attention High Voltage !! might appear after a converter damage, breakers and fuses might have been on after the event, generator was turned on with short in converter which lets the damping resistors ENR1...3 open the springs (can be soldered on again) -15VDC missing at turn-on, typically in combination with 03PB + 03HM	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB if ceramic body is cracked exchange damping spring resistor version dependent: release 2 generators with 100 Ohms resistors (horizontal mounting) 4512 100 44941 release 2+3 generators with 47 Ohms resistors (vertical mounting) 4512 100 45441 try to find the reason for the missing -15VDC, remove PCBs and all external devices using -15V like e.g. measuring chambers, suppressor diode on backpanel EZ might be short

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HK 4571 27275 6127275	W	E value (converter DC) during high tension out of range 400V > E > 780V 3 measurements within 30ms <i>E value during high tension out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select screen Error: Read HW Values to get the faulty value monitor with oscilloscope at - EZ130 X1:A5 X1:C5 24V = 750V (E value) frontal converter EQ (measuring point for all release 2 generators and all 50kW generators with one converter only) - EZ130 X1:A26 X1:C26 24V = 750V (E value) rear converter E2Q (all release 3 generators with 2 converters)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02HL 4572 27276 6127276	E	E value (converter DC) during high tension out of range 350V > E > 800V 3 measurements within 30ms <i>E value during high tension out of range</i>	with PC and XRGSCOPE: select error # from error log index list, select screen Error: Read HW Values to get the faulty value monitor with oscilloscope at - EZ130 X1:A5 X1:C5 24V = 750V (E value) frontal converter EQ (measuring point for all release 2 generators and all 50kW generators with one converter only) - EZ130 X1:A26 X1:C26 24V = 750V (E value) rear converter E2Q (all release 3 generators with 2 converters)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HM 4573 27277 6127277	W	converter 1 temperature out of range 0 deg C > T > 85 deg C 3 measurements within 30ms	4.4V...1.5V = 20...100 deg C EZ130 X1:C6 measured with NTC resistor 15kOhms (+/-10%, 20 deg C)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02HN 4574 27278 6127278	E	converter 1 temperature out of range 0 deg C > T > 90 deg C 3 measurements within 30ms	4.4V...1.5V = 20...100 deg C EZ130 X1:C6 measured with NTC resistor 15kOhms (+/-10%, 20 deg C)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB ready re-appears only after re-boot of generator if problem solved
all VTB VTC C	02HO 4575 27279 6127279	W	converter 2 temperature out of range 0 deg C > T > 85 deg C 3 measurements within 30ms	4.4V...1.5V = 20...100 deg C EZ130 X1:C27 measured with NTC resistor 15kOhms (+/-10%, 20 deg C)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HP 4576 27280 6127280	E	converter 2 temperature out of range 0 deg C > T > 90 deg C 3 measurements within 30ms	4.4V...1.5V = 20...100 deg C EZ130 X1:C27 measured with NTC resistor 15kOhms (+/-10%, 20 deg C)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB ready re-appears only after re-boot of generator if problem solved
all VTB VTC C	02HQ 4577 27281 6127281	W	high tension tank temperature out of range 0 deg C > T > 80 deg C 3 measurements within 30ms	4.4V...1.5V = 20...100 deg C EZ130 X1:C19 measured with NTC resistor 15kOhms (+/-10%, 20 deg C)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02HR 4578 27282 6127282	E	high tension tank temperature out of range 0 deg C > T > 85 deg C 3 measurements within 30ms	4.4V...1.5V = 20...100 deg C EZ130 X1:C19 measured with NTC resistor 15kOhms (+/-10%, 20 deg C)	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB ready re-appears only after re-boot of generator if problem solved

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HS 4579 27283 6127283	W	divider test cathode out of range 45.5kV > U > 50.5kV 3 measurements within 30ms	compare waveform during preparation or fluoroscopy start from anode standstill against preptest.pcx oscilloscope screenshot	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02HT 4580 27284 6127284	E	divider test cathode out of range 43kV >= U > 53kV	compare waveform during preparation or fluoroscopy start from anode standstill against preptest.pcx oscilloscope screenshot	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02HU 4581 27285 6127285	W	divider test anode out of range 45.5kV > U > 50.5kV 3 measurements within 30ms	compare waveform during preparation or fluoroscopy start from anode standstill against preptest.pcx oscilloscope screenshot	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02HV 4582 27286 6127286	E	divider test anode out of range 43kV >= U > 53kV 3 measurements within 30ms	compare waveform during preparation or fluoroscopy start from anode standstill against preptest.pcx oscilloscope screenshot	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02HW 4583 27287 6127287	W	kV anode out of range or asymmetrical +/-15% 2 measurements within 20ms <i>kV asymmetrical</i>	monitor kV actual value at EZ130 X4 (anode 20kV/V) EZ130 X5 (cathode 20kV/V, value also positive) or EZ130 X1:C17 (anode 10kV/V) EZ130 X1:C16 (cathode 10kV/V) trigger EZX74 CTRL_X_C/	check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02HX 4584 27288 6127288	E	kV anode out or range or asymmetrical +/-15% 3 measurements within 30ms <i>kV asymmetrical</i>	monitor kV actual value at EZ130 X4 (anode 20kV/V) EZ130 X5 (cathode 20kV/V, value also positive) or EZ130 X1:C17 (anode 10kV/V) EZ130 X1:C16 (cathode 10kV/V) trigger EZX74 CTRL_X_C/	release 2 generators: = check kV behavior against document ..\data_collection\kV_control\kV1_2_mod.pdf and carry out modification if necessary = carry out kV driver test chapter 8.2 FAULT FINDING release 3 generators: = check and carry out adjustment "factor for duty" cycle according to document ..\data_collection\kV_control\OPTIMUS_RF_6_b 010.pdf = carry out kV driver test chapter 5.3 register Converter R/F = check if FCO 00 135 014 has been carried out check supply voltages EZ130 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	02MA 4881 27765 6127765	E	state request not accepted because of grid mode <i>software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02MB 4882 27766 6127766	E	state request not accepted because of error state		
all VTB VTC C	02MC 4883 27767 612767	W	state requested by CU unknown		
all VTB VTC C	02OA 5009 27965 6127965	E	RMX error: timeout <i>software development error</i>		
all VTB VTC C	02OB 5010 27966 6127966	E	RMX error: memory <i>software development error</i>		
all VTB VTC C	02OC 5011 27967 6127967	E	RMX error: busy <i>software development error</i>		
all VTB VTC C	02OE 5013 27969 6127969	E	RMX error: limit <i>software development error</i>		
all VTB VTC C	02OF 5014 27970 6127970	E	RMX error: context <i>software development error</i>		
all VTB VTC C	02OG 5015 27971 6127971	E	RMX error: exist <i>software development error</i>		
all VTB VTC C	02OH 5016 27972 6127972	E	RMX error: state <i>software development error</i>		
all VTB VTC C	02OI 5017 27973 6127973	E	RMX error: not configured <i>software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02OJ 5018 27974 6127974	E	RMX error: interrupt saturation <i>software development error</i>		
all VTB VTC C	02OK 5019 27975 6127975	E	RMX error: interrupt overflow <i>software development error</i>		
all VTB VTC C	02OL 5020 27976 6127976	E	RMX error: transmission <i>software development error</i>		
all VTB VTC C	02OM 5021 27977 6127977	E	RMX error: divide by zero <i>software development error</i>		
all VTB VTC C	02ON 5022 27978 6127978	E	RMX error: overflow <i>software development error</i>		
all VTB VTC C	02OO 5023 27979 6127979	E	RMX error: type <i>software development error</i>		
all VTB VTC C	02OP 5024 27980 6127980	E	RMX error: parameter <i>software development error</i>		
all VTB VTC C	02OQ 5025 27981 6127981	E	RMX error: bad call <i>software development error</i>		
all VTB VTC C	02OR 5026 27982 6127982	E	RMX error: array bound <i>software development error</i>		
all VTB VTC C	02OS 5027 27983 6127983	E	RMX error: NDP error <i>software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02OT 5028 27984 6127984	E	RMX error: illegal opcode <i>software development error</i>		
all VTB VTC C	02OU 5029 27985 6127985	E	RMX error: emulator trap <i>software development error</i>		
all VTB VTC C	02OV 5030 27986 6127986	E	RMX error: interrupt table limit <i>software development error</i>		
all VTB VTC C	02OW 5031 27987 6127987	E	RMX error: CPU xfer data limit <i>software development error</i>		
all VTB VTC C	02OX 5032 27988 6127988	E	RMX error: wrap around <i>software development error</i>		
all VTB VTC C	02OY 5033 27989 6127989	E	RMX error: check exception <i>software development error</i>		
all VTB VTC C	02OZ 5034 27990 6127990	E	RMX error: unknown <i>software development error</i>		
all VTB VTC C	02RA 5201 28265	W	grid mode changeover requested during prep		
all VTB VTC C	02RB 5202 28266	W	tube switch requested during preparation		
all VTB VTC C	02RC 5203 28267	W	requested P out of range		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02SA 5265 28365	W	Not enough space at the destination		
all VTB VTC C	02SB 5266 28366	W	Base out of range		
all VTB VTC C	02SC 5267 28367	W	PC comm.: Value too large		
all VTB VTC C	02SD 5268 28368	W	Terminator not found		
all VTB VTC C	02SE 5269 28369	W	PC comm.: Error in description		
all VTB VTC C	02SF 5270 28370	W	PC comm.: Item type unknown		
all VTB VTC C	02SG 5271 28371	W	PC comm.: Internal type unknown		
all VTB VTC C	02SH 5272 28372	W	PC comm.: Value negative		
all VTB VTC C	02SI 5273 28373	W	PC comm.: No space at dest. buffer		
all VTB VTC C	02SJ 5274 28374	W	PC comm.: Syntax wrong		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02SK 5275 28375	W	PC comm.: String too long		
all VTB VTC C	02SL 5276 28373	W	PC comm.: String truncated		
all VTB VTC C	02SO 5275 28379	W	PC comm.: Unknown Table ID Received		
all VTB VTC C	02SP 5280 28380	W	PC comm.: Access Level to Low		
all VTB VTC C	02SQ 5281 28381	W	PC comm.: Unknown Action Requested		
all VTB VTC C	02SR 5282 28382	W	PC comm.: Routing or Message Corrupt		
all VTB VTC C	02SS 5283 28383	W	Source Buffer to Small for Incoming Message		
all VTB VTC C	02ST 5284 28384	W	CAN Buffer to Small for Outgoing Message		
all VTB VTC C	02SU 5285 28385	W	PC comm.: Access. level is N_A		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02UA 5393 28565 6128565	F/E E	HW configuration identifier wrong FU kV starts blinking during turn-on, once CU starts blinking FU kV turns LED on = FATAL error <i>HW configuration identifier wrong</i>	check resistances 460ohms each Q100 X1:21 against X1:19 and X1:23 for each converter, check continuity of cable(s) Q100X1 – EZX24 / 34 2) check that signal SI_PH/ is not zero, normal level about 2.6V, signal path EN100X1:5-EZX47:5-EZ130X1:C14	
all VTB VTC C	02UB 5394 28566	W	Set Up request received during preparation		
all VTB VTC C	02UC 5395 28567	W	adaptation aborted because no suitable correction value could be found		
all VTB VTC C	02VA 5457 28665	W	<i>DSP: divider test cathode out of range</i>		
all VTB VTC C	02WA 5521 28765	W	wrong tube selected might appear in combination with 00XS <i>wrong tube selected</i>	check status of tube selection signals TB_2/ EZ130 X1:A13 TB_3/ EZ130 X1:C13 there should not be multiple selections, TB_2/ and/or TB_3/ must not be low active if tube 1 is selected; does WGK1 (2WGK1) switch the 230VAC between X61 / X62 ? if so, is a suppressor diode parallel to the TB_?_RT/ short? check at the backpanel drawings	if multiple selections are active exchange kV control PCB; exchange WG PCB; remove suppressor diode or exchange backpanel PCB EZ;
all VTB VTC C	02WB 5522 28766 3128766	E	wrong tube selected		
all VTB VTC C	02WC 5523 28767	W	EN X C signal faulty		
all VTB VTC C	02WD 5524 28768 6128768	E	EN X C signal faulty		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02WE 5525 27769 6127769	W	wrong grid mode selected		
all VTB VTC C	02WF 5526 28770 6128770	E	wrong grid mode selected		
all VTB VTC C	02WG 5527 28771 6128771	W	tube arcing detected	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get kV nominal switch an exposure with this value and check kV actual value signal waveform against arcng.pcx or arcng2.pcx	carry out tube conditioning procedure tube_conditioning.doc to improve tube behavior
all VTB VTC C	02WH 5528 28772 6128772	E	tube arcing detected	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get kV nominal switch an exposure with this value and check kV actual value signal waveform against arcng.pcx or arcng2.pcx	carry out tube conditioning procedure tube_conditioning.doc to improve tube behavior
all VTB VTC C	02WI 5529 28773 6128773	W	kV over voltage detected <i>converter 1 kV over voltage detected</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get kV nominal , then read Error: Read HW Values to get the faulty value monitor with oscilloscope at EZ130 X3 AVHT 20kV/V or X4 anode and X5 cathode trigger: CTRL_X_C/ EZX74	

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02WJ 5530 28774 6128774	E	kV over voltage detected <i>converter 1 kV over voltage detected</i>	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values to get kV nominal , then read Error: Read HW Values to get the faulty value monitor with oscilloscope at EZ130 X3 AVHT 20kV/V or X4 anode and X5 cathode trigger: CTRL_X_C/ EZX74	
all VTB VTC C	02WK 5531 28775 6128775	W	measuring not stable	if problem can not be solved with FCO 00 135 015 check if there are other error entries like 00CD, 00M3 (look for details: which unit is sending or missing) = if a function unit is on such a detail screen check its function: does the LED blink or is it on? problem might not at all be linked to kV functions	check if solution can be found with FCO 00 135 015 , see file
all VTB VTC C	02WL 5532 28776 6128776	E	Tube Supervision Error		
all VTB VTC C	02WM 5533 28777 6128777	E	Tube Supervision Error		
all VTB VTC C	02WN 5534 28778	W	converter 1 overload detected <i>converter 1 over current detected</i>		
all VTB VTC C	02WO 5535 28779	E	converter 1 overload detected <i>converter 1 over current detected</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02WP 5536 28780	W	<i>converter 2 over voltage detected</i>		
all VTB VTC C	02WQ 5537 28781	E	<i>converter 2 over voltage detected</i>		
all VTB VTC C	02WR 5538 28782	W	<i>converter 2 over current detected</i>		
all VTB VTC C	02WS 5539 28783	E	<i>converter 2 over current detected</i>		
all VTB VTC C	02WT 5540 28784	W	<i>converter 1 short circuit detected</i>		
all VTB VTC C	02WU 5541 28785	E	<i>converter 1 short circuit detected</i>		
all VTB VTC C	02WV 5542 28786	W	<i>converter 2 short circuit detected</i>		
all VTB VTC C	02WW 5543 28787	E	<i>converter 2 short circuit detected</i>		
all VTB VTC C	02WX 5544 28788	W	<i>DSP: watchdog</i>		
all VTB VTC C	02WY 5545 28789	W	<i>DSP: error unknown</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	02WZ 5546 28790	W	DSP: divider test anode out of range		
all VTB VTC C	03AA 6161 36565	W	Internal parameter error <i>software development error on FU_mA or CU</i>		
all VTB VTC C	03AB 6162 36566	W	Wrong parameter from CU <i>software development error on CU</i>		
all VTB VTC C	03AC 6163 36567	W	emission current regulation active on two filaments <i>software development error on CU</i>	under normal conditions only one focus is active during exposure and fluoroscopy, the second focus is in standby = exception: Variofocus; the small focus filament current is always constant, the additional part of the emission current Variofocus will be controlled by the large focus	
all VTB VTC C	03AI 6169 36573	W	Wrong IIM received <i>software development error on CU</i>		
all VTB VTC C	03BA 6225 36665	W	Coordinates not monotonic boost adaptation error <i>problems with the measurement of the emission current boost curve</i>	with PC and XRGSCOPE: Select Unit > FU-mA > FU-mA > Faultfind > Adaptation Results > Select Adaptation Table for Reading type in at focus: 1 = large focus tube 1 2 = small focus tube 1 and a kV value between min and max or if known the kV value at which the generator errors > Read Previously Selected Adaptation Table detailed explanations see sheet ..\data_collection\mA_control\If-Ie-data-table.pdf	use firmware of FU_mA version 4512 113 20212 if previous version installed
all VTB VTC C	03BB 6226 36666	W	No measurement values for adaptation found <i>emission current measurement failed</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03CA 6289 36765	W	Error in CASE selector <i>internal software failure, perhaps caused by defective hardware</i>		
all VTB VTC C	03CB 6290 36766	W	A CAN message with wrong IIM-no (no recipient defined) received <i>CU sent IIM which the function unit didn't know; possibly inconsistency between FU or CU version (release/level); has a wrong version just been installed?</i>		
all VTB VTC C	03CC 6291 36767	W	multiple reception of the same CAN frame (transmitter ill) <i>communication with CU disturbed, possibly CU overloaded</i>		
all VTB VTC C	03CE 6293 36769	W	unexpected signal value in CAN rx task <i>reception from CU disturbed</i>		
all VTB VTC C	03CF 6294 36770	W	CAN bus timeout while domain transmission <i>transmission to CU disturbed</i>		
all VTB VTC C	03CG 6295 36771	W	token of CAN response mailbox is not a mailbox token <i>error message 03CF not reported because wrong error mailbox token</i>		
all VTB VTC C	03CX 6312 36788	W	multiple rx of the same CAN last/only frame (transmitter ill) <i>reception from CU disturbed</i>		
all VTB VTC C	03CY 6313 36789	W	aborted CAN domain receive (because of timeout or wrong signal) <i>reception from CU disturbed</i>		
all VTB VTC C	03CZ 6314 36790	W	unexpected CAN domain frame received (outside IIM-reception) <i>reception from CU disturbed, message is delivered nevertheless</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03DA 6353 36865	W	no CPU access to the CAN controller <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	03DB 6354 36866	W	reset or release of the CAN controller was not acknowledged <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	03DD 6356 36868	W	check of the DPRAM of the CAN controller failed <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	03DE 6357 36869	W	unexpected interrupt pointer in the CAN controller <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	03DF 6358 36870	W	CAN controller state undefined <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	03DG 6359 36871	W	CAN controller state ERROR ACTIVE after ERROR PASSIVE <i>info: 03DH ended</i>		
all VTB VTC C	03DH 6360 36872	W	CAN controller state ERROR PASSIVE <i>function unit CAN chip error because of detected transmission problem; it is just an info, the transmission is still working; possibly no running FU connected to the CAN bus or EMC problems</i>		
all VTB VTC C	03DI 6361 36873	W	CAN controller state BUS OFF <i>function unit CAN chip serious error because of detected transmission (probably EMC) problems; no transmission possible until next start-up</i>		
all VTB VTC C	03DJ 6362 36874	W	CAN controller state DPRAM ERROR <i>problem with CAN chip on function unit</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03DK 6363 36875	W	CAN controller state DPRAM ERROR and ERROR PASSIVE <i>problem with CAN chip on function unit</i>		
all VTB VTC C	03EA 6417 36965 6136965	E	CPU interrupt 0 <i>software or hardware development error</i>		
all VTB VTC C	03EB 6418 36966 6136966	E	CPU interrupt 1 <i>software or hardware development error</i>		
all VTB VTC C	03EC 6419 36967	E	CPU interrupt 2 <i>software or hardware development error</i>		
all VTB VTC C	03ED 6420 36968 6136968	E	CPU interrupt 3 <i>software or hardware development error</i>		
all VTB VTC C	03EE 6421 36969 6136969	E	CPU interrupt 4 <i>software or hardware development error</i>		
all VTB VTC C	03EF 6422 36970 6136970	E	CPU interrupt 5 <i>software or hardware development error</i>		
all VTB VTC C	03EG 6423 36971 6136971	E	CPU interrupt 6 <i>software or hardware development error</i>		
all VTB VTC C	03EH 6424 36972 6136972	E	CPU interrupt 7 <i>software or hardware development error</i>		
all VTB VTC C	03EI 6425 36973 6136973	E	CAN is unable to send an error to CU		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03FA 6481 37065	W	NVRAM: Invalid checksum occurs at turn-on/warm-start if checksum changed <i>NVRAM: invalid checksum data lost</i>	"Test" might be displayed for one or both filaments	re-adapt the non-adapted filament
all VTB VTC C	03FB 6482 37066	W	NVRAM: Standby filament not found <i>software development error</i>		
all VTB VTC C	03FC 6483 37067 6137067	E	No NVRAM plugged in <i>memory not found</i>		
all VTB VTC C	03FD 6484 37068	W	NVRAM empty	battery jumper in ON position?	battery empty ?
all VTB VTC C	03GA 6545 37165 6137165	E	Linint error <i>software development error</i>		
all VTB VTC C	03GB 6546 37166	W	Real math. error: real underflow <i>software development error</i>		
all VTB VTC C	03GC 6547 37167	W	Real math. error: real overflow <i>software development error</i>		
all VTB VTC C	03GD 6548 37168	W	Real math. error: dword overflow <i>software development error</i>		
all VTB VTC C	03GE 6549 37169	W	Real math. error: integer overflow <i>software development error</i>		
all VTB VTC C	03GF 6550 37170	W	Real math. error: word overflow <i>software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03GG 6551 37171	W	Singular matrix <i>software development error</i>		
all VTB VTC C	03GH 6552 37172	W	Real math. error: negative square root <i>software development error</i>		
all VTB VTC C	03HA 6609 37265 6137265	E	Unknown hardware		exchange PCB and firmware
all VTB VTC C	03HB 6610 37266 6137266	E/W	Intermediate circuit voltage < 200 V	= mains phase 2 present ? = check the fuses F3 and F1+2 where present = with PC and XRGSCOPE: select error # from error log index list, select screen Error: Read HW Values to get the faulty value = switch the generator off and wait about 1 minute before removing PCB EZ119 !! Attention High Voltage !! put PCB on extender and turn on measure with multi meter at EZ119 capacitors C18/19/20, should be 325VDC +/-10%	has the modification on EZ119 (versions with 3 fuses) with a 33nF capacitor parallel to triac V36 been carried out which comes with the firmware upgrade kits for release 2 and 3 ? (optical check: big flat capacitor at the soldering side of the PCB) check supply voltages EZ119 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if values indicated at the detail screens do not match the externally measured ones exchange PCB
all VTB VTC C	03HF 6614 37270	W	Undefined analog input channel <i>software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03HG 6615 37271 6137271	W	If-actual out of tolerance	<p>= check high tension cable cathode plug pins at generator and tube side</p> <p>= with PC and XRGSCOPE: select error # from error log index list, select error details and read screen</p> <p>Error: Read HW Values to get the set point and the faulty value fil. circuit 1 = small focus fil. circuit 2 = large focus</p> <p>= monitor with oscilloscope at EZ119 X5 = small focus EZ119 X7 = large focus 1V = 2.5A filament current</p> <p>= mains phase 2 present?</p> <p>= try HT cable exchange if the actual ones very old / suspicious</p> <p>= installation: 230VAC lines for HT solenoids connected?</p>	<p>check supply voltages EZ119 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15</p> <p>if values indicated at the detail screens do not match the externally measured ones exchange PCB</p>
all VTB VTC C	03HH 6616 37272 6137272	E	If set point too large	<p>= with PC and XRGSCOPE: select error # from error log index list, select error details and read screen</p> <p>Error: Read HW Values to get the set point value displayed</p> <p>= if error persistent go path > Select Unit > FU-mA > FU-mA > Faultfind > Monitoring > read If nominal fil. circuit 1 = small focus fil. circuit 2 = large focus</p>	<p>check supply voltages EZ119 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15</p>

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03HI 6617 37273 6137273	E	If-actual out of tolerance <i>500mA out of tolerance</i>	<p>= check contacts of high tension cable cathode plug pins at generator and tube side, common connection poor if error during prep</p> <p>= with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: Read HW Values to get the set point and the faulty value fil. circuit 1 = small focus fil. circuit 2 = large focus</p> <p>= monitor with oscilloscope at EZ119 X5 = small focus EZ119 X7 = large focus 1V = 2.5A filament current</p> <p>= mains phase 2 present?</p>	<p>check supply voltages EZ119 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15</p> <p>if values indicated at the detail screens do not match the externally measured ones exchange PCB</p>
all VTB VTC C	03HJ 6618 37274 6137274	E	If-actual out of tolerance <i>1A out of tolerance</i>	<p>= check contacts of high tension cable cathode plug pins at generator and tube side</p> <p>= with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: Read HW Values to get the set point and the faulty value fil. circuit 1 = small focus fil. circuit 2 = large focus</p> <p>= monitor with oscilloscope at EZ119 X5 = small focus EZ119 X7 = large focus 1V = 2.5A filament current</p> <p>= mains phase 2 present?</p> <p>= installation: 230VAC lines for HT solenoids connected?</p>	<p>check supply voltages EZ119 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15</p> <p>if values indicated at the detail screens do not match the externally measured ones exchange PCB</p>

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03HK 6619 37275 6137275	W	If-nominal out of tolerance	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values and Error: Read HW Values the set point values must be identical at both screens = if error persistent go path > Select Unit > FU-mA > FU-mA > Faultfind > Monitoring > read If nominal fil. circuit 1 = small focus fil. circuit 2 = large focus	check supply voltages EZ119 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if supply voltages ok but error persistent replace PCB
all VTB VTC C	03HL 6620 37276 6137276	E	If-nominal out of tolerance	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values and Error: Read HW Values the set point values must be identical at both screens = if error persistent go path > Select Unit > FU-mA > FU-mA > Faultfind > Monitoring > read If nominal fil. circuit 1 = small focus fil. circuit 2 = large focus	check supply voltages EZ119 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if supply voltages ok but error persistent replace PCB

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03HM 6621 37277 6137277	E	If-nominal out of tolerance	with PC and XRGSCOPE: select error # from error log index list, select error details and read screen Error: HW Set Values and Error: Read HW Values the set point values must be identical at both screens = if error persistent go path > Select Unit > FU-mA > FU-mA > Faultfind > Monitoring > read If nominal fil. circuit 1 = small focus fil. circuit 2 = large focus -15VDC missing at turn-on, typically in combination with 03PB + 02HJ	check supply voltages EZ119 + 5V X2:AC1 X2:AC2 +15V X2:AC11 - 15V X2:AC12 +26V X2:AC14 against ground X2:AC15 if supply voltages ok but error persistent replace PCB try to find the reason for the missing -15VDC, remove PCBs and all external devices using -15V like e.g. measuring chambers, suppressor diode on backpanel EZ might be short
all VTB VTC C	03HN 6622 37278 6137278	E	No re-trigger received from CU		
all VTB VTC C	03IA 6673 37365	W	Adaptation can not be completed		
all VTB VTC C	03IC 6675 37367	W	No Emission current -adaptation measurement values		
all VTB VTC C	03ID 6676 37368	W	Emission current -adaptation values could not be evaluated		
all VTB VTC C	03KA 6801 37565	W	conditioning-X-Ray mode without mAs parameter		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03MA 6929 37765	W	Undefined status <i>software development error</i>		
all VTB VTC C	03MB 6930 37766	W	Status change not allowed		
all VTB VTC C	03MC 6931 37767	W	FU init data not expected		
all VTB VTC C	03OA 7057 37965 6137965	E	RMX exception: E\$TIME <i>software development error</i>		
all VTB VTC C	03OB 7058 37966 6137966	E	RMX exception: E\$MEM <i>software development error</i>		
all VTB VTC C	03OC 7059 37967 6137967	E	RMX exception: E\$BUSY <i>software development error</i>		
all VTB VTC C	03OD 7060 37968 6137968	E	RMX exception: E\$LIMIT <i>software development error</i>		
all VTB VTC C	03OE 7061 37969 6137969	E	RMX exception: E\$CONTEXT <i>software development error</i>		
all VTB VTC C	03OF 7062 37970 6137970	E	RMX exception: E\$EXIST <i>software development error</i>		
all VTB VTC C	03OG 7063 37971 6137971	E	RMX exception: E\$STATE <i>software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03OH 7064 37972 6137972	E	RMX exception: E\$NOT\$CONFIGURED <i>software development error</i>		
all VTB VTC C	03OI 7065 37973 6137973	E	RMX exception: E\$INTERRUPT\$SATURATION <i>software development error</i>		
all VTB VTC C	03OJ 7066 37974 6137974	E	RMX exception: E\$INTERRUPT\$OVERFLOW <i>software development error</i>		
all VTB VTC C	03OK 7067 37975 6137975	E	RMX exception: E\$TRANSMISSION <i>software development error</i>		
all VTB VTC C	03OL 7068 37976 6137976	E	RMX exception: E\$ZERO\$DIVIDE <i>software development error</i>		
all VTB VTC C	03OM 7069 37977 6137977	E	RMX exception: E\$OVERFLOW <i>software development error</i>		
all VTB VTC C	03ON 7070 37978 6137978	E	RMX exception: E\$TYPE <i>software development error</i>		
all VTB VTC C	03OO 7071 37979 6137979	E	RMX exception: E\$PARAM <i>software development error</i>		
all VTB VTC C	03OP 7072 37980 6137980	E	RMX exception: E\$BAD\$CALL <i>software development error</i>		
all VTB VTC C	03OQ 7073 37981 6137981	E	RMX exception: E\$ARRAY\$BOUND <i>software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03OR 7074 37982 6137982	E	RMX exception: E\$NDP\$ERROR <i>software development error</i>		
all VTB VTC C	03OS 7075 37983 6137983	E	RMX exception: E\$ILLEGAL\$OPCODE <i>software development error</i>		
all VTB VTC C	03OT 7076 37984 6137984	E	RMX exception: E\$EMULATOR\$TRAP <i>software development error</i>		
all VTB VTC C	03OU 7077 37985 6137985	E	RMX exception: E\$INTERRUPT\$TABLE\$LIMIT <i>software development error</i>		
all VTB VTC C	03OV 7078 37986 6137986	E	RMX exception: E\$CPUXFER\$DATA\$LIMIT <i>software development error</i>		
all VTB VTC C	03OW 7079 37987 6137987	E	RMX exception: E\$SEG\$WRAP\$AROUND <i>software development error</i>		
all VTB VTC C	03OX 7080 37988 6137988	E	RMX exception: E\$CHECK\$EXCEPTION <i>software development error</i>		
all VTB VTC C	03OY 7081 37989 6137989	E	unknown RMX exception <i>software development error</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03PC 7123 38067 6138067	E	le = emission current out of tolerance (+/- 30% if le > 5mA and exp. time > 44 ms) <i>emission current out of tolerance</i>	Connect an oscilloscope at EZ119 X7 large focus or X5 small focus and monitor the filament current behavior. Set kV-mA-ms technique with 50% of the max mA value at any kV value with an exposure time of 50ms. Any deviation between mA_set and mA_measured will cause a reaction in the filament current. If mA_measured is lower compared to mA_set the filament current will rise (up to filament max), if mA_measured is higher compared to mA_set the filament current will drop down to min 0.5A. check the mA measuring circuit in standby against oscilloscope screenshot ma_pulse.pcx	If errors appear during normal work and if the tube has not been adapted for long time carry out re-adaptation.
all VTB VTC C	03PD 7124 38068	W	Set point for emission current regulation incorrect.		
all VTB VTC C	03PE 7125 38069 6138069	E	Emergency off! Grid not closed!		
all VTB VTC C	03PF 7126 38070 6138070	E	No kV discharge due to missing emission current.	Conditioning procedures must never be carried out with small filaments, not enough emission current achieved within a certain time	Installation: HT cables anode and cathode side interchanged at one side? Short circuit in HT cable for selected focus. Filament short circuit, possibly in combination with 03PA.
all VTB VTC C	03PG 7127 38071	W	Grid defect!		
all VTB VTC C	03SC 7315 38367	W	PC comm.: Value too large		
all VTB VTC C	03SE 7317 38369	W	PC comm.: Error in description		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03SF 7318 38370	W	PC comm.: Item type unknown		
all VTB VTC C	03SG 7319 38371	W	PC comm.: Internal type unknown		
all VTB VTC C	03SH 7320 38372	W	PC comm.: Value negative		
all VTB VTC C	03SI 7321 38373	W	PC comm.: No space at dest. buffer		
all VTB VTC C	03SJ 7322 38374	W	PC comm.: Syntax wrong		
all VTB VTC C	03SK 7323 38375	W	PC comm.: String too long		
all VTB VTC C	03SL 7324 38376	W	PC comm.: String truncated		
all VTB VTC C	03SO 7327 38379	W	PC comm.: Unknown Table ID Received		
all VTB VTC C	03SP 3728 38380	W	PC comm.: Access Level to Low		
all VTB VTC C	03SQ 03SQ 38381	W	PC comm.: Unknown Action Requested		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	03SR 7330 38382	W	PC comm.: Routing or Message Corrupt		
all VTB VTC C	03SU 7333 38385	W	PC comm.: Access. level is N_A		
all VTB VTC C	07CA 6176765	E	CAN: case-selector error		
all VTB VTC C	07CB	W	CAN: invalid CAN ID %u		
all VTB VTC C	07CC 6176767	E	CAN: frame repeat overflow IIM%u		
all VTB VTC C	07CD 6176768	E	CAN: no retry from CU	+26VDC missing at WA unit?	
all VTB VTC C	07CE 6176769	E	CAN: rx signal conflict IIM%u		
all VTB VTC C	07CF 6176770	E	CAN: tx timeout		
all VTB VTC C	07CI	W	CAN: IMPOSSIBLE ERROR		
all VTB VTC C	07CP	W	CAN: CPU: Pxerr %d %s(%d)		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	07CR	W	CAN: CPU: message request fail		
all VTB VTC C	07CS	W	CAN: CPU: message send error		
all VTB VTC C	07CY 6176789	E	CAN: rx abort IIM%u		
all VTB VTC C	07CZ	W	CAN: unexpected frame (IIM%u)		
all VTB VTC C	07DA 6176865	E	CA: chip access error		
all VTB VTC C	07DB 6176866	E	CAN: chip reset error		
all VTB VTC C	07DC 6176867	E	CAN: chip reset release error		
all VTB VTC C	07DE	W	CAN: illegal interrupt pointer		
all VTB VTC C	07DF 6176870	E	CAN: chip state undefined		
all VTB VTC C	07DG	W	CAN: chip err act. after pass.		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	07DH	W	CAN: chip state error passive		
all VTB VTC C	07DI	W	CAN: chip state bus-off		
all VTB VTC C	07DJ 6176874	E	CAN: chip DPRAM error		
all VTB VTC C	07DK	W	CAN: chip DPRAM error&passive		
all VTB VTC C	07DL	W	CAN: unexpected interrupt		
all VTB VTC C	07LA	W	CV received IIM unknown		
all VTB VTC C	07LB	W	rotor control stator number not available		
all VTB VTC C	07LC	W	rotor control stator not available		
all VTB VTC C	07LD 6177668	E	rotor control stator 1 read back failed		
all VTB VTC C	07LE 6177669	E	rotor control stator 2 read back failed		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	07LF 6177670	E	rotor control stator 3 read back failed		
all VTB VTC C	07LG	W	rotor control speed value out of range		
all VTB VTC C	07LH 6177672	E	rotor control speed set timeout		
all VTB VTC C	07LI	W	rotor control max stator load exceeded		If more than 4 PREP have been switched within one minute the 5th will cause this entry not allowing the next acceleration to prevent overheating of the stator.
all VTB VTC C	07LJ 6177674	E	maximal rotation time low speed rotor control exceeded = FU_CIE time out if preparation still active after 60 seconds, exposure ready disappears after max free run time 30 seconds		= during adaptation if in installation with BuckyTH system BuCo release 5.x which does not allow an exposure repetition, change settings free cassette RGDV syncmaster present = no Mounted radiographical controller = none remove signal bus EZX23; if in combination with 00XK + 00X6 load tube file again
all VTB VTC C	07LK	W	Amplimat chamber number out of range		
all VTB VTC C	07LL	W	Amplimat field number out of range		
all VTB VTC C	07LM	W	Amplimat delay value out of range		
all VTB VTC C	07LN	E		check if there is a short circuit to ground at EZX1:10-EWGX2:10-EWGX3:10	short circuit at door contact signal detected during start-up, release 2 generators only
	08CA	E	CAN: case-selector error		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
	08CB	W	CAN: invalid CAN ID %u		
	08CC	E	CAN: frame repeat overflow IIM%u		
	08CD	E	CAN: no retry from CU		
	08CE	E	CAN: rx signal conflict IIM%u		
	08CF	E	CAN: tx timeout		
	08CI	W	CAN: IMPOSSIBLE ERROR		
	08CP	W	CAN: CPU: Pxerr %d %s(%d)		
	08CR	W	CAN: CPU: message request fail		
	08CS	W	CAN: CPU: message send error		
	08CY	E	CAN: rx abort IIM%u		
	08CZ	W	CAN: unexpected frame (IIM%u)		
	08DA	E	CA: chip access error		
	08DB	E	CAN: chip reset error		
	08DC	E	CAN: chip reset release error		
	08DE	W	CAN: illegal interrupt pointer		
	08DF	E	CAN: chip state undefined		
	08DG	W	CAN: chip err act. after pass.		
	08DH	W	CAN: chip state error passive		
	08DI	W	CAN: chip state bus-off		
	08DJ	E	CAN: chip DPRAM error		
	08DK	W	CAN: chip DPRAM error&passive		
	08DL	W	CAN: unexpected interrupt		
	08HA	E	no message receive displaytask		
	08HB	E	no message release displaytask		
	08HC	E	APR not found		
	08HD	E	offset in menu structure out of range		
	08HF	E	no message request for test task		
	08HG	E	no message send for test task		
	08HH	E	APR buffer full		
	08HI	E	no message send for ODD task		
	08HJ	E	no send message to CU from ODD no message send for service task		
	08HK	E	data error in CAN message		
	08IE	E	wrong setup IIM		
	08SA	E	no request domtxtask when scanning		
	08SB	E	no request domtxtsak when testing		
	08SC	E	no send message to task2_sc		
all VTB VTC C	10CA 2193 56765 6156765	E	CAN: case-selector error <i>internal software failure perhaps caused by defective hardware</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	10CB 2194 56766	W	CAN: invalid CAN ID %u <i>CU sent IIM which the FU didn't know; possibly inconsistency between FU or CU version (release/level); has a wrong version just been installed?</i>		
all VTB VTC C	10CC 2195 56767 6156767	E	CAN: frame rep. overflow IIM%u <i>communication with CU disturbed, possibly CU overloaded</i>		
all VTB VTC C	10CD 2196 56768 6156768	E	CAN: no RTR from CU <i>transmission to CU disturbed</i>		
all VTB VTC C	10CE 2197 56769 6156769	E	CAN: rx signal conflict IIM%u <i>reception from CU disturbed</i>		
all VTB VTC C	10CF 2198 56770 6156770	E	CAN: tx timeout <i>transmission to CU disturbed</i>		
all VTB VTC C	10CI 2201 56773	W	CAN: IMPOSSIBLE ERROR <i>internal software failure, perhaps caused by defective hardware</i>		
all VTB VTC C	10CP 2208 56780	W	CAN: CPU: PXerr %d %s(%d) <i>error message of the operating system, perhaps caused by defective hardware</i>		
all VTB VTC C	10CR 2210 56782	W	CAN: CPU: message request fail <i>problem during reception from CU</i>		
all VTB VTC C	10CS 2211 56783	W	CAN: CPU: message send error <i>transmission to CU disturbed</i>		
all VTB VTC C	10CY 2217 56789 6156789	E	CAN: rx abort IIM%u <i>reception from CU disturbed</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	10CZ 2218 56790	W	CAN: unexpected frame (IIM%u) <i>reception from CU disturbed, message is delivered nevertheless</i>		
all VTB VTC C	10DA 2257 56865 6156865	E	CAN: chip access error <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	10DB 2258 56866 6156866	E	CAN: chip reset error <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	10DC 2259 56867 6156867	E	CAN: chip reset release error <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	10DE 2261 56869	W	CAN: illegal interrupt pointer <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	10DF 2262 56870 6156870	E	CAN: chip state undefined <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	10DG 2263 56871	W	CAN: chip err act. after pass. <i>info: 10DH ended</i>		
all VTB VTC C	10DH 2264 56872	W	CAN: chip state error passive <i>FU CAN chip error because of detected transmission problems; it's just an info, the transmission is still working; possibly to running FU connected to the CAN bus or EMC problems</i>		
all VTB VTC C	10DI 2265 56873	W	CAN: chip state bus-off <i>FU CAN chip serious error because of detected transmission (probably EMC) problems; no transmission possible until next start-up</i>		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	10DJ 2266 56874 6156874	E	CAN: chip DPRAM Error <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	10DK 2267 56875	W	CAN: chip DPRAM Error&passive <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	10DL 2268 56876	W	CAN: unexpected interrupt <i>problem with CAN chip on the function unit</i>		
all VTB VTC C	10FB 2386 57066 6157066		short circuit detected motor phase short circuit for more than 300ms		
all VTB VTC C	10FT 2404 57084 6157084		over current detected motor phase short circuit for less than 300ms		
all VTB VTC C	10IF 2582 57370	W	initialization failed software start-up not ok		
all VTB VTC C	10LA 2769 57665 6157665	W	acceleration count limit exceeded	bouncing hand switch? check behavior at EN_X/ EZX82	If more than 4 PREP's have been switched within one minute the 5th will cause this entry not allowing the next acceleration to prevent overheating of the stator. If in combination with 00XT (RoCo high speed only) program "enable" at "rotation prolongation after prep".
all VTB VTC C	10LC	W	current limit exceeded		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	10LH 2776 57672 6157672	E/W	intermediate current too high FU_RC 4512 104 71401...6 firmware 4512 113 22311/12 stator phase current too high FU_RC 4512 104 7142x or 4512 104 7146x firmware 4512 113 22322/3 <i>stator phase current too high</i>	check system with ..\data_collection\rotor_control\repl_high_speed_r oco.pdf FU_RC 4512 104 7142x/6x: compare stator currents for SRO tubes 9000rpm with ..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_1.pcx ..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_2.pcx ..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_3.pcx ..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_4.pcx ..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_5.pcx ..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_6.pcx or for RO tubes 3000rpm ..\data_collection\oscilloscope\RoCo_high- speed\ro_acc1.pcx ..\data_collection\oscilloscope\RoCo_high- speed\ro_acc2.pcx ..\data_collection\oscilloscope\RoCo_high- speed\ro_bra1.pcx ..\data_collection\oscilloscope\RoCo_high- speed\ro_bra2.pcx ..\data_collection\oscilloscope\RoCo_high- speed\ro_star1.pcx ..\data_collection\oscilloscope\RoCo_high- speed\ro_start.pcx	

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	10LL 2780 57676 6157676	E/W	<p>intermediate current too low FU_RC 4512 104 71401...6 firmware 4512 113 22311/12</p> <p>stator phase current too low FU_RC 4512 104 7142x or 4512 104 7146x firmware 4512 113 22322/3</p> <p>firmware 4512 113 22322/3 must not be used in units 4512 104 71401...406 with control PCBs 4512 108 08702/3 firmware details see ..\data_collection\firmware\FU_FIRM.pdf</p> <p><i>stator phase current too low</i></p>	<p>check system with <a href="..\data_collection\rotor_control\repl_high_speed_r
oco.pdf">..\data_collection\rotor_control\repl_high_speed_r oco.pdf</p> <p>FU_RC 4512 104 7142x/7146x/7410x/736xx compare stator currents for SRO tubes 9000rpm with <a href="..\data_collection\oscilloscope\RoCo_high-
speed\rdrchs_1.pcx">..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_1.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\rdrchs_2.pcx">..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_2.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\rdrchs_3.pcx">..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_3.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\rdrchs_4.pcx">..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_4.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\rdrchs_5.pcx">..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_5.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\rdrchs_6.pcx">..\data_collection\oscilloscope\RoCo_high- speed\rdrchs_6.pcx or for RO tubes 3000rpm <a href="..\data_collection\oscilloscope\RoCo_high-
speed\ro_acc1.pcx">..\data_collection\oscilloscope\RoCo_high- speed\ro_acc1.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\ro_acc2.pcx">..\data_collection\oscilloscope\RoCo_high- speed\ro_acc2.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\ro_bra1.pcx">..\data_collection\oscilloscope\RoCo_high- speed\ro_bra1.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\ro_bra2.pcx">..\data_collection\oscilloscope\RoCo_high- speed\ro_bra2.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\ro_star1.pcx">..\data_collection\oscilloscope\RoCo_high- speed\ro_star1.pcx <a href="..\data_collection\oscilloscope\RoCo_high-
speed\ro_start.pcx">..\data_collection\oscilloscope\RoCo_high- speed\ro_start.pcx</p> <p>if WG unit for 2nd or 3rd tube present: stator relay energized ?</p> <p>stator phase cables U-V-W interchanged ?</p> <p>+/- 15V supply present?</p>	

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	10LO 2783 57679 6157679	E W/E	intermediate voltage %u V (>%u) <i>should this error occur before anode acceleration then it is reported as an error, otherwise it is reported as a warning in order that the CU does not terminate the exposure</i>		
all VTB VTC C	10LT 2788 57684 6157684	E	temperature limit exceeded, heat sink temperature too high	check lines to NTC if short; NTC should have 15kohms at 20°C measure 5VDC across Y100X4:1-3 when open, about 4.425V when connected and ok	
all VTB VTC C	10LU 2789 57685 6157685	E W/E	intermediate voltage %u V (<%u) <i>should this error occur before anode acceleration then it is reported as an error, otherwise it is reported as a warning in order that the CU does not terminate the exposure</i>	measure DC supply voltage at EY100 X43 / X44 RoCo units 4512 104 7142x and 4512 104 7146x ENF3 switched on ? measure resistors between the big blue capacitors: R4/R7 = 210kohms R5/R6 = 90kohms	if resistors defective cut just the resistor body and solder the new resistor at the remaining wires
all VTB VTC C	10LZ 2794 57690 6157690	E	heat sink temperature sensor failure temperature too low	check line crimped to NTC if open; NTC should have 15kohms at 20°C measure 5VDC across Y100X4:1-3 when open, about 4.425V when connected and ok	
all VTB VTC C	10OE 2965 57969	W	CPU: PXROS error %d		
all VTB VTC C	10OF 2966 57970	W	CPU: PXROS error %d %s(%d)		
all VTB VTC C	10RC 3155 58267 6158267	E	rotation check failed		
all VTB VTC C	10RI 3161 58273 6158273	E	invalid rotation request : %u		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	10RM	E	rotation detector not present		
all VTB VTC C	10RT 3172 58284 6158284	W	rotation request timeout		= during adaptation if in installation with BuckyTH system BuCo release 5.x which does not allow an exposure repetition, change settings free cassette RGDV syncmaster present = no Mounted radiographical controller = none remove signal bus EZX23
all VTB VTC C	10SA 3217 58365	W	over-current in stator line detected	check system with ..\data_collection\rotor_control\repl_high_speed_r oco.pdf	
all VTB VTC C	10SC 3219 58367	E	short circuit in stator line detected	check system with ..\data_collection\rotor_control\repl_high_speed_r oco.pdf	
all VTB VTC C	10SF 3222 58370	W	heat sink temperature out of range temperature too low	check line crimped to NTC if open; NTC should have 15kohms at 20°C measure 5VDC across Y100X4:1-3 when open, about 4.425V when connected and ok	
all VTB VTC C	10TD 3284 58468 6158468	E	invalid data for tube %u =1= appears most likely after exchange of high speed rotor control unit to version 4512 104 7142x/46x which requires the new data for the RC firmware only at release 3.x generators, tube file TUBE_R3 (use version file date 18.4.2001) = appears with a non-programmed CU after the very first turn-on, =2= when appearing after CU Complete restore the data file might be defective <i>invalid data for tube %u</i>		=1= only at release 3.x generators: after exchange of FU_RC load tube data with file TUBE_R3.TDL (use version file date 18.4.2001) and re-adapt, download CU Complete afterwards =2= dump CU Complete file which won't work, download CU Complete again, see ..\data_collection\info_files\PC-up-download-settings.pdf erase NV-RAM (see ..\data_collection\info_files\Memory quick erase_Optimus RAD RF C.pdf and start programming from scratch
all VTB VTC C	10TE 3285 58469 6158469	W	stator %u hardware error		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
all VTB VTC C	10TF 3286 58470 6158470	E	stator %u switching failed		
all VTB VTC C	10TI 3289 58473 6158473	E	invalid stator request : %u feedback signal problem	check signals depending on the tube # selection at TB_2_RT/ EZ130 X1:A10 TB_3_RT/ EZ130 X1:C10 generated at tube extension unit WG / 1WG / 2WG	
all VTB VTC C	10TR 3298 58482 6158482	E	stator change with rotating anode		
all VTB VTC C	10UI 3353 58573	W	unknown message from CU : IIM %u		
all VTB VTC C	10UM 3357 58577	W	unexpected message from CU : IIM %u		
all VTB VTC C	10WT 3492 58784	W	CPU: watchdog timeout		
all VTB VTC C	10XX 3560 58888	W	IMPOSSIBLE ERROR		
	13CA	E	CAN: case-selector error		
	13CB	W	CAN: invalid CAN ID %u		
	13CC	E	CAN: frame repeat overflow IIM%u		
	13CD	E	CAN: no retry from CU		
	13CE	E	CAN: rx signal conflict IIM%u		
	13CF	E	CAN: tx timeout		
	13CI	W	CAN: IMPOSSIBLE ERROR		
	13CP	W	CAN: CPU: Pxerr %d %s(%d)		
	13CR	W	CAN: CPU: message request fail		
	13CS	W	CAN: CPU: message send error		
	13CY	E	CAN: rx abort IIM%u		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
	13CZ	W	CAN: unexpected frame (IIM%u)		
	13DA	E	CA: chip access error		
	13DB	E	CAN: chip reset error		
	13DC	E	CAN: chip reset release error		
	13DE	W	CAN: illegal interrupt pointer		
	13DF	E	CAN: chip state undefined		
	13DG	W	CAN: chip err act. after pass.		
	13DH	W	CAN: chip state error passive		
	13DI	W	CAN: chip state bus-off		
	13DJ	E	CAN: chip DPRAM error		
	13DK	W	CAN: chip DPRAM error&passive		
	13DL	W	CAN: unexpected interrupt		
	13LA	W	CV received IIM unknown		
	13LB	W	IO wrong bi-directional lines output value		
	13LC	W	TR TOMO value out of range		
	13LD	W	TR RGDV value out of range		
	13LE	E	TR RGDV read back failed	relay contact stuck on-board of WA102, in combination with 00X6 possible	
	13LF	W	TR wrong sync contact value		
	13LG	W	TR wrong hand switch enable value		
	13LH	E	PR S1/S2 switch active during startup		
	14CA	E	CAN: case-selector error		
	14CB	W	CAN: invalid CAN ID %u		
	14CC	E	CAN: frame repeat overflow IIM%u		
	14CD	E	CAN: no retry from CU		
	14CE	E	CAN: rx signal conflict IIM%u		
	14CF	E	CAN: tx timeout		
	14CI	W	CAN: IMPOSSIBLE ERROR		
	14CP	W	CAN: CPU: Pxerr %d %s(%d)		
	14CR	W	CAN: CPU: message request fail		
	14CS	W	CAN: CPU: message send error		
	14CY	E	CAN: rx abort IIM%u		
	14CZ	W	CAN: unexpected frame (IIM%u)		
	14DA	E	CA: chip access error		
	14DB	E	CAN: chip reset error		
	14DC	E	CAN: chip reset release error		
	14DE	W	CAN: illegal interrupt pointer		
	14DF	E	CAN: chip state undefined		
	14DG	W	CAN: chip err act. after pass.		
	14DH	W	CAN: chip state error passive		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
	14DI	W	CAN: chip state bus-off		
	14DJ	E	CAN: chip DPRAM error		
	14DK	W	CAN: chip DPRAM error&passive		
	14DL	W	CAN: unexpected interrupt		
	14LA	W	CV received IIM unknown		
	14LB	W	IO wrong bi-directional lines output value		
	14LC	W	TR TOMO value out of range		
	14LD	W	TR RGDV value out of range		
	14LE	E	TR RGDV read back failed		
	14LF	W	TR wrong sync contact value		
	14LG	W	TR wrong hand switch enable value		
	14LH	E	PR S1/S2 switch active during startup		
	15CA	E	CAN: case-selector error		
	15CB	W	CAN: invalid CAN ID %u		
	15CC	E	CAN: frame repeat overflow IIM%u		
	15CD	E	CAN: no retry from CU		
	15CE	E	CAN: rx signal conflict IIM%u		
	15CF	E	CAN: tx timeout		
	15CI	W	CAN: IMPOSSIBLE ERROR		
	15CP	W	CAN: CPU: Pxerr %d %s(%d)		
	15CR	W	CAN: CPU: message request fail		
	15CS	W	CAN: CPU: message send error		
	15CY	E	CAN: rx abort IIM%u		
	15CZ	W	CAN: unexpected frame (IIM%u)		
	15DA	E	CA: chip access error		
	15DB	E	CAN: chip reset error		
	15DC	E	CAN: chip reset release error		
	15DE	W	CAN: illegal interrupt pointer		
	15DF	E	CAN: chip state undefined		
	15DG	W	CAN: chip err act. after pass.		
	15DH	W	CAN: chip state error passive		
	15DI	W	CAN: chip state bus-off		
	15DJ	E	CAN: chip DPRAM error		
	15DK	W	CAN: chip DPRAM error&passive		
	15DL	W	CAN: unexpected interrupt		
	15LA	W	CV received IIM unknown		
	15LB	W	IO wrong bi-directional lines output value		
	15LC	W	TR TOMO value out of range		
	15LD	W	TR RGDV value out of range		
	15LE	E	TR RGDV read back failed		

Error Code detailed explanations Optimus RAD R/F C and Velara (all versions)

Gen.	error	class	explanation	test procedures	fixing suggestions
	15LF	W	TR wrong sync contact value		
	15LG	W	TR wrong hand switch enable value		
	15LH	E	PR S1/S2 switch active during startup		