

6.6 Diagnostic codes

When a fault occurs, the software, records a six-digit alphanumeric diagnostic code in the System Diagnostic Log, if possible.

Diagnostic codes for some of the POST kernel test faults cannot be displayed by the GUI and are reported only by the diagnostic LED array on the applicable CPU PCB. The system is unable to record these particular faults in the System Diagnostic Log.

6.6.1 How to interpret diagnostic codes

The first letter of a diagnostic code in the System Diagnostic Log identifies the module (BD or GUI) where the fault was detected and whether it was minor or major. First letters in a diagnostic code of L and K denote BD CPU minor and major faults, respectively, while the letters Z and X denote GUI CPU minor and major faults.

The second letter in the six-digit code indicates where the fault occurred in the software. The last four diagnostic code characters can provide additional error code information.

XXXS below outlines the possible values of certain digits in the alphanumeric diagnostic code and provides top-level interpretations.




Table 6-1: Values of diagnostic code digits

| where: | may be... | which means... |
|----------|-----------|---|
| a | A | Alert (during SST/EST) |
| | D or H | BDU problem that resulted in soft reset during operation (as opposed to during POST) |
| | E | BDU user event (not an error) |
| | F | Failure (during SST/EST) |
| | G | BDU illegal instruction trap, watchdog reset, or illegal address trap that resulted in BDU soft reset |
| | J | BDU watchdog umpire (3 "strikes" in 24 hours) caused Safety Valve Open (SVO) |
| | K | BDU failure (during POST or background check) caused SVO |
| | L | POST or background check alert or communication error in BDU |
| | S | GUI user event |
| | U or V | GUI problem that resulted in soft reset during operation |
| | X | GUI failure (during POST or background check) caused GUI or ventilator inoperative condition |
| | Z | POST or background check alert or communication error in GUI |

Table 6-1: Values of diagnostic code digits

| where: | may be... | which means... |
|-------------|-----------|--|
| b | B | Background check |
| | C | Communications test |
| | E | EST |
| | N | Nonmaskable interrupt |
| | P | POST or initialization software |
| | S | SST |
| | T | Hardware-detected failure (trap) |
| | Y | GUI watchdog umpire (3 "strikes" in 24 hours) causes GUI inoperative condition |
| cccc | (None) | Soft fault (assertion) |
| | (Varies) | Other error identification information |

6.7 Organization of diagnostic codes table

Table 6-2 is a comprehensive summary of the diagnostic codes that the 840 software can report. The organization of the information in this table is as follows:

- The first column lists, in alphanumeric order, the codes.
- The second column lists the accompanying message.
- The third column lists the part of software that was running when the error was detected.
- The fourth column lists the ventilator's response to the condition, as follows:

| | |
|------------------|---|
| ALERT | <p>Test result not ideal, but not critical.</p> <p>In POST: POST continues to end and ventilation starts. A DEVICE ALERT alarm is annunciated (Section 7).</p> <p>In SST/EST: SST/EST continues to end. You can override the alert and start ventilation.</p> <p>In a background check: Ventilation continues, and a DEVICE ALERT alarm is annunciated.</p> |
| FAILURE | <p>Critical problem detected.</p> <p>In POST: Ventilator inoperative condition is declared.</p> <p>In SST/EST: You can continue trying to pass SST or EST, but if test does not pass, ventilator inoperative condition is declared. In a background check: Ventilator inoperative condition is declared.</p> |
| BDU RESET | <p>Circuitry in the BDU is reset, which causes BDU POST to be rerun. If POST passes, ventilation continues. If POST fails, it generates an alert or failure.</p> |
| GUI RESET | <p>Circuitry in the GUI is reset, which causes GUI POST to be rerun. If POST passes, GUI operation resumes. If GUI POST does not pass, it declares a GUI inop condition.</p> |
| VENT INOP | <p>Ventilator is put into SVO state, permitting patient to breathe room air.</p> |

| | |
|-----------------|---|
| ALERT | <p>Test result not ideal, but not critical.</p> <p>In POST: POST continues to end and ventilation starts. A DEVICE ALERT alarm is annunciated (Section 7).</p> <p>In SST/EST: SST/EST continues to end. You can override the alert and start ventilation.</p> <p>In a background check: Ventilation continues, and a DEVICE ALERT alarm is annunciated.</p> |
| FAILURE | <p>Critical problem detected.</p> <p>In POST: Ventilator inoperative condition is declared.</p> <p>In SST/EST: You can continue trying to pass SST or EST, but if test does not pass, ventilator inoperative condition is declared. In a background check: Ventilator inoperative condition is declared.</p> |
| GUI INOP | <p>The BDU alarms, ventilator settings are locked, and a message is displayed.</p> |
| STATUS | <p>Code/message listed for information only; requires no action.</p> |

- The fifth column provides additional information and/or identifies possible causes.
- The sixth column suggests how to correct the condition. These actions are sequenced to correct the most probable malfunction or to present the most efficient corrective action first. The proposed fixes listed, however, may not always correct the particular problem.

In addition to the actions suggested in the tables in this section, keep the following in mind when troubleshooting the ventilator:

- Verify secure connections of cables and ventilator modules.
- If possible, run full EST, bypassing any failures or faults that may occur, to further diagnose a problem.
- Replace BD or GUI CPU PCB only after all other remedies have been attempted. Contact Puritan-Bennett Technical Support for further assistance.
- Check for system leaks, particularly at the expiratory filter. Make sure the expiratory filter collector vial is secured tightly, the drain port is capped, and the filter is mounted securely to the ventilator. Make sure the test circuit is securely attached.
- Before running SST or EST, ensure that the unit has been warmed up for at least 10 minutes in ambient temperature. Failure to warm up the ventilator may result in false flow sensor or pressure transducer failures.

When troubleshooting SST or EST, always use a known good patient circuit or gold standard circuit and filter(s).

Table 6-2: 840 Ventilator diagnostic codes

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---|-----------------------------------|----------|--|---|
| AE0110 | Unable to establish O ₂ flow | EST Flow sensors cross check Test | Alert | Flow controller unable to establish and control oxygen flow at 120 L/min. | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected and unrestricted. 2. Verify oxygen regulator pressure is set between 9-12 psi. 3. Switch PSOLs to see if failure transfers to the other gas side. If yes, return the air PSOL to its original position and replace the oxygen PSOL. 4. Run the leak test in EST to check for leaks/occlusions. 5. Perform a flow sensor calibration. 6. Replace Q1. 7. Replace the Inspiratory Electronics PCB. 8. Replace the AI PCB. |
| AE0111 | Unable to establish air flow | EST Flow sensors cross check Test | Alert | Flow controller unable to establish and control air flow at 120 L/min. | <ol style="list-style-type: none"> 1. Make sure air supply is connected and unrestricted. 2. Verify air regulator pressure is set between 9-12 psi. 3. Switch PSOL's to see if failure transfers to the other gas side. If yes, return Oxygen PSOL to its original position and replace the Air PSOL. 4. Run the leak test in EST to check for leaks/occlusions. 5. Perform a flow sensor calibration. 6. Replace Q2. 7. Replace the Inspiratory Electronics PCB. 8. Replace the AI PCB. |
| AE0213 | Air PSOL leak | EST Gas Supply/SV Test | Alert | Air PSOL (PSOL2) forward leak was detected via excessive pressure buildup (> 50 cmH ₂ O but < 100 cmH ₂ O) in blocked inspiratory module. | <ol style="list-style-type: none"> 1. Check for leaks around the Q2 O-rings. 2. Make sure air supply is connected and unrestricted. 3. Reseat Air PSOL. 4. Replace Air PSOL. 5. Replace AI PCB. |
| AE0214 | O ₂ PSOL leak | EST Gas Supply/SV Test | Alert | Oxygen PSOL (PSOL1) forward leak was detected via excessive pressure buildup (> 50 cmH ₂ O but < 100 cmH ₂ O) in blocked inspiratory module. | <ol style="list-style-type: none"> 1. Check for leaks around the Q1 O-rings. 2. Make sure oxygen supply is connected and unrestricted. 3. Reseat oxygen PSOL. 4. Replace oxygen PSOL. 5. Replace AI PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|-------------------------------------|-------------------|----------|---|---|
| AE0306 | Test circuit not connected | EST Leak Test | Alert | Pressure not detected on expiratory side | <ol style="list-style-type: none"> 1. Make sure test circuit is properly connected. 2. Replace expiratory bacteria filter. 3. Check for leaks around the Q3 flow sensor. 4. Check/replace the exhalation valve. 5. Replace the expiratory pressure transducer PCB. |
| AE0601 | GUI High Alarm LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0602 | GUI Medium Alarm LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0603 | GUI Low Alarm LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0604 | GUI Normal LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0605 | GUI Batt Backup LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0606 | GUI On Batt Pwr LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0607 | GUI Compressor Ready LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0608 | GUI Compressor Operating LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0609 | GUI 100% O ₂ LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace keyboard. |
| AE0610 | GUI Alarm Silence LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | <ol style="list-style-type: none"> 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--|------------------------|----------|---|--|
| AE0611 | GUI Screen Lock LED fails. | EST GUI Lamp Test | Alert | CLEAR key pressed to indicate LED not on. | 1. Check/replace interconnect cable between the GUI LED PCB and the GUI CPU PCB. 2. Replace the GUI LED PCB. |
| AE0702 | Bad Vent inop LED | EST BD Lamp Test | Alert | CLEAR key pressed to indicate one or both ventilator inoperative LEDs not on. | Replace BD LED PCB. |
| AE0703 | Bad SVO LED | EST BD Lamp Test | Alert | CLEAR key pressed to indicate one or both SVO LEDs not on. | Replace BDU LED PCB. |
| AE0704 | Bad Loss of GUI LED | EST BD Lamp Test | Alert | CLEAR key pressed to indicate loss of GUI LED not on. | Replace BDU LED PCB. |
| AE1001 | Air PSOL loopback current OOR | EST PSOL Loopback Test | Alert | Air PSOL (PSOL2) loopback current out of range of drive current. | 1. Verify that the air supply is good. 2. Verify air regulator pressure set to between 9 and 12 psi. 3. Switch PSOLs to see if failure transfers to the other gas side. If yes, return oxygen PSOL (PSOL1) to its original position and replace PSOL2. 4. Switch Q1 and Q2, run a flow sensor calibration and rerun test. If the problem transfers to the other gas side, return Q1 to its original position and replace Q2. 5. Replace the AI PCB. 6. Replace the Inspiratory Electronics PCB. |
| AE1002 | O ₂ PSOL loopback current OOR | EST PSOL Loopback Test | Alert | Oxygen PSOL (PSOL1) loopback current out of range of drive current. | 1. Verify that the oxygen supply is good. 2. Verify oxygen regulator pressure set to between 9 and 12 psi. 3. Switch PSOLs to see if failure transfers to the other gas side. If yes, return the air PSOL to its original position and replace PSOL1. 4. Switch Q1 and Q2, run a flow sensor calibration and rerun test. If the problem transfers to the other gas side, return Q2 to its original position and replace Q1. 5. Replace the AI PCB. 6. Replace the Inspiratory Electronics PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|----------------------------------|-----------------------------|----------|---|---|
| AE1104 | Insp check valve test failed | EST Safety System Test | Alert | It took too little time to relieve excess pressure through open safety valve, indicating inspiratory check valve (CV3) may be damaged or incorrectly mounted. | <ol style="list-style-type: none"> 1. Make sure test circuit is connected. 2. Make sure CV3 is not installed backward. 3. Replace CV3. |
| AE1201 | Exp valve loopback current OOR | EST Exp Valve Loopback Test | Alert | Exhalation valve loopback current is out of range of drive current. | <ol style="list-style-type: none"> 1. Verify that the system has no leaks or occlusions by running the leak test in EST. 2. Clean exhalation valve diaphragm. 3. Calibrate the exhalation valve. 4. Clean/replace the exhalation valve. 5. Replace the AI PCB. |
| AE1305 | Seal test failed | EST Exp Valve Seal Test | Alert | Seal test Δ pressure is above alert level but below failure level. | <ol style="list-style-type: none"> 1. Verify that the system has no leaks or occlusions by running the leak test in EST. 2. Clean the exhalation valve. 3. Calibrate exhalation valve. 4. Replace the exhalation valve. 5. Replace the AI PCB. |
| AE1600 | Compressor Test - Not installed | EST Compressor Test | Status | Ventilator did not sense a compressor attached and skipped test. | No action required. |
| AE1601 | Wall air pressure detected | EST Compressor Test | Alert | Wall air pressure switch (PS2) detected air after user was prompted to disconnect air. | <ol style="list-style-type: none"> 1. Make sure air supply is disconnected. 2. Disconnect PS2 and rerun test. If test passes, replace PS2. |
| AE1602 | ac power not connected | EST Compressor Test | Alert | System is still running on battery power after prompting user to connect ac power. Compressor can only run on ac (facility) power. | <ol style="list-style-type: none"> 1. Plug in ventilator power cord and check the cord connection at the ventilator. 2. Check ac. 3. Disconnect BPS to isolate problem. 4. Replace power supply. |
| AE1603 | Compressor pressure not detected | EST Compressor Test | Alert | Compressor pressure transducer (PC) indicates that compressor air is not present, although compressor motor is on. | <ol style="list-style-type: none"> 1. Run compressor leak test to check for leaks. <ol style="list-style-type: none"> a. Use leak detector to check for leaks at the accumulator fittings and other tubing connections. b. Verify no leaks at CV2 within the ventilator by plugging the air inlet fitting. 2. Replace compressor PCB. 3. Contact Puritan-Bennett Technical Support. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--|--------------------------|----------|---|--|
| AE1604 | Run mode time OOR | EST Compressor Test | Alert | Compressor timer is not running while compressor motor is on. | Listen for motor. If motor is on, replace compressor PCB. Otherwise, replace compressor. |
| AE1606 | Compressor pressure detected | EST Compressor Test | Alert | Compressor pressure transducer (PC) indicates that compressor air is present after compressor motor is disabled and accumulator drained. | Replace compressor PCB. |
| AE1607 | Disabled mode time OOR | EST Compressor Test | Alert | Compressor timer is running while compressor motor is off. | Replace compressor PCB. |
| AE1608 | Unable to test standby mode | EST Compressor Test | Alert | Compressor standby mode check cannot be run, because of inability to verify timer functionality during compressor run and disabled tests. | 1. Troubleshoot code AE1604 or AE1607, if present. 2. Replace compressor PCB. |
| AE1609 | Standby mode time OOR | EST Compressor Test | Alert | Compressor motor is still running. During standby mode test phase, compressor motor should eventually turn off. | Replace compressor PCB. |
| AE1610 | Unable to perform compressor load test | EST Compressor Test | Alert | Compressor load test cannot be run, because of inability to verify PC during compressor run and disabled tests. | Troubleshoot code AE1603 or AE1606. |
| AE1611 | Compressor load test failed | EST Compressor Test | Alert | Compressor unable to maintain minimum pressure under worst-case breath delivery waveform. | 1. Run compressor leak test to check for compressor leak. a. Use leak detector to check for leaks at the accumulator fittings and other tubing connections. b. Verify no leaks at CV2 within the ventilator by plugging the air inlet fitting. 2. Replace compressor. 3. Replace compressor PCB. |
| AE1700 | Compressor Leak Test - Not installed | EST Compressor Leak Test | Status | Ventilator did not sense a compressor attached and skipped test. | No action required. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--|--------------------------|----------|---|--|
| AE1701 | Unable to perform compressor leak test | EST Compressor Leak Test | Alert | Compressor leak test cannot be run, because of inability to verify timer functionality. | 1. Troubleshoot accompanying code AE1604 or AE1607. 2. Replace compressor PCB. |
| AE1702 | Wall air pressure detected | EST Compressor Leak Test | Alert | Wall air pressure switch (PS2) detected air presence after user was prompted to disconnect air. | 1. Make sure air supply is disconnected. 2. Disconnect PS2 and rerun test. If test passes, replace PS2. |
| AE1703 | Wall air pressure not detected | EST Compressor Leak Test | Alert | Wall air pressure switch (PS2) did not detect air presence after user was prompted to connect air. | 1. Make sure air supply is connected. 2. Run Gas Supply/SV Test. |
| AE1704 | Compressor leak detected | EST Compressor Leak Test | Alert | Compressor leak was detected using compressor timer to detect compressor turning on momentarily during test. | Troubleshoot compressor compartment or inspiratory module for leaks. |
| AE1901 | GUI touch: Error | EST GUI Touch Test | Alert | Touch screen error occurred (e.g., blocked beam or low-level error), buffer cannot be read, or report is invalid. | 1. Clean touch screen, removing any obstructions. 2. Replace touch frame PCB. 3. Replace GUI CPU PCB. |
| AE2001 | Bad GUI serial port | EST GUI Serial Port Test | Alert | While in loopback mode, failed to verify received message was identical to transmitted message. | Replace GUI CPU PCB. |
| AE2101 | Battery not charged | EST Battery Test | Alert | BPS not fully charged at start of test. | 1. Allow BPS to fully charge, then repeat test. 2. Replace BPS PCB. 3. Replace battery pack. 4. Replace BD CPU PCB. |
| AE2102 | Battery not discharging | EST Battery Test | Alert | BPS not discharging after ac power was disconnected. | 1. Verify ac power is disconnected when prompted. 2. Replace BPS PCB. 3. Replace battery pack. 4. Replace BD CPU PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|-------------------------------------|------------------|----------|---|--|
| AE2103 | Bad Backup Power Supply | EST Battery Test | Alert | While BPS was discharging, BPS voltage dropped below accepted level or dropped too quickly. | <ol style="list-style-type: none"> 1. Ensure that the battery pack is fully charged by checking that the green LED on the BPS is lit prior to initiating an EST. If the amber LED is lit, allow the unit to charge the batteries prior to rerunning EST. 2. Replace the battery pack. 3. Replace the BPS PCB. 4. Replace the AI PCB. 5. Replace the power supply. |
| AE2104 | Battery not charging | EST Battery Test | Alert | BPS not charging after ac power was reconnected. | <ol style="list-style-type: none"> 1. Verify that ac power is reconnected when prompted and that ac is good. 2. Replace BPS PCB. 3. Replace the battery pack. 4. Replace the power supply. 5. Replace the BD CPU. 6. Replace the AI PCB. |
| AE2300 | GUI Nurse Call Test - Not installed | EST Test | Status | User pressed CLEAR to indicate nurse's call device not installed. Test was skipped. | No action required. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---|----------------------|----------|---|--|
| AS0010 | Unable to establish O ₂ flow | SST flow sensor test | Alert | Flow controller unable to establish and control oxygen flow at 120 L/min. | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected and unrestricted. 2. Verify that the oxygen supply meets minimum pressure requirements. 3. Verify that the patient circuit system has no leaks or occlusions. If not sure, run the first four tests in EST to get to the leak test. If the leak test passes in EST, exit out of EST. Correct the leak or occlusion in the patient circuit used in SST and rerun or try another patient circuit. 4. Check the oxygen inlet filter assembly. 5. Verify that the oxygen regulator pressure is set between 9-12 psi. 6. Run a flow sensor calibration. 7. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the air side, return Q2 back to its original position and replace Q1. 8. Switch PSOLs to see if the failure transfers to the air side. If yes, return PSOL2 back to its original position and replace PSOL1. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--------------------------------------|-----------------------|----------|--|--|
| AS0011 | Unable to establish air flow | SST flow sensor test | Alert | 1. Flow controller unable to establish and control air flow at 120 L/min. | <ol style="list-style-type: none"> 1. Make sure air supply is connected and unrestricted. 2. Verify that the air supply meets minimum pressure requirements. 3. Verify that the patient circuit system has no leaks or occlusions. If not sure, run the first four tests in EST to get to the leak test. If the leak test passes in EST, exit out of EST. Correct the leak or occlusion in the patient circuit used in SST and rerun or try another patient circuit. 4. Check the air inlet filter (F2). 5. Verify that the air regulator pressure is set between 9-12 psi. 6. Run a flow sensor calibration. 7. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the oxygen side, return Q1 back to its original position and replace Q2. 8. Switch PSOLs to see if the failure transfers to the oxygen side. If yes, return PSOL1 back to its original position and replace PSOL2. |
| AS0012 | O ₂ pressure not detected | SST flow sensor test | Alert | Oxygen pressure not detected via PS1. Only air available for SST. | Make sure oxygen supply is connected. |
| AS0013 | Wall air pressure not detected | SST flow sensor test | Alert | Air pressure not detected via PS2 or PC. Only oxygen available for SST. | Make sure air supply is connected. |
| AS0202 | Excessive leak | SST Circuit leak | Alert | Pressure drops to 85 cmH ₂ O in 10 s, then in 10 s more by ≥ 10 cmH ₂ O. | <ol style="list-style-type: none"> 1. Make sure patient circuit is connected and is not leaking. 2. Check exhalation valve operation. 3. Verify connections of bacteria filters and humidifier are secure. |
| AS0305 | Occluded expiratory filter | SST Expiratory filter | Alert | Pressure drop across filter > 2 cmH ₂ O, but < 3 cmH ₂ O. | Consider replacing expiratory filter. |
| AS0308 | Occluded expiratory compartment | SST Expiratory filter | Alert | Exhalation compartment pressure > 3 cmH ₂ O but < 4 cmH ₂ O. | <ol style="list-style-type: none"> 1. Check compartment for obstruction. 2. Verify exhalation valve operation by running EST. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|----------------------------------|----------------------------|----------|--|--|
| AS0311 | Low expiratory filter ΔP | SST Expiratory filter | Alert | Pressure drop across expiratory filter < 0.4 cmH ₂ O, but > 0.1 cmH ₂ O. | 1. Repeat test, following directions more closely. 2. Replace filter. |
| AS0403 | Occluded inspiratory limb | SST Circuit Resistance | Alert | Inspiratory limb pressure > 8.5 cmH ₂ O (adult) or 5.5 cmH ₂ O (pediatric), but < 12.5 cmH ₂ O (adult) or 7.5 cmH ₂ O (pediatric), indicating occlusion. | Check for occluded patient tubing. |
| AS0406 | Occluded exhalation limb | SST Circuit Resistance | Alert | Expiratory limb pressure > 8.5 cmH ₂ O (adult) or 5.5 cmH ₂ O (pediatric) but > 12.5 cmH ₂ O (adult) or 7.5 cmH ₂ O (pediatric), indicating occlusion. | Check for occluded patient tubing. |
| AS0407 | Unable to reach min peak flow | SST Circuit Resistance | Alert | During characterization of total circuit resistance over a range of flows, peak flow < 80 L/min but > 60 L/min. | Check for kinked or occluded patient tubing. |
| AS0411 | Unable to reach min peak flow | SST Circuit Resistance | Alert | During characterization of total circuit resistance over a range of flows, peak flow was less than alert threshold. | Check for kinked or occluded patient tubing. |
| AS0413 | Insp limb resistance low | SST Circuit Resistance | Alert | Inspiratory limb pressure < 0.6 cmH ₂ O (adult) or 5.5 cmH ₂ O (pediatric), but > 0.2 cmH ₂ O. | 1. Make sure inspiratory filter is installed. 2. Repeat test, following directions more closely. 3. Replace inspiratory filter. 4. Replace patient circuit. |
| AS0414 | Exp limb resistance low | SST Circuit Resistance | Alert | Expiratory limb pressure < 0.6 cmH ₂ O (adult) or 0.5 cmH ₂ O (pediatric), but > 0.2 cmH ₂ O. | Replace patient circuit. |
| AS0505 | Excessive compliance | SST Compliance calibration | Alert | High compliance > 6 mL/cmH ₂ O (adult) or 4.5 mL/cmH ₂ O (pediatric), but < 12 mL/cmH ₂ O (adult) or 9 mL/cmH ₂ O (pediatric). | 1. Make sure correct patient tubing type was specified in SST. 2. Replace patient circuit. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--------------------------|----------------------------|---|---|---|
| AS0507 | Compliance low | SST Compliance calibration | Alert | High compliance falls below 1.56 mL/cmH ₂ O (adult) or 1.34 mL/cmH ₂ O (pediatric) but not lower than 1.05 mL/cmH ₂ O. | <ol style="list-style-type: none"> 1. Make sure correct patient tubing type was specified in SST. 2. Replace patient circuit with a known good circuit and filter set. 3. Run EST to check the operation of PI and PE during the Circuit Pressure Test. Replace applicable pressure transducer. 4. Run Atmospheric Pressure Transducer calibration. |
| AS0509 | Excessive compliance | SST Compliance calibration | Alert | Low compliance > 6 mL/cmH ₂ O (adult) or 4.5 mL/cmH ₂ O (pediatric), but < 12 mL/cmH ₂ O (adult) or 9 mL/cmH ₂ O (pediatric). | <ol style="list-style-type: none"> 1. Make sure correct patient tubing type was specified in SST. 2. Replace patient circuit with a known good circuit and filter set. 3. Run EST to check the operation of PI and PE during the Circuit Pressure Test. Replace applicable pressure transducer. 4. Run Atmospheric Pressure Transducer calibration. |
| AS0511 | Compliance low | SST Compliance calibration | Alert | Low compliance falls below 1.56 mL/cmH ₂ O (adult) or 1.34 mL/cmH ₂ O (pediatric), but not below 1.05 mL/cmH ₂ O. | <ol style="list-style-type: none"> 1. Make sure correct patient tubing type was specified in SST. 2. Replace patient circuit with a known good circuit and filter set. 3. Run EST to check the operation of PI and PE during the Circuit Pressure Test. Replace applicable pressure transducer. 4. Run Atmospheric Pressure Transducer calibration. |
| Dxxxxx | Assertion | Background Checks (BD) | Failure that results in a POST or a reset | System generated a reset to correct a boundary check or possible data corruption of control variables. | Replace the BDCPU PCB. |
| DT0002 | Bus error / Access fault | Background Checks (BD) | Failure that results in a POST or a reset | Hardware trap from an access fault due to a bad memory chip, bad control line, or a hardware timing issue. | Replace the BD CPU PCB. |
| Exxxxx | Varies | Background Checks (GUI) | Status | A status message indicating an event that was intentionally caused. | |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--|-----------------------------------|---------------------------|----------|---|--|
| NOTE: For all "FE" codes (failures reported during EST), diagnose the problem and perform the repair. Run a complete EST to reset the EST test failure in memory. If there is a failed EST test result in memory, normal operation is prevented until the failed EST test is rerun and passes. | | | | | |
| FE0001 | Inspiratory autozero out of range | EST Circuit Pressure Test | Failure | Inspiratory pressure transducer ADC count at 0 cmH ₂ O is out of range. | 1. Replace SOL1. 2. Replace Inspiratory Electronics PCB. 3. Replace AI PCB. |
| FE0002 | Expiratory autozero out of range | EST Circuit Pressure Test | Failure | Exhalation pressure sensor ADC count at 0 cmH ₂ O is out of range. | 1. Replace SOL2. 2. Replace exhalation transducer PCB. 3. Replace AI PCB. |
| FE0003 | Failed to reach test pressure | EST Circuit Pressure Test | Failure | Unable to build pressure (air) to 10 cmH ₂ O at 5 L/min within time-out period. | 1. Make sure that test circuit is installed and air supply or compressor is available and good. 2. Verify that the air regulator pressure is set between 9-12 psi. 3. Verify that the patient circuit system has no leaks or occlusions by running the first four tests in EST to get to the leak test. |
| FE0004 | Cross-check failed | EST Circuit Pressure Test | Failure | Inspiratory/expiratory pressure transducer readings at 10 cmH ₂ O test pressure are too far apart. | 1. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test 2. If the leak test passes in EST, exit out of EST. Review the data for the Circuit Pressure Test to determine which pressure transducer is out of range: PI or PE. Replace applicable pressure transducer. 3. Replace AI PCB. |
| FE0005 | Bad insp autozero solenoid | EST Circuit Pressure Test | Failure | Inspiratory pressure reading (taken after inspiratory pressure transducer autozero solenoid (SOL1) actuated) out of range (-0.60 to 0.60 cmH ₂ O). | 1. Replace SOL1. 2. Replace Inspiratory Electronics PCB. 3. Replace AI PCB. |
| FE0006 | Bad exp autozero sol | EST Circuit Pressure Test | Failure | Expiratory pressure reading (taken after expiratory pressure transducer autozero solenoid (SOL2) actuated) out of range (-0.60 to 0.60 cmH ₂ O). | 1. Replace SOL2. 2. Replace exhalation transducer PCB. 3. Replace AI PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---|-----------------------------------|----------|---|--|
| FE0007 | Cross-check failed | EST Circuit Pressure Test | Failure | Inspiratory/expiratory pressure transducer measurements at 50 or 100 cmH ₂ O test pressure are too far apart. | <ol style="list-style-type: none"> 1. Replace the expiratory bacteria filter. 2. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 3. If the leak test passes in EST, exit out of EST. Review the data for the Circuit Pressure Test to determine which pressure transducer is out of range: PI or PE. Replace applicable pressure transducer. 4. Replace AI PCB. |
| FE0008 | Failed to reach test pressure | EST Circuit Pressure Test | Failure | Unable to build pressure (air) to 50 or 100 cmH ₂ O at 5 L/min within time-out period. | <ol style="list-style-type: none"> 1. Make sure air supply or compressor is available. 2. Check for system leak at the expiratory bacteria filter or O₂ sensor. If not sure, run the first four tests in EST to run the leak test. |
| FE0010 | ac power not connected | EST Circuit Pressure Test | Failure | System is still running on battery power after prompting user to connect ac power. EST can only run on ac (facility) power. | <ol style="list-style-type: none"> 1. Plug in ventilator power cord. 2. Disconnect BPS to isolate problem. 3. Replace power supply. |
| FE0101 | O ₂ flow sensor cross check failed | EST Flow sensors cross check Test | Failure | Oxygen flow sensor (Q1) cross-check failed. | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected and unrestricted. 2. Verify that the oxygen supply is good. 3. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 4. Run a flow sensor calibration.6. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the air side, return Q2 back to its original position and replace Q1. 5. Switch PSOLs to see if the failure transfers to the air side. If yes, return PSOL2 back to its original position and replace PSOL1. 6. Replace exhalation flow sensor (Q3) 7. Replace AI PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--|-----------------------------------|----------|---|---|
| FE0102 | O ₂ PSOL current out of range | EST Flow sensors cross check Test | Failure | Oxygen PSOL (PSOL1) current is out of range with respect to flow sensor (Q1). | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected and unrestricted. 2. Verify that the oxygen supply is good. 3. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 4. Switch PSOLs to see if the failure transfers to the air side. If yes, return PSOL2 back to its original position and replace PSOL1. 5. Run a flow sensor calibration. 6. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the air side, return Q2 back to its original position and replace Q1. |
| FE0103 | Air flow sensor cross check failed | EST Flow sensors cross check Test | Failure | Inspiratory module air flow sensor (Q2) cross-check failed. | <ol style="list-style-type: none"> 1. Make sure air supply is connected and unrestricted. 2. Verify that the air supply is good. 3. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 4. Run a flow sensor calibration. 5. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the oxygen side, return Q1 back to its original position and replace Q2. 6. Switch PSOLs to see if the failure transfers to the air side. If yes, return PSOL back to its original position and replace PSOL2. 7. Replace exhalation flow sensor (Q3). 8. Replace AI PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---|-----------------------------------|----------|--|---|
| FE0104 | Air PSOL current out of range | EST Flow sensors cross check Test | Failure | Air PSOL (PSOL2) current is out of range with respect to air flow sensor (Q2). | <ol style="list-style-type: none"> 1. Make sure air supply is connected and unrestricted. 2. Verify that the air supply is good. 3. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 4. Switch PSOLs to see if the failure transfers to the air side. If yes, return PSOL back to its original position and replace PSOL2 5. Run a flow sensor calibration. 6. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the oxygen side, return Q1 back to its original position and replace Q2. |
| FE0106 | Unable to establish O ₂ flow | EST Flow sensors cross check Test | Failure | Flow controller unable to establish and control oxygen flow at 60, 5, and 1 L/min. | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected. 2. Check regulated oxygen pressure. 3. Replace PSOL1 or Q1. 4. Replace AI PCB. |
| FE0107 | Unable to establish air flow | EST Flow sensors cross check Test | Failure | Flow controller unable to establish and control air flow at 60, 5, and 1 L/min. | <ol style="list-style-type: none"> 1. Make sure air supply is connected. 2. Check regulated air pressure. 3. Perform flow sensor calibration. 4. Replace PSOL2 or Q2. 5. Replace AI PCB. |
| FE0108 | O ₂ zero flow check failed | EST Flow sensors cross check Test | Failure | Inspiratory flow > 0.153 L/min with oxygen PSOL (PSOL1) commanded to 0 (closed). | <ol style="list-style-type: none"> 1. Verify no leaks at the Q1 O-rings. 2. Run EST Gas Supply Test to check for PSOL1 leak. Remove and then reseal PSOL1 3. Replace PSOL1. 4. Perform a flow sensor calibration. 5. Replace Q1. |
| FE0109 | Air zero flow check failed | EST Flow sensors cross check Test | Failure | Inspiratory flow > 0.153 L/min with air PSOL (PSOL2) commanded to 0 (closed). | <ol style="list-style-type: none"> 1. Verify no leaks at the Q2 O-rings. 2. Run EST Gas Supply Test to check for PSOL2 leak. Remove and then reseal PSOL2 3. Replace PSOL2. 4. Perform a flow sensor calibration. 5. Replace Q2. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--|------------------------|----------|--|---|
| FE0204 | Wall air pressure not detected | EST Gas Supply/SV Test | Failure | Wall air not detected initially and wall air still not detected after user was prompted to connect wall air. | <ol style="list-style-type: none"> 1. Make sure air supply is connected. 2. Check PS2: Remove the wiring connectors from PS2 and jumper the connectors to each other. If the system now recognizes the air supply, replace PS2. |
| FE0205 | O ₂ pressure not detected | EST Gas Supply/SV Test | Failure | Oxygen pressure not detected initially and oxygen pressure still not detected after user was prompted to connect oxygen. | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected. 2. Check PS1: Remove the wiring connectors from PS1 and jumper the connectors to each other. If the system now recognizes the air supply, replace PS1. |
| FE0206 | O ₂ pressure detected (O ₂ not disconnected) | EST Gas Supply/SV Test | Failure | Oxygen pressure switch detected presence of oxygen after user was prompted to disconnect oxygen. | <ol style="list-style-type: none"> 1. Make sure oxygen supply is disconnected. 2. Replace Inspiratory Electronics PCB. 3. Replace PS1. |
| FE0207 | Air PSOL leak | EST Gas Supply/SV Test | Failure | Air PSOL (PSOL2) forward leak was detected via excessive pressure buildup (> 100 cmH ₂ O) in blocked inspiratory module. | <ol style="list-style-type: none"> 1. Check for leaks around the Q2 O-rings. 2. Verify that the safety valve relieves pressures above 100 cmH₂O. Listen for the pressure relief while watching the numeric digital display of system pressure in the upper screen. If the safety valve does not crack open, replace the safety valve. 3. Replace PSOL2. |
| FE0208 | Wall air pressure detected | EST Gas Supply/SV Test | Failure | Wall air pressure switch (PS2) detected wall air after user was prompted to disconnect it. | <ol style="list-style-type: none"> 1. Make sure air supply is disconnected. 2. Replace Inspiratory Electronics PCB. 3. Replace PS2. |
| FE0209 | O ₂ PSOL leak | EST Gas Supply/SV Test | Failure | Oxygen PSOL (PSOL1) forward leak was detected via excessive pressure buildup (> 100 cmH ₂ O) in blocked inspiratory module. | <ol style="list-style-type: none"> 1. Check for leaks around the Q1 O-rings. 2. Verify that the safety valve relieves pressures above 100 cmH₂O. Listen for the pressure relief while watching the numeric digital display of system pressure in the upper screen. If the safety valve does not crack open, replace the safety valve. 3. Replace PSOL1. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---------------------------------------|------------------------|----------|---|---|
| FE0210 | SV pressure relief failed | EST Gas Supply/SV Test | Failure | Safety valve cracking pressure and/or peak steady-state pressure is out of range. | <ol style="list-style-type: none"> 1. Make sure <i>To patient</i> port is blocked. 2. Check for leaks at the O₂ sensor, SOL1 or PI. 3. Replace the safety valve. 4. Replace PI. |
| FE0211 | O ₂ pressure not detected | EST Gas Supply/SV Test | Failure | PS1 did not detect oxygen after user was prompted to connect it. | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected. 2. Replace Inspiratory Electronics PCB. |
| FE0212 | Compressor pressure detected | EST Gas Supply/SV Test | Failure | Compressor pressure transducer (PC) detected that compressor was pressurized. | Replace compressor PCB. |
| FE0215 | Air zero flow check failed | EST Gas Supply/SV Test | Failure | During zero-flow check, air flow sensor (Q2) reads > 0.05 L/min. | <ol style="list-style-type: none"> 1. Make sure gas supplies are disconnected. 2. Make sure compressor is not running. 3. Verify no leaks at the Q2 O-rings. 4. Check for PSOL2 leak. 5. Remove and then reseal PSOL2. 6. Perform a flow sensor calibration. 7. Replace PSOL2. 8. Replace Q2. |
| FE0216 | O ₂ zero flow check failed | EST Gas Supply/SV Test | Failure | During zero-flow check, oxygen flow sensor (Q1) reads > 0.05 L/min. | <ol style="list-style-type: none"> 1. Make sure gas supplies are disconnected. 2. Make sure compressor is not running. 3. Verify no leaks at the Q2 O-rings. 4. Check for PSOL2 leak. 5. Remove and then reseal PSOL2. 6. Perform a flow sensor calibration. 7. Replace PSOL2. 8. Replace Q2. |
| FE0217 | Exp zero flow check failed | EST Gas Supply/SV Test | Failure | During zero-flow check, exhalation flow sensor (Q3) reads > 0.1 L/min. | <ol style="list-style-type: none"> 1. Make sure gas supplies are disconnected. 2. Make sure compressor is not running. 3. Verify no leaks at the Q3 O-rings. 4. Perform a flow sensor calibration. 5. Replace Q3. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|-------------------------------------|-----------------------|----------|--|--|
| FE0301 | Excessive leak | EST Leak Test | Failure | System pressure dropped below failure pressure level. | <ol style="list-style-type: none"> 1. Make sure test circuit is connected and is not leaking. 2. Check for system leaks or occlusions especially at the O₂ sensor and expiratory filter. 3. Verify secure connection of expiratory filter. 4. Check exhalation valve operation. |
| FE0305 | Unable to establish pressure | EST Leak Test | Failure | System cannot attain leak test starting pressure using oxygen or air within time-out period. | <ol style="list-style-type: none"> 1. Make sure test circuit is connected and is not leaking. 2. Check exhalation valve operation, and verify secure connection of expiratory filter. |
| FE0401 | Accept key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0402 | Clear key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0403 | Insp. Pause key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0404 | Exp. Pause key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0405 | Man Insp fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0406 | 100% O ₂ /CAL key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0407 | Info key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0408 | Alarm Reset key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0409 | Alarm Silence key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0410 | Alarm Volume key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |
| FE0411 | Screen brightness fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | <ol style="list-style-type: none"> 1. Repeat test. 2. Replace keyboard. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--|------------------------|----------|---|--|
| FE0412 | Screen contrast key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | 1. Repeat test. 2. Replace keyboard. |
| FE0413 | Screen lock key fails. | EST GUI Keyboard Test | Failure | Wrong key pressed or key not pressed within 15 s. | 1. Repeat test. 2. Replace keyboard. |
| FE0501 | Bad knob | EST GUI Knob Test | Failure | Knob was not turned in direction as prompted within 15 s. | 1. Repeat test. 2. Replace keyboard. |
| FE0801 | SAAS (Safety Audible Alarm System) test failed | EST GUI Audio Test | Failure | CLEAR key pressed to indicate GUI audio diagnostic failed. | 1. Verify the GUI alarm cable connection to the GUI CPU PCB. 2. Replace GUI alarm assembly. 3. Replace GUI CPU PCB. |
| FE0901 | Bad alarm cable | EST BDU Audio Test | Failure | Alarm cable voltage is out of range (< 3.5 or > 5.05 V). | 1. Make sure BD alarm cable is connected. 2. Replace BD alarm. 3. Replace AI PCB. 4. Replace BD alarm cable. |
| FE0902 | Bad power fail cap | EST BDU Audio Test | Failure | Power failure capacitor initial voltage is out of range (< 4.5 or > 5.05 V). | 1. Make sure BD alarm cable is connected. 2. Replace BD alarm. 3. Replace AI PCB. 4. Replace BD alarm cable. 5. Replace Motherboard PCB. |
| FE0903 | Bad power fail cap | EST BDU Audio Test | Failure | Power failure capacitor final voltage is out of range or RC constant < 60 s. | 1. Make sure BD alarm cable is connected. 2. Replace BD alarm. 3. Replace AI PCB. |
| FE0904 | Bad BD audio | EST BDU Audio Test | Failure | CLEAR key pressed to indicate user did not hear alarm, although alarm was active. | 1. Make sure BD alarm cable is connected. 2. Replace BD alarm. 3. Replace AI PCB. 4. Replace BD alarm cable. |
| FE1101 | Safety valve occluded | EST Safety System Test | Failure | Excessive safety valve back pressure when safety valve is open. | Replace safety valve. |
| FE1102 | Bad safety valve driver or loopback | EST Safety System Test | Failure | Safety valve loopback current is out of range during one or more of timed test points. | 1. Replace safety valve. 2. Replace AI PCB. 3. Replace Inspiratory Electronics PCB. |
| FE1103 | Insp check valve test failed | EST Safety System Test | Failure | It took too long to relieve excess pressure through open safety valve, indicating inspiratory check valve (CV3) is occluded or test circuit is too large. | 1. Make sure proper test circuit is used. 2. Make sure CV3 is not installed backward. 3. Replace CV3. 4. Replace Safety Valve (SV). |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|------------------------------|-------------------------|----------|--|--|
| FE1105 | Unable to establish flow | EST Safety System Test | Failure | Flow controller unable to establish and control gas flow at 60 L/min. | <ol style="list-style-type: none"> 1. Make sure air supply is connected and unrestricted. 2. Check air regulator pressure. 3. Run flow sensor calibration. 4. Switch PSOLs to see if test passes. If it does, return PSOL1 to its original position and replace PSOL2. 5. Replace Q2. |
| FE1301 | Seal test failed | EST Exp Valve Seal Test | Failure | Seal test Δ pressure is above failure level. | <ol style="list-style-type: none"> 1. Clean exhalation valve. 2. Calibrate exhalation valve. 3. Run flow sensor calibration. 4. Replace exhalation valve. 5. Replace AI PCB. 6. Replace PE. |
| FE1302 | Exp valve temp OOR | EST Exp Valve Seal Test | Failure | Exhalation valve magnet temperature out of range (10 to 100°C). | <ol style="list-style-type: none"> 1. Ensure the unit has been warmed up at ambient temperature for at least 10 minutes. 2. Calibrate the exhalation valve (EV). 3. Replace exhalation valve (EV). 4. Replace AI PCB. |
| FE1303 | Unable to establish exp flow | EST Exp Valve Seal Test | Failure | Flow controller unable to establish and control air flow measured by exhalation flow sensor (Q3). | <ol style="list-style-type: none"> 1. Make sure proper test circuit it used and that there are no leaks or occlusions. 2. Make sure air supply is still connected. 3. Run flow sensor calibration. 4. Replace Q3. 5. Replace Q2. 6. Replace the exhalation valve. |
| FE1304 | Exp valve not calibrated | EST Exp Valve Seal Test | Failure | Exhalation valve table checksum is not valid or last calibration performed was not completed successfully. | <ol style="list-style-type: none"> 1. Check for leaks or occlusions. Correct and then run the exhalation valve calibration. 2. Replace the exhalation valve. 3. Replace the AI PCB. 4. Replace Q3. 5. Replace Q2. |
| FE1401 | Bad calibration | EST Exp Valve Test | Failure | Measured system pressure at one or more test points is out of range. | <ol style="list-style-type: none"> 1. Calibrate exhalation valve. 2. Replace exhalation valve. 3. Replace AI PCB. 4. Replace the Exhalation Pressure Transducer PCB. |
| FE1402 | Exp valve not calibrated | EST Exp Valve Test | Failure | Exhalation valve table checksum is not valid or last calibration performed was not completed successfully. | <ol style="list-style-type: none"> 1. Check for leaks or occlusions. Correct and then run the exhalation valve calibration. 2. Replace the exhalation valve. 3. Replace the AI PCB. 4. Replace Q3. 5. Replace Q2. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|------------------------------|-----------------------------|----------|--|--|
| FE1403 | Unable to establish exp flow | EST Exp Valve Test | Failure | Flow controller unable to establish and control air flow measured by exhalation flow sensor (Q3). | <ol style="list-style-type: none"> 1. Check for leaks or occlusions. Correct and then run the exhalation valve calibration. 2. Replace the exhalation valve. 3. Replace the AI PCB. 4. Replace Q3. 5. Replace Q2. |
| FE1501 | Unable to establish air flow | EST Exp Heater Test | Failure | Flow controller unable to establish and control 60 L/min air flow. | <ol style="list-style-type: none"> 1. Make sure air supply is connected and unrestricted. 2. Check air regulator pressure. 3. Run flow sensor calibration. 4. Switch PSOLs to see if test passes. If it does, return PSOL1 to its original position and replace PSOL2. 5. Replace Q2. |
| FE1502 | Bad exp heater | EST Exp Heater Test | Failure | Exhalation heater temperature did not rise sufficiently when heater was turned on. | <ol style="list-style-type: none"> 1. Replace exhalation heater. 2. Replace AI PCB. 3. Replace interconnect cable between exhalation compartment and motherboard. |
| FE1503 | Bad exp heater | EST Exp Heater Test | Failure | Heater temperature did not drop sufficiently during an interval after heater was turned off. | <ol style="list-style-type: none"> 1. Replace exhalation heater. 2. Replace AI PCB. |
| FE2201 | Low exp ΔP | EV Velocity Transducer Test | Failure | Expiratory ΔP too low, indicating velocity transducer not responding properly. | <ol style="list-style-type: none"> 1. Check for leaks or occlusions. Correct and then run the exhalation valve calibration. 2. Run flow sensor calibration. 3. Replace exhalation valve. 4. Replace Q3. 5. Replace Q2. |
| FE2301 | Nurse call stuck on | EST GUI Nurse Call Test | Failure | CLEAR key pressed to indicate nurse's call (remote alarm) relay is stuck on when it should be off. | <ol style="list-style-type: none"> 1. Make sure test equipment is connected properly to remote alarm port. 2. Replace GUI CPU PCB. |
| FE2302 | Nurse call stuck off | EST GUI Nurse Call Test | Failure | CLEAR key pressed to indicate nurse's call (remote alarm) relay is stuck off when it should be on. | <ol style="list-style-type: none"> 1. Make sure test equipment is connected properly to remote alarm port. 2. Replace GUI CPU PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|---|---|----------------------|----------|--|--|
| NOTE: For all "FS" codes (failures reported during SST), if the corrective action indicated is to run an EST to further diagnose the problem, perform the repair after the EST, verify the fix in EST, and then rerun SST in order to enter normal ventilator operation. If there is a failed SST test result in memory, normal operation until is prevented until the failed SST test is rerun and passes. | | | | | |
| FS0001 | O ₂ flow sensor cross check failed | SST Flow Sensor Test | Failure | Oxygen flow sensor (Q1) cross-check failed. | <ol style="list-style-type: none"> 1. Correct the leak or occlusion in the SST patient circuit and rerun or try known good patient circuit and filter set. 2. Verify that the ventilator system has no leaks or occlusions by running the first four tests in EST to run the leak test. <ol style="list-style-type: none"> a. If the leak test fails in EST, troubleshoot the expiratory filter or ventilator system for leaks or occlusions. b. If the leak test passes in EST, troubleshoot the SST patient circuit. 3. Run a flow sensor calibration. 4. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the air side, return Q2 back to its original position and replace Q1. 5. Replace Q3 6. Switch PSOLs to see if the failure transfers to the air side. If yes, return PSOL2 back to its original position and replace PSOL1. |
| FS0002 | O ₂ PSOL current out of range | SST Flow Sensor Test | Failure | Oxygen PSOL (PSOL1) command current is out of range with respect to oxygen flow sensor (Q1). | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected and unrestricted. 2. Verify that the oxygen supply is good. 3. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 4. Run a flow sensor calibration. 5. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the air side, return Q2 back to its original position and replace Q1. 6. Replace Q3. 7. Switch PSOLs to see if the failure transfers to the air side. If yes, return PSOL2 back to its original position and replace PSOL1. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|------------------------------------|----------------------|----------|--|---|
| FS0003 | Air flow sensor cross check failed | SST Flow Sensor Test | Failure | Air flow sensor (Q2) cross-check failed. | <ol style="list-style-type: none"> 1. Correct the leak or occlusion in the SST patient circuit and rerun or try known good patient circuit and filter set. 2. Verify that the ventilator system has no leaks or occlusions by running the first four tests in EST to run the leak test. 3. If the leak test fails in EST, troubleshoot the expiratory filter or ventilator system for leaks or occlusions. 4. If the leak test passes in EST, troubleshoot the SST patient circuit. 5. Run a flow sensor calibration. 6. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the oxygen side, return Q1 back to its original position and replace Q2. 7. Replace Q3. 8. Switch PSOLs to see if the failure transfers to the oxygen side. If yes, return PSOL1 back to its original position and replace PSOL2. |
| FS0004 | Air PSOL current out of range | SST Flow Sensor Test | Failure | Air PSOL (PSOL2) command current is out of range with respect to air flow sensor (Q2). | <ol style="list-style-type: none"> 1. Make sure air supply is connected and unrestricted. 2. Verify that the air supply is good. 3. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 4. Run a flow sensor calibration. 5. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the oxygen side, return Q1 back to its original position and replace Q2. 6. Replace Q3. 7. Switch PSOLs to see if the failure transfers to the oxygen side. If yes, return PSOL1 back to its original position and replace PSOL2. |
| FS0005 | Gas not connected | SST Flow Sensor Test | Failure | No gas is available (neither PS1, PS2, nor PC detects pressure). | Connect gas supply. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---|----------------------|----------|--|--|
| FS0006 | Unable to establish O ₂ flow | SST Flow Sensor Test | Failure | Flow controller unable to establish and control oxygen flow at 60, 5, and 1 L/min. | <ol style="list-style-type: none"> 1. Make sure oxygen supply is connected and unrestricted. 2. Verify that the oxygen supply is good. 3. Check regulated oxygen pressure. 4. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 5. Run a flow sensor calibration. 6. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the air side, return Q2 back to its original position and replace Q1. 7. Replace exhalation flow sensor (Q3). 8. Switch PSOLs to see if the failure transfers to the air side. If yes, return PSOL2 back to its original position and replace PSOL1. |
| FS0007 | Unable to establish air flow | SST Flow Sensor Test | Failure | Flow controller unable to establish and control air flow at 60, 5, and 1 L/min. | <ol style="list-style-type: none"> 1. Make sure air supply is connected unrestricted. 2. Verify that the air supply is adequate. 3. Check regulated air pressure. 4. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 5. Run a flow sensor calibration. 6. Switch Q1 and Q2. Rerun the flow sensor calibration and EST. If the failure transfers to the oxygen side, return Q1 back to its original position and replace Q2. 7. Replace exhalation flow sensor (Q3). 8. Switch PSOLs to see if the failure transfers to the oxygen side. If yes, return PSOL1 back to its original position and replace PSOL2. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---------------------------------------|---------------------------|----------|--|---|
| FS0008 | O ₂ zero flow check failed | SST Flow Sensor Test | Failure | Inspiratory flow > 0.153 L/min with oxygen PSOL (PSOL1) commanded to 0 (closed). | <ol style="list-style-type: none"> 1. Verify no leaks at the Q1 O-rings. 2. Run EST Gas Supply Test to check for PSOL1 leak. 3. Remove and then reseal PSOL1. 4. Replace PSOL1. 5. Perform a flow sensor calibration. 6. Replace Q1. |
| FS0009 | Air zero flow check failed | SST Flow Sensor Test | Failure | Inspiratory flow > 0.153 L/min with air PSOL (PSOL2) commanded to 0 (closed). | <ol style="list-style-type: none"> 1. Verify no leaks at the Q2 O-rings. 2. Run EST Gas Supply Test to check for PSOL2 leak. 3. Remove and then reseal PSOL2. 4. Replace PSOL2. 5. Perform a flow sensor calibration. 6. Replace Q2. |
| FS0101 | Inspiratory autozero out of range | SST circuit pressure test | Failure | Inspiratory pressure transducer ADC count at 0 cmH ₂ O is out of range. | <ol style="list-style-type: none"> 1. Replace Inspiratory Electronics PCB 2. Replace AI PCB. |
| FS0102 | Expiratory autozero out of range | SST circuit pressure test | Failure | Expiratory pressure transducer ADC count at 0 cmH ₂ O is out of range. | <ol style="list-style-type: none"> 1. Replace exhalation transducer PCB. 2. Replace AI PCB. 3. Replace SOL1. |
| FS0103 | Failed to reach test pressure | SST circuit pressure test | Failure | Unable to build pressure (air) to 10 cmH ₂ O at 5 L/min within time-out period. | <ol style="list-style-type: none"> 1. Verify that the patient circuit system has no leaks or occlusions or use a known good patient circuit and filter set. 2. Verify that the air supply or compressor is available and adequate. 3. Verify that the ventilator system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|-------------------------------|---------------------------|----------|---|--|
| FS0104 | Cross-check failed | SST circuit pressure test | Failure | Inspiratory/expiratory pressure transducer readings at 10 cmH ₂ O test pressure are too far apart. | <ol style="list-style-type: none"> 1. Verify that the patient circuit system has no leaks or occlusions or use a known good patient circuit and filter set. 2. Verify that the ventilator system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 3. If the leak test passes in EST, exit out of EST. Review the data for the Circuit Pressure Test to determine which pressure transducer is out of range: PI or PE. Replace applicable pressure transducer. 4. Replace AI PCB. |
| FS0105 | Bad insp autozero solenoid | SST circuit pressure test | Failure | Inspiratory pressure reading taken after actuating inspiratory pressure transducer autozero solenoid (SOL1) is out of range (-0.60 to 0.60 cmH ₂ O). | <ol style="list-style-type: none"> 1. Replace SOL1. 2. Replace Inspiratory Electronics PCB. 3. Replace AI PCB. |
| FS0106 | Bad exp autozero sol | SST circuit pressure test | Failure | Expiratory pressure reading taken after actuating expiratory transducer autozero solenoid (SOL2) is out of range (-0.60 to 0.60 cmH ₂ O). | <ol style="list-style-type: none"> 1. Replace SOL2. 2. Replace exhalation transducer PCB. 3. Replace AI PCB. |
| FS0107 | Cross-check failed | SST circuit pressure test | Failure | Inspiratory/expiratory pressure transducer readings at 50 or 100 cmH ₂ O test pressure are too far apart. | <ol style="list-style-type: none"> 1. Replace the expiratory bacteria filter. 2. Verify that the system has no leaks or occlusions. If not sure, run the first four tests in EST to run the leak test. 3. If the leak test passes in EST, exit out of EST. Review the data for the EST Circuit Pressure Test to determine which pressure transducer is out of range: PI or PE. Replace applicable pressure transducer. 4. Replace AI PCB. |
| FS0108 | Failed to reach test pressure | SST circuit pressure test | Failure | Unable to build pressure (air) to 50 or 100 cmH ₂ O at 5 L/min within time-out period. | <ol style="list-style-type: none"> 1. Make sure air supply or compressor is available. 2. Check for system leak. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|----------------------------------|------------------------|----------|--|---|
| FS0201 | Excessive leak | SST Circuit leak | Failure | System pressure dropped below failure pressure level. | 1. Make sure patient circuit is connected and is not leaking. 2. Check exhalation valve operation, and verify secure connections of bacteria filters, water traps, and humidifier. |
| FS0205 | Unable to establish pressure | SST Circuit leak | Failure | Unable to attain leak test starting pressure within time-out period using oxygen or air. | 1. Make sure patient circuit is connected and is not leaking. 2. Check exhalation valve operation, and verify secure connections of bacteria filters, water traps, and humidifier. |
| FS0301 | Unable to establish flow | SST Expiratory filter | Failure | Flow controller unable to establish and control gas flow. | Make sure gas supply is still connected. |
| FS0303 | Occluded expiratory compartment | SST Expiratory filter | Failure | Exhalation compartment pressure > 4 cmH ₂ O. | 1. Check compartment for obstruction. 2. Verify exhalation valve operation by running EST. |
| FS0304 | Occluded expiratory filter | SST Expiratory filter | Failure | Pressure drop across filter > 3 cmH ₂ O. | Replace expiratory filter. |
| FS0306 | Patient circuit not disconnected | SST Expiratory filter | Failure | A test flow was used to verify that circuit was disconnected, and an expiratory flow was detected. | Make sure patient circuit is disconnected at expiratory filter. |
| FS0307 | Patient circuit not reconnected | SST Expiratory filter | Failure | A test flow was used to verify that circuit was reconnected, and an expiratory flow was not detected. | Make sure patient circuit is connected at expiratory filter. |
| FS0310 | Low expiratory filter ΔP | SST Expiratory filter | Failure | Pressure drop across expiratory filter < 0.1 cmH ₂ O. | 1. Repeat test, following directions more closely. 2. Replace filter. |
| FS0401 | Unable to establish flow | SST Circuit Resistance | Failure | Flow controller unable to establish and control gas flow. | Make sure gas supply is connected. |
| FS0402 | Occluded inspiratory limb | SST Circuit Resistance | Failure | Inspiratory limb pressure > 12.5 cmH ₂ O (adult) or 7.5 cmH ₂ O (pediatric), indicating occlusion. | Check for occluded patient tubing. |
| FS0404 | Unable to reach min peak flow | SST Circuit Resistance | Failure | During characterization of total circuit resistance over a range of flows, peak flow was less than failure threshold. | Check for kinked or occluded patient tubing. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--------------------------------|----------------------------|----------|---|--|
| FS0405 | Occluded exhalation limb | SST Circuit Resistance | Failure | Expiratory limb pressure > 12.5 cmH ₂ O (adult) or 7.5 cmH ₂ O (pediatric), indicating occlusion. | Check for occluded patient tubing. |
| FS0408 | Insp limb resistance low | SST Circuit Resistance | Failure | Inspiratory limb pressure < 0.2 cmH ₂ O. | <ol style="list-style-type: none"> 1. Make sure inspiratory filter is installed. 2. Repeat test, following directions more closely. 3. Replace inspiratory filter. 4. Replace patient circuit. |
| FS0409 | Exp limb resistance low | SST Circuit Resistance | Failure | Expiratory limb pressure < 0.2 cmH ₂ O. | Replace patient circuit. |
| FS0410 | Unable to reach min peak flow | SST Circuit Resistance | Failure | During characterization of total circuit resistance over a range of flows, peak flow was less than failure threshold. | Check for kinked or occluded patient tubing. |
| FS0412 | Wye not blocked | SST Circuit Resistance | Failure | Unable to pressurize system within time-out period. | <ol style="list-style-type: none"> 1. Block wye when prompted. 2. Check for circuit leaks. |
| FS0501 | Unable to pressurize circuit | SST Compliance calibration | Failure | System cannot pressurize to one of the test pressure points. | Check patient circuit for leaks. Replace as necessary. |
| FS0502 | Unable to pressurize circuit | SST Compliance calibration | Failure | System cannot pressurize to one of the test pressure points. | Check patient circuit for leaks. Replace as necessary. |
| FS0503 | Compliance calculation failure | SST Compliance calibration | Failure | Out-of-range pressure ratio calculation. | <ol style="list-style-type: none"> 1. Repeat test, making sure circuit is undisturbed during test. 2. Repeat SST to retest pressure transducers. 3. Run EST and verify all pneumatics tests pass. |
| FS0504 | Excessive compliance | SST Compliance calibration | Failure | High compliance > 12 mL/cmH ₂ O (adult) or 9 mL/cmH ₂ O (pediatric). | <ol style="list-style-type: none"> 1. Make sure correct patient tubing type was specified in SST. 2. Replace patient circuit. |
| FS0506 | Compliance low | SST Compliance calibration | Failure | High compliance falls below 1.05 mL/cmH ₂ O | <ol style="list-style-type: none"> 1. Make sure correct patient tubing type was specified in SST. 2. Replace patient circuit. |
| FS0508 | Excessive compliance | SST Compliance calibration | Failure | Low compliance > 12 mL/cmH ₂ O (adult) or 9 mL/cmH ₂ O (pediatric). | <ol style="list-style-type: none"> 1. Make sure correct patient tubing type was specified in SST. 2. Replace patient circuit. |
| FS0510 | Compliance low | SST Compliance calibration | Failure | Low compliance falls below 1.05 mL/cmH ₂ O | <ol style="list-style-type: none"> 1. Make sure correct patient tubing type was specified in SST. 2. Replace patient circuit. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--|------------------------|-----------|--|--|
| HN0001 | Non-maskable interrupt (NMI): Dynamic random access memory (DRAM) Parity Error | Other (BDU) | BDU reset | | Replace BD CPU PCB. |
| HN0002 | NMI: Ethernet Parity Error | Other (BDU) | BDU reset | | Replace BD CPU PCB. |
| HN0016 | NMI: Analog Interface Error: analog to digital converter (ADC) Channel Sequencer Fault | Other (BDU) | BDU reset | | 1. Replace AI PCB. 2. Replace BD CPU PCB. |
| HN0016 | NMI: Analog Interface Error: ADC Timing Fault | Other (BDU) | BDU reset | | 1. Replace AI PCB. 2. Replace BD CPU PCB. |
| HN0016 | NMI: Analog Interface Error: Hamming Decode Fault | Other (BDU) | BDU reset | | 1. Replace AI PCB. 2. Replace BD CPU PCB. |
| HN0080 | NMI: Analog Interface Error: ADC Timing Fault | Other (BDU) | BDU reset | | Replace AI PCB. |
| HN0129 | NMI: DRAM Parity Error | Other (BDU) | BDU reset | | 1. Check GUI/BD cable connections. 2. Replace power supply. 3. Replace BD CPU PCB. |
| HN0130 | NMI: Ethernet Parity Error | Other (BDU) | BDU reset | | 1. Check GUI/BD cable connections. 2. Replace power supply. 3. Replace BD CPU PCB. |
| KB0001 | Bad safety valve switched side | Background check (BDU) | Vent inop | Measured voltage on safety valve switched side indicates valve is not in expected state. | 1. Replace safety valve. 2. Replace AI PCB. 3. Replace Inspiratory Electronics PCB. 4. Replace interconnect cable between the mother board and the Inspiratory Electronics PCB. |
| KB0002 | Bad expiratory flow | Background check (BDU) | Vent inop | Exhalation flow sensor (Q3) reading out of range | 1. If possible, run EST and use the Flow Sensor Cross Check test to determine if Q3 is failing. Replace Q3 if applicable. 2. Perform flow sensor calibration. 3. Replace AI PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---------------------------------------|------------------------|-----------|--|---|
| KB0003 | Bad O ₂ PSOL current | Background check (BDU) | Vent inop | Oxygen PSOL (PSOL1) current out of range | <ol style="list-style-type: none"> 1. If possible, run EST to determine if PSOL1 is failing. Switch PSOLs to see if the failure transfers to the other side. Replace PSOL1 if applicable. 2. Replace AI PCB. 3. Replace Inspiratory Electronics PCB. 4. Replace interconnect cable between the motherboard and the Inspiratory Electronics PCB. |
| KB0004 | Bad air PSOL current | Background check (BDU) | Vent inop | Air PSOL (PSOL2) current out of range | <ol style="list-style-type: none"> 1. If possible, run EST to determine if PSOL2 is failing. Switch PSOLs to see if the failure transfers to the other side. Replace PSOL2 if applicable. 2. Replace AI PCB. 3. Replace Inspiratory Electronics PCB. 4. Replace interconnect cable between the motherboard and the Inspiratory Electronics PCB. |
| KB0005 | Bad exp motor current | Background check (BDU) | Vent inop | Current to exhalation valve motor out of range | <ol style="list-style-type: none"> 1. Perform exhalation valve (EV) calibration. 2. Replace EV. 3. Replace AI PCB. |
| KB0007 | Bad exp pressure | Background check (BDU) | Vent inop | PE reading out of range | <ol style="list-style-type: none"> 1. Replace exhalation transducer PCB. 2. Replace AI PCB. |
| KB0008 | Bad insp pressure | Background check (BDU) | Vent inop | PI reading out of range | <ol style="list-style-type: none"> 1. Replace Inspiratory Electronics PCB. 2. Replace AI PCB. |
| KB0009 | Air flow out of range HIGH | Background check (BDU) | Vent inop | Q2 reading too high | <ol style="list-style-type: none"> 1. Perform flow sensor calibration. 2. Replace Q2. 3. Replace AI PCB. |
| KB0012 | O ₂ flow out of range HIGH | Background check (BDU) | Vent inop | Q1 reading too high | <ol style="list-style-type: none"> 1. Perform flow sensor calibration. 2. Replace Q1. 3. Replace AI PCB. |
| KB0016 | Bad BD 10V supply | Background check (BDU) | Vent inop | BDU +10 V supply out of range | Replace AI PCB. |
| KB0017 | Bad BD 12 V supply | Background check (BDU) | Vent inop | BDU +12 V supply out of range | <ol style="list-style-type: none"> 1. Replace AI PCB. 2. Replace power supply or other power input components. |
| KB0018 | Bad BD 15 V supply | Background check (BDU) | Vent inop | BDU +15 V supply out of range | <ol style="list-style-type: none"> 1. Replace AI PCB. 2. Replace power supply or other power input components. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--------------------------------|------------------------|-----------|--|---|
| KB0019 | Bad BD -15 V | Background check (BDU) | Vent inop | BDU -15 V supply out of range | <ol style="list-style-type: none"> 1. Replace AI PCB. 2. Replace power supply or other power input components. |
| KB0022 | Bad BD 5 V supply | Background check (BDU) | Vent inop | BDU +5 V supply out of range | <ol style="list-style-type: none"> 1. Replace AI PCB. 2. Replace power supply or other power input components. |
| KB0023 | O ₂ PSOL stuck | Background check (BDU) | Vent inop | Oxygen PSOL (PSOL1) command current out of range | <ol style="list-style-type: none"> 3. If possible, run EST to determine if PSOL1 is failing. Switch PSOLs to see if the failure transfers to the other side. Replace PSOL1 if applicable. 4. Replace AI PCB. 5. Replace Inspiratory Electronics PCB. 6. Replace interconnect cable between the motherboard and the Inspiratory Electronics PCB. |
| KB0024 | Air PSOL stuck | Background check (BDU) | Vent inop | Air PSOL (PSOL2) command current out of range | <ol style="list-style-type: none"> 1. If possible, run EST to determine if PSOL2 is failing. Switch PSOLs to see if the failure transfers to the other side. Replace PSOL2 if applicable. 2. Replace AI PCB. 3. Replace Inspiratory Electronics PCB. 4. Replace interconnect cable between the motherboard and the Inspiratory Electronics PCB. |
| KB0025 | Air PSOL stuck open | Background check (BDU) | Vent inop | Air PSOL (PSOL2) command current reading indicates PSOL stuck open | <ol style="list-style-type: none"> 1. If possible, run EST to determine if PSOL2 is failing. Switch PSOLs to see if the failure transfers to the other side. Replace PSOL2 if applicable. 2. Replace AI PCB. 3. Replace Inspiratory Electronics PCB. 4. Replace interconnect cable between the motherboard and the Inspiratory Electronics PCB. |
| KB0026 | O ₂ PSOL stuck open | Background check (BDU) | Vent inop | PSOL1 command current reading indicates PSOL stuck open | <ol style="list-style-type: none"> 1. If possible, run EST to determine if PSOL1 is failing. Switch PSOLs to see if the failure transfers to the other side. Replace PSOL1 if applicable. 2. Replace AI PCB. 3. Replace Inspiratory Electronics PCB. 4. Replace interconnect cable between the motherboard and the Inspiratory Electronics PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--------------------------------------|------------------------|-----------|--|---|
| KB0030 | Bad safety valve current | Background check (BDU) | Vent inop | Current to safety valve out of range | <ol style="list-style-type: none"> 1. Replace safety valve. 2. Replace AI PCB. 3. Replace Inspiratory Electronics PCB. 4. Replace interconnect cable between the motherboard and the Inspiratory Electronics PCB. |
| KB0031 | Insp pressure stuck | Background check (BDU) | Vent inop | Inspiratory pressure transducer (PI) reading indicates transducer is stuck | <ol style="list-style-type: none"> 1. Replace Inspiratory Electronics PCB. 2. Replace AI PCB. |
| KB0032 | Exp pressure stuck | Background check (BDU) | Vent inop | Expiratory pressure transducer (PE) reading indicates transducer is stuck | <ol style="list-style-type: none"> 1. Replace exhalation transducer PCB. 2. Replace AI PCB. |
| KB0033 | Insp pressure autozero offset failed | Background check (BDU) | Vent inop | Inspiratory pressure transducer (PI) reading following autozero out of range | <ol style="list-style-type: none"> 1. Replace inspiratory pressure transducer autozero solenoid (SOL1). 2. Replace Inspiratory Electronics PCB. 3. Replace AI PCB. |
| KB0034 | Exp pressure autozero offset failed | Background check (BDU) | Vent inop | Expiratory pressure transducer (PE) reading following autozero out of range | <ol style="list-style-type: none"> 1. Replace expiratory pressure transducer autozero solenoid (SOL2). 2. Replace exhalation transducer PCB. 3. Replace AI PCB. |
| KB0037 | Analog-Digital converter failed high | Background check (BDU) | Vent inop | Analog-to-digital converter failure | Replace AI PCB. |
| KB0038 | Analog-Digital converter failed low | Background check (BDU) | Vent inop | Analog-to-digital converter failure | Replace AI PCB. |
| KB0039 | Analog-Digital loopback failed | Background check (BDU) | Vent inop | Analog-to-digital converter failure | Replace AI PCB. |
| KB0044 | BD NOVRAM checksum error | Background check (BDU) | Vent inop | BD NOVRAM failure | Replace BD CPU PCB. |
| KB0053 | BD EEPROM checksum error | Background check (BDU) | Vent inop | BD EEPROM failure | Replace BD CPU PCB. |
| KB0064 | LV Ref out of range | Background check (BDU) | Vent inop | Low-voltage reference out of range | Replace AI PCB. |
| KB0065 | SV current out of range | Background check (BDU) | Vent inop | Safety valve current out of range | <ol style="list-style-type: none"> 1. Replace safety valve. 2. Replace Inspiratory Electronics PCB. 3. Replace AI PCB. 4. Replace interconnect cable between the motherboard and the Inspiratory Electronics PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|---------------------------|-----------------------------|------------------------|-----------|---|---|
| KB0076 | Task Monitor | Background check (BDU) | Vent inop | | Replace BD CPU PCB. |
| KB0079 | BK vent inop occurred | Background check (BDU) | Vent inop | Ventilator inoperative signal read by BDU is active. This could mean GUI has declared a ventilator inoperative condition. | 1. Run the VENT INOP test. a. If the test passes, run EST to reset the Device Alert. Run the unit for 48 hours and then put back into service if the code cannot be duplicated. b. If the test fails, troubleshoot per Table 6-5, VENT INOP Test troubleshooting. |
| KB0082 | Watchdog failure occurred | Background check (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0001 ○○○ ○○○ ● | Processor Initialization | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0002 ○○○ ○○○ ● | Integer Unit Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0003 ○○○ ○○○ ● | DRAM Refresh Timer Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0004 ○○○ ○○○ ● | Kernel DRAM Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0005 ○○○ ○○○ ● | Boot EPROM Checksum Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0006 ○○○ ○○○ ● | POST Phase 2 Initialization | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0007 ○○○ ○○○ ● | Addressing Mode Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|----------------------|-----------------------------------|------------|-----------|--|---|
| KP0008 ○○○ ●○○ | Kernel NOVRAM Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0009 ○○○ ●○○ | Rolling Thunder Test | POST (BDU) | Vent inop | POST has started (but not run to completion) three or more times, for reasons unrelated to power. | 1. Replace AI PCB. 2. Replace BD CPU PCB. 3. Replace motherboard. |
| KP0011 ○○○ ●○○ | Time of Day Clock Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0012 ○○○ ●○○ | Timer Test | POST (BDU) | Vent inop | Timer failed comparison test with real-time clock (external timing reference) or Timer failed to generate interrupt | Replace BD CPU PCB. |
| KP0013 ○○○ ●○○ | Watchdog Timer Test | POST (BDU) | Vent inop | Watchdog timer did not time out as expected | Replace BD CPU PCB. |
| KP0015 ○○○ ●○○ | FLASH Memory Checksum Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0081 ○○○ ●○○ | Memory Management Unit Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0082 ○○○ ●○○ | Bus Timer Test | POST (BDU) | Vent inop | Activity has ceased on local bus or Bus time-out circuit did not generate an interrupt as expected | Replace BD CPU PCB. |
| KP0083 ○○○ ●○○ | NMI Source Register Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0084 ○○○ ●○○ | POST DRAM Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|-----------------|------------------------------|------------|-----------|---|---|
| KP0087 ●●●●● | Unexpected Reset Umpire Test | POST (BDU) | Vent inop | POST has been invoked three times in 24 operational hours due to unexpected resets. | 1. Check associated errors in the System Diagnostic and System Information log to determine why POST was invoked three times within 24 hours. If the codes indicate that the BD CPU generated the resets, replace the BD CPU (Other codes may be present indicating that the GUI lost communications with the BD). 2. Run a complete EST to check for analog device failures. |
| KP0089 ●●●●● | Floating Point Unit Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0090 ●●●●● | DRAM Parity Circuit Test | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0113 ●●●●● | Analog Interface PCB Test | POST (BDU) | Vent inop | | 1. Replace BD CPU PCB. 2. Replace AI PCB. 3. Replace motherboard. |
| KP0114 ●●●●● | ADC Test | POST (BDU) | Vent inop | Analog-to-digital converter data not available to CPU as expected | 1. Replace AI PCB. 2. Replace motherboard. |
| KP0115 ●●●●● | DAC Test | POST (BDU) | Vent inop | Digital-to-analog converter data not as expected | 1. Replace AI PCB. 2. Replace motherboard. |
| KP0116 ●●●●● | Analog Devices Test | POST (BDU) | Vent inop | Critical analog data out of range | 1. Refer to Section 6.8 to identify which analog device is failing. 2. Run EST to get more information on the analog device failure. 3. Replace the AI PCB. 4. Replace the motherboard. 5. Replace the interconnect cable between the Inspiratory Electronics PCB and the motherboard. |
| KP0117 ●●●●● | BD Serial Device Test | POST (BDU) | Vent inop | | 1. Replace AI PCB. 2. Replace BD CPU PCB. 3. Replace the motherboard. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|-------------------------------------|------------------------|-----------|---|--|
| KP0120 | Safe State System Test | POST (BDU) | Vent inop | Places PSOLs and exhalation valve into safe state and verifies that they cannot be commanded. | <ol style="list-style-type: none"> 1. Look up associated codes reported in Diagnostic Log and/or the BD CPU LED array to get more information about other possible system, software, or hardware faults. Troubleshoot those codes. 2. Run a Ground Isolation Test to troubleshoot shorts. 3. Try another inspiratory module and see if the code can be reset by running the VENT INOP, EST and POST tests. <ol style="list-style-type: none"> a. If the unit passes with a known good inspiratory module, replace the Inspiratory Electronics PCB. b. If the unit fails, replace the inspiratory blind mate interconnect cable. 4. Replace the Inspiratory Electronics PCB. 5. Replace the AI PCB. 6. Replace the BD CPU PCB. |
| KP0128 | Download operating system (OS) Boot | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0129 | Application OS Boot | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0130 | PB-MON Boot | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| KP0131 | Application Boot | POST (BDU) | Vent inop | | Replace BD CPU PCB. |
| LB0006 | Bad exhalation valve coil temp. | Background check (BDU) | Alert | Exhalation valve coil temperature out of range | <ol style="list-style-type: none"> 1. Replace exhalation valve. 2. Replace AI PCB. 3. Replace interconnect harness between the exhalation compartment connector and the motherboard. |
| LB0010 | Air flow out of range LOW | Background check (BDU) | Alert | Air flow sensor (Q2) reading too low | <ol style="list-style-type: none"> 1. Perform flow sensor calibration. 2. Replace Q2. 3. Replace AI PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--------------------------------------|------------------------|----------|---|---|
| LB0011 | Bad air flow temperature | Background check (BDU) | Alert | Air flow sensor (Q2) thermistor reading out of range | 1. Replace Q2. 2. Replace AI PCB. |
| LB0013 | O ₂ flow out of range LOW | Background check (BDU) | Alert | Oxygen flow sensor (Q1) reading too low | 1. Ensure that the ventilator has been warmed up for at least 10 minutes in service mode at ambient temperature. 2. Run a flow sensor calibration. 3. Replace Q1.4. Replace the AI PCB. |
| LB0014 | Bad O ₂ flow temp. | Background check (BDU) | Alert | Oxygen flow sensor (Q1) thermistor reading out of range | 1. Replace Q1. 2. Replace AI PCB. |
| LB0015 | Bad expiratory flow temp | Background check (BDU) | Alert | Expiratory flow sensor (Q3) thermistor reading out of range | 1. Replace Q3. 2. Replace AI PCB. |
| LB0020 | Bad GUI 12V supply | Background check (BDU) | Alert | GUI +12 V supply out of range | 1. Check cabling from BD CPU PCB to GUI CPU PCB. 2. Replace AI PCB. 3. Replace power supply. 4. Check whether or not the cable from the GUI to the BDU was reconnected to the unit while the ventilator power was on. If yes, run EST to reset the DEVICE ALERT. |
| LB0021 | Bad GUI 5V supply | Background check (BDU) | Alert | GUI +5 V supply out of range. | 1. Check cabling from BD CPU PCB to GUI CPU PCB. 2. Replace AI PCB. 3. Replace power supply. 4. Check whether or not the cable from the GUI to the BDU was reconnected to the unit while the ventilator power was on. If yes, run EST to reset the DEVICE ALERT. |
| LB0027 | Bad atmospheric press OOR | Background check (BDU) | Alert | Atmospheric pressure transducer reading out of range | 1. Perform atmospheric pressure calibration. 2. Replace Inspiratory Electronics PCB. 3. Replace AI PCB. |
| LB0028 | Bad O ₂ sensor OOR | Background check (BDU) | Alert | Oxygen sensor (percentage) reading out of range | 1. Calibrate oxygen sensor. 2. Replace oxygen sensor. |
| LB0029 | Bad O ₂ sensor OOR reset | Background check (BDU) | Status | A status message indicating that alert was reset | No action required. |
| LB0035 | Bad power fail capacitor voltage | Background check (BDU) | Alert | Power fail capacitor voltage out of range | 1. Replace AI PCB. 2. Replace power supply. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---------------------------------|-------------------------|----------|---|--|
| LB0036 | Alarm cable error | Background check (BDU) | Alert | Alarm cable voltage out of range | 1. Check cabling to main alarm. 2. Replace BD alarm. 3. Replace AI PCB. |
| LB0039 | ADC loopback constant | Background checks (BDU) | Alert | | Replace AI PCB. |
| LB0043 | ac switch stuck | Background check (BDU) | Alert | Power switch is in off state but power fail NMI did not occur | 1. Replace power switch. 2. Replace AI PCB. |
| LB0045 | BD Time of Day failed | Background check (BDU) | Alert | Real-time clock failure | Replace BD CPU PCB. |
| LB0048 | Bad backup power supply voltage | Background check (BDU) | Alert | BPS voltage out of range | 1. Replace BPS battery pack. 2. Replace AI PCB. 3. Replace BPS PCB. |
| LB0049 | Bad backup power supply current | Background check (BDU) | Alert | BPS current out of range | 1. Replace BPS battery pack. 2. Replace AI PCB. 3. Replace BPS PCB. |
| LB0050 | Bad backup power supply model | Background check (BDU) | Alert | Model information incorrect | Replace BPS PCB. |
| LB0051 | Bad exp heater | Background check (BDU) | Alert | Exhalation heater thermistor reading out of range | 1. Replace exhalation heater. 2. Replace AI PCB. 3. Replace interconnect cable between the exhalation compartment and the motherboard. |
| LB0056 | Compressor elapsed timer error | Background check (BDU) | Alert | Compressor timer failure | Replace compressor PCB. |
| LB0057 | Compressor bad eeprom data | Background check (BDU) | Alert | Data in compressor EPROM not as expected | Replace compressor PCB. |
| LB0058 | Loss of GUI communication | Background check (BDU) | Alert | | 1. This code indicates that the BD logged a loss of communications with the GUI. Check for codes generated by the GUI indicating a GUI fault. 2. Check cabling from BD CPU PCB to the GUI CPU PCB. 3. Replace GUI CPU PCB or BD CPU PCB. |
| LB0060 | Resume GUI communication | Background check (BDU) | Status | A status message indicating that communication with GUI was resumed | No action required. |
| LB0062 | Est required | Background check (BDU) | Alert | EST is required, but user cycled power into normal operation, rather than into service mode | Run EST. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|-------------------------------------|-------------------------|----------|---|---|
| LB0075 | Data key update failed | Background check (BDU) | Alert | | 1. Plug in data key. 2. Contact Service or your Puritan Bennett representative for a new data key. |
| LB0076 | Task monitor | Background checks (BDU) | Alert | | No action required unless XP0087 error is also present. |
| LB0080 | Breath delivery extended | Background checks (BDU) | Alert | | Replace BD CPU PCB. |
| LB0083 | Init Resume GUI Communication | Background check (BDU) | Status | A status message indicating that communication with GUI was resumed | No action. |
| LB0085 | Init Loss GUI Communication | Background check (BDU) | Status | A status message indicating that communication with GUI was lost | No action. |
| LB0087 | Compressor S/N updated | Background check (BDU) | Status | | No action. |
| LB0088 | 10000 hours stored for elapsed time | Background check (BDU) | Alert | Compressor hours corrupted. Contact your Puritan Bennett representative to reset. | Replace the compressor PCB. |
| LB0089 | Cannot determine datakey size | Background check (BDU) | Alert | | Replace data key. |
| LB0092 | Battery Event | Background checks (BDU) | Alert | A status message regarding the state of the battery. | 1. Ensure that the green LED is lit on the front of the BPS. a. If the green LED is not lit, allow the BPS to charge until the green LED lights. b. If the green LED does not light (within 6-8 hours or less), replace the battery pack. c. Replace the BPS PCB 2. Once the green LED is lit, run EST to test the BPS and use EST diagnostics to determine if further corrective action is needed. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|----------------------|------------------------------|----------------------------|----------|--|---|
| LC1xxx | Varies | Communications error (BDU) | Alert | | <ol style="list-style-type: none"> 1. Ensure that the green LED is lit on the front of the BPS. <ol style="list-style-type: none"> a. If the green LED is not lit, allow the BPS to charge until the green LED lights. b. If the green LED does not light (within 6-8 hours or less), replace the battery pack. c. Replace the BPS PCB 2. Once the green LED is lit, run EST to test the BPS and use EST diagnostics to determine if further corrective action is needed. |
| LP0008 ○○○ ●○○ | Kernel NOVRAM Test | POST (BD) | Alert | Noncritical NOVRAM data failure | Replace the BD CPU PCB. |
| LP0010 | Interrupt Controller Test | POST (BD) | Alert | | Replace BD CPU PC. |
| LP0011 | Time of Day Clock Test | POST (BD) | aLERT | | Replace BD CPU PCB. |
| LP0085 ○○● ●○○ | Ethernet Self-Test Start | POST (BD) | Alert | | Replace BD CPU PCB. |
| LP0086 ○○● ●○○ | Ethernet Self-Test End | POST (BDU) | Alert | | Replace BD CPU PCB. |
| LP0087 ○○● ●○○ | Unexpected Reset Umpire Test | POST (BDU) | Alert | POST was invoked due to a watchdog time-out (unexpected reset) | <ol style="list-style-type: none"> 1. Check all logs to see associated errors occurring around the same time and date as this code. 2. Run EST to get more information. |
| LP0088 ○○● ●○○ | POST NOVRAM Test | POST (BDU) | Alert | Noncritical NOVRAM data failure | <ol style="list-style-type: none"> 1. Check all logs to see associated errors occurring around the same time and date as this code. 2. Run EST to get more information. |
| LP0112 ○○● ○○○ | Ventilator INOP Test | POST (BDU) | Alert | Ventilator inoperative signal not in expected state | <ol style="list-style-type: none"> 1. Replace the interconnect cable between the Inspiratory Electronics PCB and the motherboard. 2. Run VENT INOP Test. 3. Replace BD CPU PCB. |
| LP0114 | ADC Test | POST (BD) | Alert | | Replace AI PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|---------------------------|------------------------|----------|--|--|
| LP0115 | DAC Test | POST (BD) | Alert | | Replace AI PCB. |
| LP0116 | Analog Devices Test | POST (BDU) | Alert | Noncritical analog data out of range | 1. Refer to Table 6-3: "Address codes for BDU POST analog devices test errors". 2. Replace AI PCB. |
| LP0121 | Service Switch Stuck Test | POST (BDU) | Alert | Service switch appears to be closed. (Only requests to enter service mode made after this test are honored by system.) | 1. Turn off ventilator. Release switch. 2. Check for mechanical obstruction to switch. 3. Replace BD CPU PCB. |
| LP0122 | ac Voltage Test | POST (BDU) | Alert | ac monitor voltage not within set nominal line voltage $\pm 20\%$ | 1. Make sure ventilator is plugged into ac source. 2. Make sure nominal line voltage is set correctly. |
| Sxxxxx | <i>Varies</i> | Other | Status | Status message that indicates an intentionally caused event | No action required. |
| Uxxxxx | Assertion Failure | Background check (GUI) | Alert | | Check System Information and Patient logs for any messages occurring with a high frequency. Otherwise, no corrective action unless accompanied by XP0087 diagnostic code. |
| U04004 | Assertion Failure | Background check (GUI) | Alert | Can occur if there is an intermittent connection to any digital I/O line. | 1. Check all cable connections. 2. Perform Ground Isolation Test. 3. Replace GUI CPU PCB. |
| U05013 | Assertion Failure | Background check (GUI) | Alert | Can occur if there is an intermittent connection to any digital I/O line. | 1. Check all cable connections. 2. Perform Ground Isolation Test. 3. Replace GUI CPU PCB. |
| U08002 | Assertion Failure | Background check (BDU) | Alert | Occurs when the GUI is overloaded with invalid data from the serial port. Caused by the host device transmitting bad data that is generating over-run, parity, or framing errors. The GUI generates a soft reset or assertion to clear the condition and resynchronize with the BDU. | 1. Check for wet expiratory or inspiratory filter. 2. Check all cable connections: GUI, Serial, Internal cables. 3. Review the ventilator logs, including patient logs, observe any occurrences of rapidly repeating messages. This pattern may contribute to a buffer overflow situation that the ventilator will attempt to clear by running POST. 4. Perform Ground Isolation Test. 5. Replace GUI CPU PCB. |
| U08012 | Assertion Failure | Background check (GUI) | Alert | The GUI generates a soft reset or assertion to clear the condition and re synchronize with the BDU. | 1. Check all cable connections. 2. Perform Ground Isolation Test. 3. Replace GUI CPU PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|----------------------------|-------------------------|-----------|--|--|
| U14019 | Assertion Failure | Background check (GUI) | Alert | The GUI generates a soft reset or assertion to clear the condition and resynthesized with the BDU. | <ol style="list-style-type: none"> 1. Check all cable connections. 2. Perform Ground Isolation Test. 3. Replace GUI CPU PCB. |
| U14021 | Assertion Failure | Background check (GUI) | Alert | If the time stamps between the GUI and the BD are out of range, the GUI generates a soft reset or assertion to clear the condition and resynchronize with the BDU. | <ol style="list-style-type: none"> 1. Check all cable connections. 2. Perform Ground Isolation Test. 3. Replace GUI CPU PCB. |
| UT0002 | Assertion Failure | Background check (GUI) | Alert | A reset of the GUI has occurred as a result of a hardware-trap detection. | <p>NOTE: Refer to Section 6.10.1 for further information regarding for this error code.</p> <hr/> <ol style="list-style-type: none"> 1. Refer to Table 6-3: "Address codes for BDU POST analog devices test errors". |
| VN0129 | NMI: DRAM Parity Error | Other (GUI) | GUI reset | | <ol style="list-style-type: none"> 1. Check GUI/BD cable connections. 2. Replace power supply. 3. Replace GUI CPU PCB. |
| VN0130 | NMI: Ethernet Parity Error | Other (GUI) | GUI reset | | <ol style="list-style-type: none"> 1. Check GUI/BD cable connections. 2. Replace power supply. 3. Replace GUI CPU PCB. |
| VN0132 | NMI: +5 V dc Overvoltage | Other (GUI) | GUI reset | | <ol style="list-style-type: none"> 1. Check GUI/BD cable connections. 2. Replace power supply. 3. Replace GUI CPU PCB. |
| VN0136 | NMI: +12 V dc Overvoltage | Other (GUI) | GUI reset | | <ol style="list-style-type: none"> 1. Check GUI/BD cable connections. 2. Replace power supply. 3. Replace GUI CPU PCB. |
| VN0144 | NMI: +12 V dc Undervoltage | Other (GUI) | GUI reset | | <ol style="list-style-type: none"> 1. Check GUI/BD cable connections. 2. Replace power supply. 3. Replace GUI CPU PCB. |
| XB0066 | Monitor alarms fail | Background checks (GUI) | Vent inop | | Call Technical Support or your Puritan Bennett representative. |
| XB0067 | Monitor apnea alarm fails | Background checks (GUI) | Vent inop | | Call Technical Support or your Puritan Bennett representative. |
| XB0068 | Monitor apnea int fails | Background checks (GUI) | Vent inop | | Call Technical Support or your Puritan Bennett representative. |
| XB0069 | Monitor hip fails | Background checks (GUI) | Vent inop | | Call Technical Support or your Puritan Bennett representative. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--------------------------------------|-------------------------|-----------|------------------------------|--|
| XB0070 | Monitor insp time fails | Background checks (GUI) | Vent inop | | Call Technical Support or your Puritan Bennett representative. |
| XB0071 | Monitor no data | Background checks (GUI) | Vent inop | | Call Technical Support or your Puritan Bennett representative. |
| XB0072 | Monitor data corrupted | Background checks (GUI) | Vent inop | | Call Technical Support or your Puritan Bennett representative. |
| XB0073 | Monitor O ₂ mixture fails | Background checks (GUI) | Vent inop | | Call Technical Support or your Puritan Bennett representative. |
| XB0074 | Monitor breath time fails | Background checks (GUI) | Vent inop | | Replace GUI CPU PCB. |
| XP0001 | Processor Initialization | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0002 | Integer Unit Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0003 | DRAM Refresh Timer Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0004 | Kernel DRAM Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0005 | Boot EPROM Checksum Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0006 | POST Phase 2 Initialization | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0007 | Addressing Mode Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0008 | Kernel NOVRAM Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0010 | Interrupt Controller Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|----------------------|------------------------------|------------|-----------|---|--|
| XP0011 ○○○ ●●● | Time of Day Clock Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0012 ○○○ ●●● | Timer Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0013 ○○○ ●●● | Watchdog Timer Test | POST (GUI) | GUI reset | Watchdog timer did not time out as expected | 1. Make sure ventilator is plugged in to wall power and BPS is fully charged. 2. Replace GUI CPU PCB. |
| XP0015 ○○○ ●●● | FLASH Memory Checksum Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0081 ○○○ ●●● | Memory Management Unit Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0082 ○○○ ●●● | Bus Timer Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0083 ○○○ ●●● | NMI Source Register Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0084 ○○○ ●●● | POST DRAM Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0087 ○○○ ●●● | Unexpected Reset Umpire Test | POST (GUI) | GUI inop | POST has been invoked three times in 24 operational hours due to unexpected resets. | Check associated errors in log. Call Technical Support or your Puritan Bennett representative. |
| XP0089 ○○○ ●●● | Floating Point Unit Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0090 ○○○ ●●● | DRAM Parity Circuit Test | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0097 ○○○ ●●● | SAAS Self-Test Start | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |






Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|-------------------------------|-------------------------|----------|--|--|
| XP0098 | SAAS Self-Test End | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0128 | Download OS Boot | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0129 | Application OS Boot | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0130 | PB-MON Boot | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| XP0131 | Application Boot | POST (GUI) | GUI inop | | Replace GUI CPU PCB. |
| ZB0040 | Touch screen failed | Background checks (GUI) | Alert | | Replace touch frame. |
| ZB0041 | Touch screen blocked | Background checks (GUI) | Alert | | 1. Check for obstruction on screen or clean screen. 2. Replace touch frame. |
| ZB0042 | Touch screen resumed | Background checks (GUI) | Status | A status message indicating that communication with touch screen was resumed | No action required. |
| ZB0046 | GUI Time of Day failed | Background checks (GUI) | Alert | | Replace GUI CPU PCB. |
| ZB0047 | GUI NOVRAM checksum error | Background checks (GUI) | Alert | Noncritical NOVRAM data failure | 1. Replace GUI CPU PCB. 2. Call Technical Support or your Puritan Bennett representative. |
| ZB0052 | GUI key stuck | Background checks (GUI) | Alert | | 1. Replace keyboard. 2. Replace GUI CPU PCB. |
| ZB0054 | GUI EEPROM checksum error | Background checks (GUI) | Alert | | Replace GUI CPU PCB. |
| ZB0055 | GUI SAAS communication failed | Background checks (GUI) | Alert | | Replace GUI CPU PCB. |
| ZB0059 | Loss of BD communication | Background checks (GUI) | Alert | | 1. Check cabling from BD CPU PCB to GUI CPU PCB. 2. Replace BD CPU PCB or GUI CPU PCB. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|-------------------------------|----------------------------|----------|--|---|
| ZB0061 | Resume BD communication | Background checks (GUI) | Status | A status message indicating that communication with BD was resumed | No action required. |
| ZB0063 | GUI SAAS Audio failed | Background checks (GUI) | Alert | | 1. Replace GUI alarm assembly. 2. Replace GUI CPU PCB. |
| ZB0076 | Task Monitor | Background checks (GUI) | Alert | | No action required unless a XP0087 error is also present. |
| ZB0077 | GUI dropped a waveform packet | Background checks (GUI) | Status | A status message indicating a waveform data packet was lost in transmission from the BD. | No action required. |
| ZB0084 | Init Resume BD communication | Background checks (GUI) | Status | A status message indicating that communication with BD was resumed. | No action required. |
| ZB0086 | Init Loss of BD communication | Background checks (GUI) | Alert | A status message indicating that communication with BD was lost. | See associated error codes. |
| ZB0090 | Touch Screen blocked | Background checks (GUI) | Alert | | 1. Remove visible items from GUI screen. 2. Clean GUI screen. 3. Replace touchscreen PCB. |
| ZB0091 | Touch Screen resumed | Background checks (GUI) | Status | Status message indicates that a touch screen blocked error is cleared. | |
| ZC0xxx | <i>Varies</i> | Communications error (GUI) | Alert | | No action required unless a ZB0059 error is also present. |
| ZC0xxx | <i>Varies</i> | Communications error (BDU) | Alert | | 1. Ensure that the green LED is lit on the front of the BPS. a. If the green LED is not lit, allow the BPS to charge until the green LED lights. b. If the green LED does not light (within 6-8 hours or less), replace the battery pack. c. Replace the BPS PCB 2. Once the green LED is lit, run EST to test the BPS and use EST diagnostics to determine if further corrective action is needed. |
| ZC1xxx | <i>Varies</i> | Communications error (GUI) | Alert | | No action required unless a ZB0059 error is also present. |

Table 6-2: 840 Ventilator diagnostic codes (continued)

| Code | Message displayed | Test | Response | Information / Possible cause | Corrective action |
|--------|--|----------------------------|----------|--|--|
| ZC2000 | DCI parity error | Communications error (GUI) | Alert | | Check parity of host device. |
| ZC2001 | DCI input buffer overflow error | Communications error (GUI) | Alert | | 1. Check cabling between ventilator and host. 2. Check baud rate of host device. |
| ZC2002 | DCI command error | Communications error (GUI) | Alert | Undefined command received | 1. Check host software for compatibility with ventilator. 2. Check cabling between ventilator and host. |
| ZC2003 | DCI unknown error | Communications error (GUI) | Alert | | 1. Check host software for compatibility with ventilator. 2. Check cabling between ventilator and host. |
| ZP0008 |  Kernel NOVRAM Test | POST (GUI) | Alert | Noncritical NOVRAM data failure | Call Technical Support or your Puritan Bennett representative. |
| ZP0085 |  Ethernet Self-Test Start | POST (GUI) | Alert | Spec says failure | Replace GUI CPU PCB. |
| ZP0086 |  Ethernet Self-Test End | POST (GUI) | Alert | Spec says failure | Replace GUI CPU PCB. |
| ZP0087 |  Unexpected Reset Umpire Test | POST (GUI) | Alert | POST was invoked due to an unexpected reset. | Check associated errors in log. No action required unless other errors are present. |
| ZP0088 |  POST NOVRAM Test | POST (GUI) | Alert | Noncritical NOVRAM data failure | Replace GUI CPUPCB. |


6.8 System Diagnostic Log and BDU POST analog devices test

Analog device errors reported during the BDU POST analog devices test are recorded in the System Diagnostic Log. These errors are reported as diagnostic codes KP0116 and LP0116. Information in the NOTES column of the log identifies the analog channel on which the error occurred.

Using an example of a BDU POST analog device error, as it might be reported in the System Diagnostic Log:

| TIME | TEST/EVENT | CODE | TYPE | NOTES |
|-----------------------|---------------|--------|---------|--|
| 12:55:59 08 Aug 03 | ANALOG DEVICE | KP0116 | FAILURE | PC: 0x000202DD EV: 0 NMI: 0xC0 Err Code: 0xCC |

The error address (NOTES) identifies the analog channel:



The diagnostic codes, KP0116 (BDU) and LP0116 (GUI), are major faults (VENT INOP) that can occur during the Analog Devices Test (Phase 2 POST).

If there are multiple KP0116 and/or LP0116 diagnostic codes, check the PC channels and determine if they are all the same. If the channels are all the same, replace the associated analog device or the AI PCB. If the channels are different, but originate from the same module, check and/or replace the associated module, interconnect cable or AI PCB.

Using the fifth and sixth digits of error address reported in the System Diagnostic Log and Table 6-3, the analog channel on which the error occurred can be identified.

Table 6-3: Address codes for BDU POST analog devices test errors

| If the 5th and 6th digits of the error address are: | Parameter Measured | Replace This: |
|---|---------------------------------|---|
| 00 | Inspiratory Pressure Filtered | Inspiratory Electronics PCB |
| 01 | Expiratory Pressure Filtered | Expiratory PCB |
| 02 | Q (O ₂) Filtered | Q1 (O ₂) Flow Sensor |
| 03 | Q (O ₂) Temperature | Q1 (O ₂) Flow Sensor |
| 04 | Q (air) Filtered | Q2 (air) Flow Sensor |
| 05 | Q (air) Temperature | Q2 (air) Flow Sensor |
| 06 | Q (exh) Filtered | Q3 (exh) Flow Sensor |
| 07 | Q (exh) Temperature | Q3 (exh) Flow Sensor |
| 08 | SUBMUX 0: DACWRAP | AI PCB |
| 09 | Safety Valve Switched Side | Safety Valve (SV) Assembly; check Inspiratory Module connections |
| 0A | 12 V GUI Sentry | GUI CPU PCB |

Table 6-3: Address codes for BDU POST analog devices test errors

| If the 5th and 6th digits of the error address are: | Parameter Measured | Replace This: |
|---|---------------------------------|---|
| 0B | Alarm Cable Voltage | GUI CPU PCB or alarm cable assembly |
| 0C | O ₂ PSOL Current | O ₂ PSOL or AI PCB |
| 0D | Air PSOL Current | Air PSOL or AI PCB |
| 0E | Low Voltage Reference | Power Supply |
| 0F | Atmospheric Pressure Transducer | Inspiratory Electronics PCB |
| 10 | Exhalation Coil Temperature | Exhalation Valve |
| 11 | Exhalation Pressure Transducer | Expiratory PCB |
| 12 | O ₂ Sensor | O ₂ Sensor |
| 13 | GUI 5V dc Sentry | GUI CPU PCB |
| 14 | 12V dc Sentry | Power Supply |
| 15 | Safety Valve Current | Safety Valve or Inspiratory Electronics PCB or AI PCB |
| 16 | +15V Sentry | Power Supply or AI PCB |
| 17 | -15V Sentry | Power Supply or AI PCB |
| 18 | Power Fail Cap Voltage | Power Supply |
| 19 | Exhalation Manifold Heater Temp | Exhalation Heater |
| 1A | BPS Battery Voltage Signal | BPS PCB |
| 1B | 5V dc Venthead | Power Supply |
| 1C | BPS Battery Current | BPS PCB |
| 1D | ac Line Voltage | Power Supply or AI PCB |
| 1E | Exhalation Motor Current | Exhalation Valve Assembly |
| 1F | 10V Sentry | Power Supply |

6.9 Diagnostic codes for POST faults

Use the following tables to determine the error code associated with the pattern of either the BD or the GUI LED array when a fault occurs during POST.

Table 6-4: BDU and GUI—Phase 1 (kernel) POST diagnostic codes























| Test | Test Description | BD and GUI LED arrays | | | Fault Type | Corrective Action |
|---------------------------------|--|---|---|---|------------|---|
| | | BDU Diag. code | GUI (10.4-inch) Diag. code | GUI (9.4-inch) Diag. code | | |
| Processor Initialization | Prepares the processor for executing instructions |  KP0001 |  XP0001 |  XP0001 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Integer Unit Test | General CPU confidence test |  KP0002 |  XP0002 |  XP0002 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| DRAM Refresh Timer Test | Tests DRAM refresh circuitry |  KP0003 |  XP0003 |  XP0003 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Kernel DRAM Test | Tests read/write function of DRAM |  KP0004 |  XP0004 |  XP0004 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Boot PROM Checksum Test | Verifies kernel PROM integrity |  KP0005 |  XP0005 |  XP0005 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Addressing Mode Test | Verifies CPU functions in preparation for tests using multiple addressing modes |  KP0007 |  XP0007 |  XP0007 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Kernel NOVRAM Test | Validates ranges for NOVRAM variables used in later tests |  KP0008 |  XP0008 |  XP0008 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Rolling Thunder Test (BDU only) | Checks for unexpected resets during POST. Three or more resets not related to ac failures causes the test to fail. |  KP0009 | N/A | N/A | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace AI PCB. 3. Replace BD CPU PCB. 4. Replace mother-board. |

Table 6-4: BDU and GUI—Phase 1 (kernel) POST diagnostic codes (continued)




























| Test | Test Description | BD and GUI LED arrays | | | Fault Type | Corrective Action |
|------------------------|--|---|---|---|----------------|---|
| | | BDU Diag. code | GUI (10.4-inch) Diag. code | GUI (9.4-inch) Diag. code | | |
| Time of Day Clock Test | Verifies functionality of the Time of Day clock |  KP0011 or LP0011 |  XP0011 or ZP0011 |  XP0011 or ZP0011 | Major or Minor | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Timer Test | Compares system timer to Time of Day clock to verify functionality |  KP0012 |  XP0012 |  XP0012 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Watchdog Timer Test | Verifies watchdog timer times out as expected |  KP0013 |  XP0013 |  XP0013 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| EEPROM Checksum Test | Verifies integrity of flash memory |  KP0015 |  XP0015 |  XP0015 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |

Table 6-5: BDU only—Phase 2 POST diagnostic codes

| BDU Test | BDU Test Description | BDU Diag. Code | BDU Fault Type | Corrective Action |
|-------------------------|---|---|----------------|--|
| ac Voltage Test | Compares ac monitor voltage to specified range |  LP0122 | Minor | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Make sure ventilator is plugged into ac source. 3. Make sure nominal line voltage is set correctly. |
| ADC Test | Checks analog-to-digital converter data availability |  KP0114 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace AI PCB. |
| Analog Devices Test | Performs a range check on each of the 32 analog channels |  KP0116 or LP0116 | Major or Minor | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Refer to Section 6.8 for additional troubleshooting information regarding this fault. 3. Replace affected component. 4. Replace AI PCB. 5. Call Technical Support or your Puritan Bennett representative. |
| Analog Interface Test | Tests analog interface circuitry |  KP0113 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace BD CPU PCB. 3. Replace AI PCB. 4. Replace mother board. |
| Bus Timer Test* | Monitors activity on the local bus |  KP0082 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace BD CPU PCB. |
| DAC Test | Tests digital-to-analog converter data |  KP0115 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace AI PCB. |
| DRAM Memory Test* | Tests DRAM by writing and verifying data patterns to memory |  KP0084 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace BD CPU PCB. |
| DRAM Parity Error Test* | Checks the ability to detect a parity error upon reading defective parity from memory |  KP0090 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace BD CPU PCB. |




* Tested in Short POST

Table 6-5: BDU only—Phase 2 POST diagnostic codes (continued)

| BDU Test | BDU Test Description | BDU Diag. Code | BDU Fault Type | Corrective Action |
|--------------------------|--|---|----------------|--|
| Ethernet Self-Test End | |  LP0086 | Minor | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace BD CPU PCB. |
| Ethernet Self-Test Start | Internal routine verifies functionality of Ethernet controller |  KP0085 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace BD CPU PCB. |
| NMI Register Test* | Verifies NMI source register is in reset state (no bits set) |  KP0083 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace BD CPU PCB. |
| Phase 2 Initialization* | Start non-kernel portion of POST |  KP0006 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace BD CPU PCB. |
| Phase 2 NOVRAM Test* | Compares NOVRAM data to valid states and ranges |  LP0088 | Minor | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Call Technical Support or your Puritan Bennett representative. |
| Safe State Test | Places PSOLs and exhalation valve into safe state and verifies that they cannot be commanded |  KP0120 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace AI PCB. 3. Replace BD CPU PCB. |
| Serial Device Test | Writes to serial EEPROM to verify accessibility |  KP0117 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace AI PCB. 3. Replace BD CPU PCB. |
| Service Switch Test End* | |  LP0121 | Minor | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Turn off ventilator. Release switch. 3. Check for mechanical obstruction to switch. 4. Replace BD CPU PCB. |

* Tested in Short POST

Table 6-5: BDU only—Phase 2 POST diagnostic codes (continued)

| BDU Test | BDU Test Description | BDU Diag. Code | BDU Fault Type | Corrective Action |
|-------------------------------|--|---|----------------|---|
| Service Switch Test Start* | Checks that the service mode switch is not stuck, and prevents entry into Service Mode from a power fail condition |  LP0121 | Minor | <ol style="list-style-type: none"> 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Turn off ventilator. Release switch. 3. Check for mechanical obstruction to switch. 4. Replace BD CPU PCB. |
| Unexpected Reset Umpire Test* | Checks for unexpected resets of the CPU. Three resets (strikes) in 24 hours will cause a VENT INOP condition. |  KP0087 or LP0087 | Major or Minor | <ol style="list-style-type: none"> 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Check associated errors in the System Diagnostic and System Information log to determine why POST was invoked three times within 24 hours. <ol style="list-style-type: none"> a. If the codes indicate that the BD CPU generated the resets, replace the BD CPU (Other codes may be present indicating that the GUI lost communications with the BD). b. If the codes indicated that the GUI CPU generated the resets, replace the GUI CPU (Other codes may be present indicating that the BD lost communications with the GUI). 3. Run a complete EST to check for analog device failures. |
| VENT INOP Test | Checks to see if the ventilator is in the VENT INOP state |  KP0112 | Major | <ol style="list-style-type: none"> 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Check cabling from BD CPU PCB to GUI CPU PCB. 3. Replace BD CPU PCB. 4. Call Technical Support or your Puritan Bennett representative. |

* Tested in Short POST

Table 6-6: GUI only—Phase 2 POST diagnostic codes

















| GUI Test | GUI Test Description | GUI (10.4-inch) Diag. code | GUI 9.4-inch) Diag. code | GUI Fault Type | Corrective Action |
|--------------------------|---|---|---|----------------|--|
| Bus Timer Test | Monitors activity on the local bus |  XP0082 |  XP0082 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI CPU PCB. |
| DRAM Memory Test | Tests DRAM by writing and verifying data patterns to memory |  XP0084 |  XP0084 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI CPU PCB. |
| DRAM Parity Error Test | Checks the ability to detect a parity error upon reading defective parity from memory |  XP0090 |  XP0090 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI CPU PCB. |
| Ethernet Self-test End | |  ZP0086 |  ZP0086 | Minor | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI CPU PCB. |
| Ethernet Self-Test Start | Internal routine verifies functionality of Ethernet controller |  XP0085 |  XP0085 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI CPU PCB. |
| NMI Register Test | Verifies NMI source register is in reset state (no bits set) |  XP0083 |  XP0083 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI CPU PCB. |
| Phase 2 Initialization | Start non-kernel portion of POST |  XP0006 |  XP0006 | Major | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI CPU PCB. |
| Phase 2 NOVRAM Test | Compares NOVRAM data to valid states and ranges |  ZP0088 |  ZP0088 | Minor | 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI CPU PCB. |

Table 6-6: GUI only—Phase 2 POST diagnostic codes (continued)



















| GUI Test | GUI Test Description | GUI (10.4-inch) Diag. code | GUI 9.4-inch) Diag. code | GUI Fault Type | Corrective Action |
|---------------------------------|---|--|--|----------------------|--|
| SAAS Self-test End | |  XP0098 |  XP0098 | Major | <ol style="list-style-type: none"> 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI audio alarm. 3. Replace GUI CPU PCB. |
| SAAS Self-test Start | Detects internal errors of alarm circuitry and lack of audio feedback |  XP0097 |  XP0097 | Major | <ol style="list-style-type: none"> 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Replace GUI audio alarm. 3. Replace GUI CPU PCB. |
| Unexpected Reset Umpire Test | Checks for unexpected resets of the CPU. Three resets (strikes) in 24 hours will cause a VENT INOP condition. |  XP0087 or ZP0087 |  XP0087 or ZP0087 | Major or Minor | <ol style="list-style-type: none"> 1. Check the diagnostic code's corrective actions in Table 6-2. 2. Check associated errors in System Diagnostic Log. 3. Call Technical Support or your Puritan Bennett representative. |

Table 6-7: BDU or GUI—Phase 3 POST diagnostic codes

| Test Step | Test Description | Diag. code BDU PCB LEDs | Diag. code GUI PCB LEDs (10.4-inch) | Diag. code GUI PCB LEDs (9.4-inch) | Fault Type | Corrective Action |
|----------------------------------|--|--|--|--|---------------|---|
| Operating System Initialization* | Loads operating system |  KP0129 |  XP0129 |  XP0129 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Floating Point Unit Test* | Tests floating point functionality of the microprocessor |  KP0089 |  XP0089 |  XP0089 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Memory Management Unit Test* | Tests microprocessor's memory management unit |  KP0081 |  XP0081 |  XP0081 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |
| Application Initialization* | Loads application software |  KP0131 |  XP0131 |  XP0131 | Major | 1. Check the diagnostic codes' corrective actions in Table 6-2. 2. Replace affected CPU PCB. |

* Tested in Short POST

6.9.1 POST interrupt errors and test failures

Table 6-8 below lists the errors that can occur during particular POST test steps. These errors, reported by the diagnostic LED array on the applicable CPU PCB, are of two types: interrupts and test failures. An interrupt error may indicate that an external event (e.g. a power fail interrupt) occurred during the test step. A test failure indicates that the test failed to meet its specifications.

Table 6-8: Interrupt errors and test failures – POST self tests








































| Error | BD and GUI LED arrays | | | Error Type | May be caused by |
|--------------------------------|---|---|---|------------|------------------------------|
| | BDU Diag. code | GUI (10.4-inch) Diag. code | GUI (9.4-inch) Diag. code | | |
| Unknown NMI |  |  |  | Interrupt | CPU PCB |
| Ethernet Parity Error |  |  |  | Interrupt | CPU PCB |
| DRAM Parity Error |  |  |  | Interrupt | CPU PCB |
| Analog Interface Error |  |  |  | Interrupt | AI PCB |
| Power Fail NMI (BDU only) |  |  |  | Interrupt | Loss of ac power during POST |
| 5 Vdc overvoltage (GUI only) |  |  |  | Interrupt | Power Supply |
| 12 Vdc overvoltage (GUI only) |  |  |  | Interrupt | Power Supply |
| 12 Vdc undervoltage (GUI only) |  |  |  | Interrupt | Power Supply |

Table 6-8: Interrupt errors and test failures – POST self tests (continued)

| Error | BD and GUI LED arrays | | | Error Type | May be caused by |
|--------------------------------|---|---|---|------------|-----------------------------------|
| | BDU Diag. code | GUI (10.4-inch) Diag. code | GUI (9.4-inch) Diag. code | | |
| SAAS NMI |  |  |  | Interrupt | GUI alarm or alarm cabling |
| Access fault/Bus error |  |  |  | Interrupt | CPU PCB |
| Other Unexpected interrupt |  |  |  | Interrupt | CPU PCB |
| POST Internal Software Failure |  |  |  | Interrupt | CPU PCB |
| Test Failed |  |  |  | Failure | Specific analog device or CPU PCB |