

Reference:	Serial No.:
Company name:	DMX-Standard & Basic DMX2-Pro & Plus

## CAUTION!


**There is no interchangeability between the components of the MX family (DMX-Standard & Basic) and those of the MX2 family (DMX2-Pro & Plus).**

**Never use a control unit, motor or hose from one family with the components from another family.**


**EQUIPMENT TO BE USED FOR THE INSPECTION:**

- |   |  |                              |                             |
|---|--|------------------------------|-----------------------------|
| ❑ | Stabilised power supply  | 3300102-001                  | or equivalent = 32 Vdc 10 A |
| ❑ | 1x hose attachment   | DMX → 4VX hose               | REF. 1600387                |
|   |  | DMX2 → MX2 hose              | REF. 1600700                |
| ❑ | 1x test reference motor  | DMX → MX motor               | REF. 1600375                |
|   |  | DMX2 → MX2 motor             | REF. 1600677                |
| ❑ | 1x CA or PM ratio 1:1, blue, with Ø 2 to 4 mm spherical bur.                                 |                              |                             |
| ❑ | 1x piece of braking test material.   |                              |                             |
| ❑ | 1x plate of insulated antistatic material on which to place the DMX or DMX2 to be inspected. |                              |                             |
| ❑ | 1x RS232 cable:  | REF. 1500579                 |                             |
| ❑ | A PC with the following Bien-Air test program:   |                              |                             |
|   | New 2010 version replaces the old version:   | MotorDriveController.exe     |                             |
|   | and the following pilot program:   | mfc70d.dll and msvcrt70d.dll |                             |


## Installing the system for controlling the DMX-Standard




## Installing the system for controlling the DMX2-Pro




**Inspection panel on PC display.**



**Connections for DMX-Standard**








**Connections for DMX2-Pro**





## INSPECTION CRITERIA

Y = Yes N = No

POS	PARAMETER	METHOD	INSPECTION	CONFORMITY	Y	N
1.1. DMX S & B	Power supply connection Hose and MX motor connection	2 wires on white DMX connector: → +32 Vdc on <b>pin 1</b> connector → Gnd on <b>pin 4</b> Connect the hose for the motor to the orange connector on its control unit as shown opposite →		The connectors must be correctly plugged in.	<input type="checkbox"/>	<input type="checkbox"/>
	DIP switch settings	Positions: 				
	Connection to PC	Connect the DMX to the PC using the RS 232 series cable				
1.2. DMX2 Pro & Plus	Power supply connection	2 wires on the DMX2 connector: → +32 Vdc (red) see image → Gnd (black) see image opposite	 	The connectors must be correctly plugged in.	<input type="checkbox"/>	<input type="checkbox"/>
	<b>MX2:</b> <b>Hose + motor connection</b>	Connect the <b>hose for the motor</b> to the connector on its control unit as shown opposite →				
	DIP switch settings	Positions: 				
	Connection to PC	Connect the DMX2 to the PC using the RS 232 cable				
2	Power supply inspection	Switch on the power supply and check that the voltage is +32 Vdc.		Voltage 32 Vdc ± 2 %.	<input type="checkbox"/>	<input type="checkbox"/>
3	Motor operation	Launch the test program: <b>MotorDriveController.exe</b> then click on "Start"  Move the "Speed" cursor to maximum then click on "ccw" (counterclockwise).  Reset the speed to 100 rpm and the direction of rotation to clockwise. "cw"  Click on "Stop"	The motor starts and the light comes on  Acceleration  Basic values  The motor stops	Rotation speed 100 rpm.  Reaches 40,000 rpm then reverses direction of rotation  Speeds 100 rpm. Direction reversal	<input type="checkbox"/>	<input type="checkbox"/>

4	Light operation.	Click on "Start" to start the motor. The light comes on automatically	Visible light	Continuous lighting.		
		Click on "Light"	A new screen appears			
		Move the cursor from 1 to 16 and from 16 to 1	Brightness variation	The brightness increases then decreases again.	<input type="checkbox"/>	<input type="checkbox"/>
		Click on "Motor Control"	The main screen reappears			
		Click on "Stop"	The motor stops	The light goes out after ~10 seconds		

**Point 5 only applies to DMX-Standard and DMX2-Pro.  
Go straight to point 6 for DMX-Basic and DMX2-Plus.**

Point 5 only applies to DMX-Standard and DMX2-Pro. Go straight to point 6 for DMX-Basic and DMX2-Plus.									
5	Auto-reverse and auto-forward operation	Click on "Auto-rev."	A new screen appears	Torque reaches 10% and reversal of rotation direction.	<input type="checkbox"/>	<input type="checkbox"/>			
		Click on "Edit"							
		Change the torque to 10% then click on "ok"	The new screen disappears						
		Click on "Start"	The motor starts						
		Slow the bur until the direction of rotation reverses automatically.	The motor stops then restarts.						
		Click on "Stop"	The motor stops						
		Click on "Auto-for."	A new screen appears						
		Click on "Edit"							
		Change "Auto-forward time" to 30 then click on "ok"	The new screen disappears						
		Click on "Start"	The motor starts						
		Slow the motor until the direction of rotation reverses.	Stop + start reverse direction + normal direction				Reaches torque value and reverses for ~ 3 seconds then returns to clockwise direction.		
		Click on "Stop"	The motor stops						

6	Max. torque and overheating protection	Click on "Normal"				
		Click on "Edit"	A new screen appears			
		Change the torque to 100% then click on "ok"	The screen disappears			
		Click on "Start"	The motor starts	Speed 100 rpm		
		Mill into a test material until the motor stops and hold for 5-10 seconds	Motor stoppage	The motor gradually slows then stops. "Motor current" on the screen increases to ~4.5A then drops back down to ~1.5A Two motor symbols appear: 1x jammed motor 1x overheated motor	<input type="checkbox"/>	<input type="checkbox"/>
		Click on "Stop"	The motor stops			
7	End of test	Exit the program by clicking on "Exit" then switch off the power supply. Disconnect the connections indicated above	The screen disappears			
8	Traceability	Complete and archive (computerised or paper version) the SU 824-xxx and IC 751-015_xx. Any returns to Bien-Air Switzerland must include a paper copy of the completed form.				

**CERTIFICATE OF CONFORMITY**

Name and signature: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_