


⑤



Relay open, Short circuit on Fan motor, Short circuit Heater
Overheat prevention worked, Ambient temperatur of microboad
more than 65°C.

