

<b>FG 9938 Fuses</b>	
<b>AC input fuse</b>	
Netz	Fuse 6.3 A slow, in series to the bridge rectifier
<b>Overvoltage protection circuit fuse</b>	
OVP	Fuse 4 A slow, in the ground wire Fuse is blown by a SCR if the output voltage gets too high
	E1226 CAN module missing 17,9 E1711 No communication PPC Generator (if you try screening)