

NX100S Excellent-Parts Enumeration

PART LIST			
NO.	NAME	Q'TY	P/N
1	NOSE CAP COVER	1	BL800K-11005
2	DUST SEAL	1	BL800K-11006
3	SEAL COVER	1	BL800K11009
4	HAND CAP COVER	1	NX100S-E10101
5	DUST COLLECTOR	1	BL800K-11007
6	HAND CAP	1	NX100S-E10102
7	TEST BAR	1	NX100S-10211
8	COLLET CHUCK	1	BL800K11311
9	COLLET CHUCK CASE	1	BL800A-11301
10	BALL BEARING	1	BL800A-11304
11	BEARING STOPPER	2	BL800A-11305
12	BEARING COVER	1	BL800A-11306
13	CONICAL SPRING	19	BL800A-11309
14	CAM PUSHER	1	BL800A-11310
15	CAM PIN	1	BL800A-11314
16	PUSHER GUIDE	1	NX100S-E11331
17	WAVE WASHER	1	BL800A-11328
18	COLLET CHUCK JOINT	1	BL800K-11320
19	O-RING	2	BL800A-11323
20	DELRIN JOINT	1	BL800A-11322
21	BALL BEARING(1260zz)	1	1260ZZ
22	BALL GUIDE HOLDER	1	NX100S-E11215
23	BALL GUIDE INNER	1	BL800A-11205
24	HANDLE SPRING	1	BL800A-11206
25	O-RING	1	Φ12x1
26	HANDLE CAM	1	NX100S-E10702
27	BALL	2	BL800A-11211
28	BALL RIM	2	BL800A-11212
29	O-RING	1	Φ10x1
30	BALL BEARING	1	1030ZZ
31	BALL GUIDE OUTER	1	BL800A-11103
32	HANDLE	1	NX100S-E10801
33	MOTOR CASE COVER	1	NX100S-E10901
34	O-RING	1	Φ17x1
35	MOTOR CASE	1	NX100S-E10902
36	FLAT HEAD BOLT	2	M2xP0.4xL4
37	MAGNET	1	NX100S-11003
38	ARMATURE ASSY	1	MAX88K-11100
39	WASHER	1	NX100S-11007
40	BALL BEARING	1	830ZZ
41	BRUSH HOLDER ASSY	1	NX100S-11200
42	O-RING	1	Φ8x1
43	WAVE WASHER	1	BL800A-11328
44	WASHER	1	NX100S-11500
45	CARBON ASSY	2	NX100S-11400
46	FAN HEAD BOLT	2	M2xP0.4xL4
47	TERMINAL(L/R)	2	NX100S-11403
48	CORE ASSY	1	NX100S-11700
49	CAP	1	MAX88K-11000

