

Auxiliary alarm error group 54

Error code	Description of malfunction	Possible remedy
54.0000	Test current for signal generator (piezo) is too high.	1. Check connection between signal generator and Control PCB. 2. Replace signal generator. 3. Replace Control PCB.
54.0001	Test current for signal generator (piezo) is too low.	1. Check connection between signal generator and Control PCB. 2. Replace signal generator. 3. Replace Control PCB.