

E302: MASTER-CBC1 COMM ERROR

Possible Cause/Criteria	Countermeasure
Cable is disconnected.	Connect the cable.
UT-7146 MASTER Board failure.	Replace the board with a new one.
UT-7147 SLAVE CBC Board failure.	Replace the board with a new one.